LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 C 0 F S V 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 2 0 4 57 CAT 58
CON'T O 1 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) [0] While operating at 1% reactor power, a secondary to primary side leak was discovered
in the EES section of the B-2-3 module in the Loop 2 steam generator. The leak is
assumed to have developed following a reactor scram transient on September 30, 1982.
No effect on public health or safety. Accompanying occurrences reported in RO 82-044.
O[6] Similar report is RO 77-42.
0 7
0 8 9
SYSTEM CAUSE SUBCODE S
SEQUENTIAL REPORT NO. 17) REPORT 8 2 - 0 4 9 - 0 1 T - 0
NUMBER 21 22 23 24 26 27 28 29 30 31 32 ACTION FUTURE EFFECT SHUTDOWN HOURS (22) ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER TAKEN ACTION ON PLANT METHOD HOURS (22) SUBMITTED FORM SUB. SUPPLIER MANUFACTURER
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The actual cause is not identified, but appears to be random in nature. The affected
steam generator was isolated. Efforts to identify the precise location of the leak
and to make necessary repairs are in progress. Upon completion of these efforts, a
final report will be submitted.
FACILITY STATUS OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) ACTIVITY CONTENT RELEASE OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
1 7 0 0 0 37 Z 38 N/A 7 8 9 PERSONNEL INJURIES 13
1 8 0 0 0 0 0 0 N/A NUMBER N/A N/A 1 8 9 11 12 12 80
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION 1 19 1 Z 1421 N/A
9 10 8301180372 821222 NRC USE ONLY PDR ADOCK 05000267 NRC USE ONLY
S SSUED DESCRIPTION (45) S PDR
NAME OF PREPARER Charles Fully PHONE: (303) 785-2224 &