LICENSEE EVENT REPORT

	CONTROL BLOCK:
0 1	FILS L S 1 3 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 3 4 5 5 CAT 38
O I	SOURCE SO SI SOCKET NUMBER 68 SP EVENT DATE 75 REPORT DATE 30
0 2	During a surveillance test, MV-09-11 (1C Auxiliary Feedwater Pump Flow
03	Control Valve) failed to cycle as required by T.S. 4.7.1.2.a.4. The
54	L valve operated until the torque switch actuator roller separated from
0 5	its operator arm. T.S. 3.7.1.2 ACTION was entered. The torque switch was
0 5	replaced and the valve was returned to service within the required T.S.
0 7	3.7.1.2 time limit. The health and safety of the public was not affected
0 3	by this event.
0 9	SYSTEM CAUSE COOK SUSCODE SUSC
	TO REPORT VEAR REPORT NO. LEA POR TYPE NO. 17 REPORT VEAR REPORT NO. 18 2 1 22 23 24 26 27 28 29 20 20 21 12 12 12 12 12 12 12 12 12 12 12 12
	ACTION FITURE SHUTGOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUS. PRIME COMPONENT MANUFACTURER LIZ 10 0 0 0 0 1 N 20 N 24 A 25 L 2 10 10 10 COMPONENT MANUFACTURER LIZ 10
10	MV-09-11 failed to operate properly due to a torque switch roller shaft
	bearing being approximately 1/4 inch short. This problem is considered
12	to be an isolated case as the one other valve of this type was checked
T1	and no problems were found. The torque switch was replaced and the
14	valve was returned to service.
15	STATUS STATUS O 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9
	CETUTY CONTENT ELEASED OF AELEASE AMOUNT OF ACTIVITY (35) NA 1
1 7	O O O O Z Z 3 NA
1 3	O O O O O O O O O O O O O O O O O O O
1 9	LOSS OF CH CAMAGE TO FACILITY (3) TYPE DESCRIPTION NA NA
2 0	SSUED DESCRIPTION (45) NAC USE ONLY NAC USE ONLY
, 3	T. S. Rotella 240NE 305-465-3550