



UNITED STATES

NUCLEAR REGULATORY COMMISSION

REGION IV

URANIUM RECOVERY FIELD OFFICE
BOX 25325
DENVER, COLORADO 80225

Returned to URFO 467-55
Docket 40-8783
PDR

URFO:YAY
Docket No. 40-8783
04008783101E

JAN 18 1983

MEMORANDUM FOR: Docket File No. 40-8783
FROM: Yvonne A. Young, Project Manager
Licensing Branch I
Uranium Recovery Field Office
Region IV
SUBJECT: ERROR CORRECTIONS TO URANERZ U.S.A., INC.'S SOURCE
MATERIAL LICENSE SUA-1401 LICENSE CONDITION NO. 10

This memorandum documents my review of License Condition No. 10 of Uranerz U.S.A., Inc.'s Source Material License SUA-1401. Errors pertinent to License Condition No. 10 were corrected. Background information leading to these corrections is included in the discussion below:

Discussion

During the latter part of September, 1982, Mr. Chuck Cain, Region IV inspector, telephoned me and informed me that he would perform an inspection (as required by License Condition No. 47 at least six weeks prior to commencing mining operations to allow NRC to review the licensee's development and implementation of administrative and operating procedures and monitoring programs) at the Uranerz U.S.A., Inc's Ruth ISL site on or around October 5, 1982. However, Mr. Cain noted that License Condition No. 10 of Source Material License SUA-1401 didn't reference the proper section of the licensee's revised application which incorporates the Radiation Safety Program (RSP) and that the supplemental data accompanying the original application for source material license dated December 1980 was incorrectly dated as December 1981 in the license condition.

Mr. Pete Garcia of the staff and I have reviewed the licensee's submittals (including the licensee's original application, dated December 1980 and the revised application dated October 9, 1981) and it was noted that sections discussing the RSP in the original application had been

8301260163 830118
PDR ADCK 04008783
C PDR

DESIGNATED ORIGINAL

Certified By B. Fisher

JAN 18 1983

revised and renumbered in the licensee's submittal dated October 9, 1981, prior to issuance of the license. Thus, the RSP was not properly tied down in the license. Therefore, License Condition No. 10 of SUA-1401 should be revised to read as follows:

10. Authorized use for recovery from pregnant lixiviant in accordance with statements, representations, and conditions contained in (1) Figure 23 and Sections 5.0 and 6.0 of the licensee's submittal dated October 9, 1981, and (2) portions of the licensee's April 6, 1981 supplement to application for a Source Material License as revised by the licensee's submittal dated October 9, 1981 as follows: Figure D-6.4; and Part III Reclamation. Whenever the word "will" is used in the licensee's submittals, it shall denote a requirement. Notwithstanding the above, the following conditions shall override any conflicting statements contained in the licensee's application and supplements.

Yvonne Young

Yvonne A. Young, Project Manager
Licensing Branch I
Uranium Recovery Field Office
Region IV

Approved By:

John J. Linehan

John J. Linehan, Branch Chief
Licensing Branch I
Uranium Recovery Field Office
Region IV

Case Closed: 04008783101E