Attachment to AECM-83/86 Page 1 of 2

	Page 1 of 2
	CONTROL BLOCK: [] [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	M S G G S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 EICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 4 1 6 7 0 1 10 5 8 3 8 0 2 0 7 8 3 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 During an inspection of completed work which corrected fire protection deficiencies
0 3	Jon redundant raceways/cables, Maintenance Field Engineering noted similar deficiencies
0 4	in the Auxiliary Building, Turbine Building, and Control Building. Fire watches were
0 5	established in accordance with T.S.3.7.7.a. The event had no effect on the health
06	and safety of the public and did not constitute a threat to plant safety. This is
	submitted as a Special Report pursuant to T.S.3.7.7.a.
0 7	Submitteed as a special nepote parameter
7 8	9 SYSTEM CAUSE CAUSE COMP VALVE
0 9	A B 10 1 B 12 C 13 Z Z Z Z Z Z Z Z Z 16
	17) REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
	ACTION FUTURE ACTION ON PLANT SHUTDOWN METHOD HOURS 22 ATTACHMENT FORM SUBMITTED
1 0	The cause of the deficiencies was incomplete construction. Maintenance work
111	authorizations were initiated for correction. Estimated completion is April, 1983.
1 2	Field Engineering is continuing in an effort to identify and resolve all redundant
1 3	division raceway fire protection deficiencies. This is an interim report. A final
1 4	report will be submitted by April 15, 1983.
1 5	FACILITY STATUS SPOWER OTHER STATUS OTHER ST
	ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA 9 10 11 NA PERSONNEL EXPOSURES AMOUNT OF ACTIVITY 35 NA 44 45 BO BO
1 7	NUMBER TYPE DESCRIPTION (39) NA NA
7 8	PERSONNEL INJURIES NUMBER DESCRIPTION 41
1 8 7 8	NA NA
	LOSS OF OR DAMAGE TO FACILITY 43
7 8	9 8302150106 830207 9 8302150106 830207
2 0	N 44 S NA
7 8	NAME OF PREPARER Original signed by Ron Byrd PHONE

SUPPLEMENTARY INFORMATION TO LER 83-010/99 X-0

Mississippi Power & Light Company Grand Gulf Nuclear Station - Unit 1 Docket No. 50-416

Technical Specification Involved: 3.7.7
Reported Under Technical Specification: 6.9.2

Event Narrative:

During an inspection of completed work which corrected fire protection deficiencies on redundant raceways/cables (Ref. LER 82-106/01 I-0), Field Engineering identified similar deficiencies which were not previously identified by the Architect Engineer but which were a result of incomplete construction. LCO's 83-0018, 83-0019 and 83-0020 were entered on January 5, 1983 to establish fire watches in the Auxiliary Building, Turbine Building and Control Building areas which were not previously covered under LCO 82-0036 (Ref. LER 82-106/01 T-0).

Maintenance work authorizations were issued to correct the deficiencies. Estimated completion is April, 1983. Maintenance Field Engineering is continuing in an effort to identify and resolve all redundant division raceway fire protection deficiencies. Any further discoveries will be submitted as an update to this report. This is submitted as an interim report.