LICENSEE EVENT REPORT

	LICENSEE EVENT REPORT
	CONTROL BLOCK: [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 8	G A E I H 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 6 5 6 EICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 67 CAT 58
CON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 3 2 1 7 0 1 0 6 8 3 8 0 2 0 3 8 3 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 With Unit 2 at steady-state full power, the power supply for Unit 1
0 3	standby gas treatment fan 1A was found inoperable. This event is
0 4	contrary to Unit 2 Tech. Specs. section 3.6.6.1. SBGT subsystems 1B,
0 5	2A, & 2B remained operable. Unit 2 was placed in a 7-day LCO as per
0 6	Unit 2 Tech. Specs. section 3.6.6.1, ACTION a. The health and safety
0 7	of the public were not affected by this non-repetitive event.
08	
7 8	SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC
10	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
1 1	"OFF". The reason for this breaker's being "OFF" is unknown. The
1 2	breaker was returned to the "ON" position and the "STANDY GAS TREATMENT
1 3	SYSTEM VENTILATION AND OPERABILITY" procedure was performed, thus
1 4 7 8	returning SBGT 1A to normal operable status.
1 5	TACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 H 28 0 0 0 0 29 NA A 31 Operator Observation STATUS OPERATOR OF DISCOVERY DESCRIPTION 32 A 31 Operator Observation 80
1 6 R	ELEASED OF RELEASE AMOUNT OF ACTIVITY (35) Z 33 Z 34 NA NA PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
7 8	0 0 0 37 Z 38 NA 9 PERSONNEL INJURIES 13 NUMBER DESCRIPTION 41
1 8 7 8 1 9 7 8	0 0 0 0 40 NA 9 11 12 LOSS OF OR DAMAGE TO FACILITY (43) PDR ADOCK 05000321 TYPE DESCRIPTION NA S PDR
2 0	PUBLICITY NRC USE ONLY NRC USE ONLY NA NA 68 69 80 5
	NAME OF PREPARED S. B. Tipps PHONE (912) 367-7851

LER No.: 50-321/1983-005

Licensee: Georgia Power Company

Facility: Edwin I. Hatch

Docket #: 50-321

Narrative Report for LER 50-321/1983-005

With Unit 1 in cold shutdown and Unit 2 in steady-state full power, and while performing visual inspection of Unit 1 control console, personnel found control indications for SBGT fan 1A not illuminated. Further investigation revealed that the power supply for SBGT fan 1A was inoperable. This event is contrary to Unit 2 Tech. Specs. section 3.6.6.1. Standby gas treatment subsystems 1B, 2A, and 2B remained operable. Unit 2 was placed in a 7-day LCO, as per Unit 2 Tech. Specs. section 3.6.6.1, ACTION a. The health and safety of the public were not affected by this non-repetitive event.

The cause of this event was due to the power supply breaker for standby gas treatment fan lA being "OFF". The reason for this breaker's being "OFF" is unknown. The breaker was returned to the "ON" position and "STANDBY GAS TREATMENT SYSTEM VENTILATION AND OPERABILITY" procedure was satisfactorily performed, thus returning SBGT lA to normal operable status.