



Carolina Power & Light Company

Brunswick Steam Electric Plant  
P. O. Box 10429  
Southport, NC 28461-0429

February 1, 1983

FILE: B09-13520  
SERIAL: BSEP/83-251

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II, Suite 3100  
101 Marietta Street N.W.  
Atlanta, GA 30303

3 FEB 8 10:31


BRUNSWICK STEAM ELECTRIC PLANT, UNIT NOS. 1 & 2  
LICENSE NOS. DPR-71 AND DPR-62  
DOCKET NOS. 50-325 AND 50-324  
SUPPLEMENTAL RESPONSE TO IDENTIFIED 10CFR21 DEFICIENCY

Dear Mr. O'Reilly:

Carolina Power & Light Company informed Region II by telephone and follow-up correspondence (Serial No. BSEP/82-932) in April 1982 of an identified 10CFR21 deficiency; "A review of the Reactor Building environmental report...determined that a postulated pipe crack in the HPCI, RCIC, KWCU, and main steam line drains could result in a limiting environment for the Reactor Buildings of both units."

In that 10CFR21 report, CP&L committed to submit a supplemental response providing a schedule for determining the corrective action required and the installation of any required modifications. United Engineers & Constructors is currently completing its evaluation of the Reactor Building Environmental Report and developing required corrective actions. A listing of any required modifications and a schedule for implementation will be provided no later than March 31, 1983.

Very truly yours,

  
C. R. Dietz, General Manager  
Brunswick Steam Electric Plant

RMP/mcg/LETGG1

cc: Mr. R. C. DeYoung

8302150172 830201  
PDR ADOCK 05000324  
S PDR

OFFICIAL COPY  
LE 19