## LICENSEE EVENT REPORT

	LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 7 8	C T H N P 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 5 EICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T 0 1 7 8	SOURCE LL 6 0 5 0 - 0 2 1 3 7 0 1 1 1 1 8 3 8 0 2 0 4 8 3 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2	While in Mode i, a Diesel Generator (EG2B) unit annunciator alarm was received on
0 3	the main control board. Response to the alarm showed the diesel generator air
0 4	compressor had thrown its belt and had apparent mechanical damage.
0 5	
0 6	
0 7	
0 8	<u></u>
0 9	SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
	LER/RO REPORT NO.  O O O 2  ACTION FUTURE EFFECT SHUTDOWN  REPORT NO.  O O O 2  27  ACTION FUTURE EFFECT SHUTDOWN  REPORT NO.  O ATTACHMENT NPRD-4 PRIME COMP. COMPONENT
	TAKEN ACTION ON PLANT METHOD HOURS (22) SUBMITTED FORM SUB. SUPPLIER MANUFACTURER 1 0 0 0 0 0 N 23 Y 24 Z 25 1 0 7 5 26 A4 A7
1 0	Mechanical failure of the EG2B air compressor occurred as a result of 2 broken
11	connecting rods between the crank shaft and piston. The failed unit was replaced.
1 ?	The failed compressor was then repaired for future use as a spare.
1 3	
1 4 7 8	9 80
1 5	FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 DISCOVERY DISCOVERY DESCRIPTION 32 DISCOVERY DISCOVERY DESCRIPTION 32 DISCOVERY DESCRIPTION 32 DISCOVERY DISCOVERY DISCOVERY DISCOVERY DISCOVERY DISCOVERY DISCOVERY DISCOVE
	9 10 12 13 44 45 46 80  ACTIVITY CONTENT AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36 80  LZ 33 Z 34 N/A N/A N/A 80
1 7	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 0 0 0 37 Z 38 N/A
1 8	9 PERSONNEL INJURIES 13 80 NUMBER DESCRIPTION 41 N/A 9 11 12 12 80
1 9	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION N/A
7 8	PUBLICITY PDR ADDCK 05000213 PDR S PDR S PDR S 68 69 80 2 80 2 80 2 80 2 80 2 80 2 80 2 80
	Michael D. Quinn PHONE (203) 267-2556