

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK / / / / / / / (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
/V/A/N/A/S/2/ (2) /0/0/-/0/0/0/0/0/-/0/0/ (3) /4/1/1/1/1/ (4) / / / (5)
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT
REPORT SOURCE /L/ (6) /0/5/0/0/0/3/3/9/ (7) /0/1/0/6/8/3/ (8) /0/2/0/2/8/3/ (9)
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

/0/2/ / On January 6, 1983 with Unit 2 in Mode 3, MOV-RS-255B, Recirculation Spray Pump /
/0/3/ / 2B Suction Isolation Valve, would not reopen after having been closed for a pe- /
/0/4/ / riodic test, rendering 2-RS-P-2B inoperable. Since the three remaining recircu- /
/0/5/ / lation spray pumps were still available to provide containment spray if required /
/0/6/ / and only two pumps are required for adequate post LOCA cooling, the health and /
/0/7/ / safety of the public were not affected. This event is contrary to T.S. 3.6.2.2 /
/0/8/ / and reportable pursuant to T.S. 6.9.1.9.b. /

SYSTEM CAUSE CAUSE COMP. VALVE
CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE

/0/9/ /S/B/ (11) /E/ (12) /B/ (13) /V/A/L/V/E/X/ (14) /E/ (15) /D/ (16)
LER/RO EVENT YEAR SEQUENTIAL OCCURRENCE REPORT REVISION
REPORT YEAR REPORT NO. CODE TYPE NO.
(17) NUMBER /8/3/ /-/ /0/0/5/ / / /0/3/ /L/ /-/ /0/

ACTION FUTURE EFFECT SHUTDOWN ATTACHMENT NPRD-4 PRIME COMP. COMPONENT
TAKEN ACTION ON PLANT METHOD HOURS SUBMITTED FORM SUB. SUPPLIER MANUFACTURER

/B/ (18) /Z/ (19) /Z/ (20) /Z/ (21) /0/0/0/0/ (22) /Y/ (23) /N/ (24) /A/ (25) /C/6/6/5/
(26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

/1/0/ / MOV-RS-255B failed to reopen due to the motor operator torquing out from a jam- /
/1/1/ / med seal cap; a cap used to prevent water from corroding the valve stem extension/
/1/2/ / rod. The seal cap was returned to its original position and the valve stroked /
/1/3/ / satisfactorily. /
/1/4/ / /

FACILITY STATUS ZPOWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
/1/5/ /G/ (28) /0/0/0/ (29) / NA / (30) /A/ (31) / Operator Observation /

ACTIVITY CONTENT AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
/1/6/ /Z/ (33) /Z/ (34) / NA / / NA /

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
/1/7/ /0/0/0/ (37) /Z/ (38) / NA /

PERSONNEL INJURIES NUMBER DESCRIPTION (41)
/1/8/ /0/0/0/ (40) / NA /

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)
/1/9/ /Z/ (42) / NA /

PUBLICITY ISSUED DESCRIPTION (45) NRC USE ONLY
/2/0/ /N/ (44) / NA / / / / / / / / / / / / / / /

NAME OF PREPARER W. R. CARTWRIGHT PHONE (703) 894-5151

Description of Event

On January 6, 1983 with Unit 3 in Mode 1, MOV-RS-255B, Recirculation Spray Pump 2B Suction Isolation Valve which is normally maintained open, would not reopen after having been closed for a periodic test on 2-RS-P-2B. The valve was inoperable for 4 1/2 hours making 2-RS-P-2B inoperable for the same period. This event is contrary to T.S. 3.6.2.2 and reportable pursuant to T.S. 6.9.1.9.b.

Probable Consequences of Occurrence

North Anna Unit 2 has four fifty percent capacity recirculation spray pumps for the purpose of containment cooling following a loss of coolant accident or a high energy line break. Since three of the four pumps were still operable and only two are required for adequate cooling the health and safety of the public were not affected.

Cause of Event

MOV-RS-255B is located fifty five feet below its motor operator. A 1 1/2" torque tube connects the operator to the valve. To prevent corrosion of the torque tube and its casing, a seal cap is installed to prevent water from running down the length of the torque tube. The motor operator of MOV-RS-255B torqued out while attempting to reopen due to the seal cap being jammed against a pipe.

Immediate Corrective Action

The immediate corrective action was to reposition the seal cap and stroke MOV-RS-255B satisfactorily.

Scheduled Corrective Action

An engineering study will be performed to determine an alternative design which will not be interfered with by the surroundings.

Actions Taken to Prevent Recurrence

No action is required.

Generic Implications

Seal caps with pipes in close proximity exist on outside recirculation spray pump suction isolation valves on Units 1 & 2.