

LER No.: 50-366/1979-135, Revision 1
Licensee: Georgia Power Company
Facility: Edwin I. Hatch
Docket #: 50-366

Narrative Report
for LER 50-366/1979-135, Revision 1
Update Report - Previous Report Date 1/8/80

While operating at steady-state power on December 19, 1979, the "A" power supply for the RCIC steam leak detection system failed when a fuse on the 125VDC input blew. The failure caused four temperature switches to isolate. The redundant logic was operable. The fuse was replaced and the subsystem was returned to service. While operating at steady-state power on December 20, 1979, the "B" power supply for RCIC steam leak detection system failed in like manner as the "A" power supply above. The "A" logic was operable at the time. The fuse was replaced and the system returned to operable status. The health and safety of the public were not affected by this non-repetitive event.

This type instrument is utilized in other systems on both units, but no generic problems have been discovered at this time.

The cause of both events was attributed to excess current on the 125VDC input to the power supplies. The excess current caused fuses 7A and 7B to blow, disabling the power supplies. The fuses were replaced, and after further investigation it was discovered the contacts needed cleaning, the blower fan had to be replaced, and the cover plate over the capacitor circuit needed insulation to prevent short circuiting the capacitors whenever the plate was touched. These problems have been corrected.