


Public Service Company of Colorado

16805 Road 19 1/2, Platteville, Colorado 80651-9298

February 3, 1983 Fort St. Vrain Unit No. 1 P-83044

Mr. John T. Collins, Regional Administrator Region IV Nuclear Regulatory Commission oll Ryan Plaza Drive Suite 1000 Arlington, Texas 76011



Reference: Facility Operating License

No. DPR-34

Docket No. 50-267

Dear Mr. Collins:

Enclosed please find a copy of Reportable Occurrence Report No. 50-267/83-002, Final, submitted per the requirements of Technical Specification AC 7.5.2(b)3.

Also, please find enclosed one copy of the Licensee Event Report for Reportable Occurrence Report No. 50-267/83-002.

Very truly yours,

Warendoney Don Warembourg

Manager, Nuclear Production

DW/cls

Enclosure

cc: Director, MIPC

REPORTABLE OCCURRENCE DISTRIBUTION

	Number of Copies
Department of Energy	1 (P Letter)
Department of Energy	1 (P Letter)
Department of Energy	1 (P Letter)
Mr. John T. Collins, Regional Administrator	(1)(Original of P Letter)
Mr. George Kuzmycz Nuclear Regulatory Commission 7920 Norfolk Avenue Bethesda, Maryland 20034	1 (P Letter)
Director Office of Management Information and Program Control Nuclear Regulatory Commission Washington, D.C. 20555	1 (P Letter)
INPO Records Center	1 (P Letter)
Mr. Richard Phelps, FSV, GA, Site Representative General Atomic Company 16864 Weld County Road 19 1/2 Platteville, Colorado 80651	1 (P Letter)
NRC Resident Site Inspector	1 (P Letter)

REPORT DATE:

February 3, 1983

REPORTABLE OCCURRENCE 83-002

Determined

OCCURRENCE DATE: January 4, 1983

ISSUE 0 Page 1 of 3

FORT ST. VRAIN NUCLEAR GENERATING STATION PUBLIC SERVICE COMPANY OF COLORADO 16805 WELD COUNTY ROAD 19 1/2 PLATTEVILLE, COLORADO 80651-9298

REPORT NO. 50-267/83-002/03-L-0

Final

IDENTIFICATION OF OCCURRENCE:

On December 21 and 22, 1982, with the reactor shutdown, seven releases were made from the Reactor Building sump in the automatic During these releases, the proportional sampler was inoperable, and daily samples were not taken. This constitutes a degraded mode of LCO 4.8.3(f) and is reportable per Fort St. Vrain Technical Specification AC 7.5.2(b)3.

EVENT DESCRIPTION:

With the reactor shut down and the Reactor Building sump proportional sampler inoperable, seven separate automatic releases were made from the Reactor Building sump between the hours of 0600 on December 21 and 0800 on December 22, 1982.

During times that the continuous proportional sampler is inoperable and the Reactor Building sump pumps are in the automatic mode, daily samples are required to be taken from the sump and analysis made of the composite sample three times per week. On December 21 and 22, the daily samples were inadvertently not taken.

As required, however, each of the seven discharges were made at a release rate less than 10 GPM, monitored by two activity monitors, recorded, and diluted with a minimum fresh water flow of at least 1100 GPM to assure conformance with the limits of 10CFR20. No activity was detected during any of the discharges.

CAUSE DESCRIPTION:

Personnel error.

Due to an oversight by on-shift Radiation Protection personnel, samples of Reactor Building sump effluent were not taken on a daily basis as required when the proportional sampler is inoperable and the Reactor Building sump pumps are in the automatic mode.

REPORTABLE OCCURRENCE 83-002 ISSUE 0 Page 2 of 3

CORRECTIVE ACTION:

Daily sample taking resumed on December 23, 1982.

The individuals responsible for obtaining the December 21 and December 22 samples were reminded of their responsibility by the Radiation Protection Manager.

All Radiation Protection personnel responsible for taking Reactor Building sump samples received retraining via the Health Physics Order Book as to the requirements of Specification LCO 4.8.3, Reactor Building Sump Effluent, including the requirement to obtain samples on a daily basis.

Change Notice 1433 has been issued to the Nuclear Engineering Division. This Change Notice, inter alia, will replace the existing proportional sampler with a more reliable proportional sampler. Incorporation of the new sampler into the system will reduce the probability that daily sampling will be required.

No further corrective action is anticipated or required.

Prepared By:

Senior Technical Services Technician

Reviewed By:

Technical Services Engineering Supervisor

Reviewed By:

Edwin D. Hil Station Manager

Approved By:

Don Warembourg
Manager, Nuclear Production