LICENSEE EVENT REPORT

NRC FORM 386

LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 5 57 CAT 58
CON'T O 1 SOURCE L 6 0 5 0 0 0 3 1 7 7 0 7 2 9 8 2 8 0 8 2 6 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 At 1230, during routine surveillance testing, it was found that Reactor
Protective System Channel A axial shape index (ASI) setpoint was out of
o 4 specification in the nonconservative direction (T.S. 2.2.1 and 3.3.1.1).
The module was replaced and the channel returned to service at 1415.
The three redundant channels remained operable during this event.
0 7 Similar events: None.
0 8 L 80 7 8 9 SYSTEM CAUSE CAUSE COMP. VALVE
CODE SUBCODE COMPONENT CODE SUBCODE I A 11 E 12 G 13 I N S T R U 14 X 15 Z 16 SEQUENTIAL OCCURRENCE REPORT REVISION
C 18 Z 19 Z 20 Z 21 37 40 41 41 43 42 43 43 42 43 44 44
A high, erratic output of the comparator module (Bell & Howell #19-501-
2) caused the ASI setpoint to be out of specification at 110 percent
core power. The module was replaced with a spare from stock and the
failed module was discarded. This type module has not shown a high fail-
ure rate. No further preventive action is deemed necessary at this time.
7 8 9 SACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 E 28 1 0 0 0 29 N/A B 31 Surveillance Test 7 8 9 10 12 13 44 45 46 46
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) N/A N/A N/A 80
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 1 7 8 9 11 12 38 N/A 7 8 9 11 12 13 80
PERSONNEL INJURIES NUMBER DESCRIPTION (41) 1 8 9 11 12 80
LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION N/A PUBLICITY PDR ADDCK 05000317
2 0 N 44 N/A 80 58 69 80 5
NAME OF PREPARER J. S. Lagiewski/L. F. Basso PHONE 301-269-4747/4933

LER NO. 82-44/3L
DOCKET NO. 50-317
LICENSE NO. DPR 53
EVENT DATE 07-29-82
REPORT DATE 08-26-82
ATTACHMENT

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (CONT'D)

Troubleshooting revealed the ASI setpoint was in specification at 100 percent core power, but out of specification at 110 percent. Therefore, the trip may have been out of specification at the 105.4 percent High Power Trip setpoint. A high, erratic output of the comparator module (Bell & Howell, #19-501-2) caused the septoint offset.

The module was replaced with a spare from stock and the failed module was discarded. Setpoints are checked monthly during surveillance testing. This type of module has not exhibited a high failure rate. Therefore, no further preventive action is deemed necessary at this time.