

*Southern California Edison Company*

SAN ONOFRE NUCLEAR GENERATING STATION  
P.O. BOX 128  
SAN CLEMENTE, CALIFORNIA 92672

RECEIVED  
NRC  
SCE  
1983 FEB -4 PM 12:28  
REGION V  
TELEPHONE  
(714) 492-7700

H. B. RAY  
STATION MANAGER

U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, California 94596-5368

Attention: Mr. R. H. Engelken, Regional Administrator

Dear Sir:

Subject: Docket No. 50-361  
30-Day Report  
Licensee Event Report No. 82-159  
San Onofre Nuclear Generating Station, Unit 2

Reference: Letter, H.B. Ray (SCE) to R.E. Engelken (NRC),  
dated December 28, 1982, "30-Day Follow-Up Report -  
Licensee Event Report No. 82-159"

This letter provides the follow-up to the referenced report which was made in accordance with Section 6.9.1.13.b of Appendix A, Technical Specifications to Facility Operating License NPF-10, for San Onofre Unit 2. The reported occurrence involved Limiting Condition for Operation (LCO) 3.3.3.5 associated with Remote Shutdown Instrumentation.

As stated in the referenced letter, during performance of the monthly channel check surveillance on November 28, 1982, pressure indicator 2PI-8300 was observed to be reading more than 120 psia greater than a similar indicator located in the Control Room on Panel CR-52. The referenced letter erroneously indicated that 2PI-8300 was located on the Remote Shutdown Panel rather than the correct location on Essential Plant Parameter Monitoring System (EPPMS) panel 2L-411. As a result of the 120 psia discrepancy, 2PI-8300 was declared inoperable.

The indicator was replaced, calibrated and returned to service on November 29, 1982. We have been unsuccessful in determining the cause of the failure. This failure was an isolated occurrence and no further corrective action is planned. A final copy of LER 82-159 is enclosed.

8302150674 830131  
PDR ADDCK 05000361  
S PDR

IE-22  
83-40

January 31, 1983

Since the redundant indicator on Control Room Evacuation Shutdown Panel 2L-042 remained operable and the inoperable indicator was returned to service within the allowable time constraints, there was no impact on plant operation or the health and safety of plant personnel or the public.

If there are any questions regarding the above, please contact me.

Sincerely,

*HB Ray / H. M. M. M.*

Enclosure: LER 82-159

cc: A. E. Chaffee (USNRC Resident Inspector, San Onofre Units 2 & 3)

R. J. Pate (USNRC Resident Inspector, San Onofre Units 2 & 3)

U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement

U. S. Nuclear Regulatory Commission  
Office of Management Information and Program Control

Institute of Nuclear Power Operations