U.S. NUCLEAR BE COURTED TO BUILDING

11-11

	LICENSEE EVENT REPORT
	CONTROL BLOCK: [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 8	C A S O S 2 2 O O - O O O O O O O
0 1 7 8	REPORT LL 6 0 5 0 0 0 3 6 1 7 0 7 2 5 8 2 8 0 8 2 4 8 2 9
0 2	With the plant in Mode 4, containment pressure indicators 2P1-0351-2 and
0 3	2PI-0352-2 failed channel check test and were placed in the bypass condition,
0 4	prior to Mode 2 entry. The three remaining containment pressure indication
0 5	channels remained operable, thus there was no impact on lealth and safety of
0 6	plant personnel or the public.
0 7	
08	
0 9	SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
	TO REPORT NUMBER 21 22 23 24 26 23 CCCURRENCE REPORT TYPE NO.
	ACTION FUTURE COMPONENT SUBMITTED FORM SUB. PRIME COMP. COMPONENT SUBMITTED FORM SUB. SUPPLIER SUPPLIE
10	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The channel check failure was attributable to normal instrument drift. The
11	indicators were recalibrated and returned to service. Further corrective action
1 2	is not deemed necessary.
1 3	
1 4	
1 5	ACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 B 31 Surveillance Test
R	LEASED OF RELEASE AMOUNT OF ACTIVITY (35)
7 8	2 (33) 2 (34) NM NA
1 7	9 PERSONNEL INJURIES DESCRIPTION (39) PERSONNEL INJURIES 13
	NUMBER DESCRIPTION 41 NA
1 9	TYPE DESCRIPTION NA 8209080164 820824
2 0	PUBLICITY SSUED DESCRIPTION 45 PDR ADDCK 05000361 PDR NRC USE ONLY
The state of the s	9 10 68 69 80 8
	NAME OF PREPARER H. B. Ray PHONE: