LICENSEE EVENT REPORT

EIGENGEE EVENT REFORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 C A S 0 S 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 1 0 57 CAT 58 5
CON'T 0 1 REPORT L 6 0 5 0 0 0 3 6 1 7 0 7 1 4 8 2 8 0 8 1 3 8 2 9 7 8 8 8 8 8 8 8 8 8
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) O 2 While in Mode 3 operator noted while feeding steam generators that Auxiliary
[0]3 Feedwater (AFW) valve 2HV4714 was slow in stroking open. Consequently, the
1 motor driven AFW pump 2P-504 was declared inoperable. There was no consequence
to the public health and safety since the other two -100% AFW trains were
0 6 available to fulfill their function if required to do so.
07
7 8 9 SYSTEM CAUSE CAUSE 1 1 COMP. VALVE
TODE SUBCODE S
LER/RO EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE REPORT TYPE NO.* O 4 7 O 1 O 1 O 1 O 1 O 1 O 1 O 1 O 1 O 1 O
ACTION FUTURE ON PLANT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER B 18 Z 19 Z 20 Z 21 C 0 0 0 N 23 N 24 A 25 X 9 9 9 26
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
The failure was due to a metal shaving found in the solenoid. Corrective actions
included installation of a newly calibrated solenoid valve. Also, the oil was
changed, accumulator recharged and the Maintenance Instructions were revised
to indicate the proper oil.
7 8 9
FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 B 28 0 0 0 0 29 NA OTHER STATUS 30 DISCOVERY DESCRIPTION 32 7 8 9 10 12 13 44 45 46 80
RELEASED OF RELEASE AMOUNT OF ACTIVITY 35
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA NA NA NA NA NA NA NA NA N
PERSONNEL INJURIES NUMBER DESCRIPTION 41
7 8 9 11 12 82090B0200 ==
1 9 Z 42 NA S PDR
PUBLICITY ISSUED DESCRIPTION 45
1 8 5 10 NA SHAM 68 69 80 5