

LER NO. 82-47/3L
DOCKET NO. 50-317
LICENSE NO. DPR-53
EVENT DATE 07-30-82
REPORT DATE 08-27-82
ATTACHMENT

CAUSE DESCRIPTION - LER 50-317/82-47, Unit 1

On 7/23/82, maintenance procedure I-9 was performed to calculate RPS flow trip setpoints. During performance of the procedure, the Channel C and D flow data was transposed from the chart recorder readings resulting in improper setting of the trip units (TUs).

Channel C setpoint was nonconservative by 0.034 VDC, which is less than 1 percent, from the Technical Specifications limit although the Safety Analysis limit was not exceeded. Channel D setpoint was more conservative than required.

Maintenance procedure I-9 is being revised to include verification of the flow data before the TU setpoints are calculated.