

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | I | L | D | R | S | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 | LICENSEE CODE 14 15 | LICENSE NUMBER 25 26 | LICENSE TYPE 30 57 CAT 58 80

CONT
0 1 | L | 0 | 5 | 0 | 0 | 0 | 2 | 3 | 7 | 0 | 7 | 2 | 6 | 8 | 2 | 0 | 2 | 0 | 1 | 8 | 3 | 9
7 8 9 | REPORT SOURCE 80 61 | DOCKET NUMBER 58 60 | EVENT DATE 74 75 | REPORT DATE 80

0 2 | During routine power operation, a pin-hole leak was discovered in the one inch dia-
0 3 | meter HPCI Drain Pot Drain Line (2-2323-1-LX) to the main condenser. There was no
0 4 | impact upon the health and safety of the public as this event had no effect upon the
0 5 | availability of the HPCI system and no process effluent was released externally to
0 6 | the plant. Similar occurrences were reported by R.C. 81-21 on Docket 50-249 and
0 7 | R.O. 73-21 on Docket 50-237.

0 8 | _____ 80

0 9 | SYSTEM CODE S F (11) CAUSE CODE E (12) CAUSE SUBCODE B (13) COMPONENT CODE PIPEXX (14) COMP. SUBCODE A (15) VALVE SUBCODE Z (16)
7 8 9 | 9 10 11 12 13 14 15 16 17 18 19 20

17 | LER/RO REPORT NUMBER 8 2 (21) SEQUENTIAL REPORT NO. 0 3 4 (24) OCCURRENCE CODE 0 3 (28) REPORT TYPE X (30) REVISION NO. 1 (32)
ACTION TAKEN A (18) FUTURE ACTION Z (19) EFFECT ON PLANT Z (20) SHUTDOWN METHOD Z (21) HOURS 0 0 0 0 (22) ATTACHMENT SUBMITTED N (23) NPRO-4 FORM SUB. N (24) PRIME COMP. SUPPLIER N (25) COMPONENT MANUFACTURER U 0 8 0 (26)
33 34 35 36 37 40 41 42 43 44 47

1 0 | CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The cause of the failure was due to erosion. An 8 inch segment of the pipe includ-
1 1 | ing the elbow was replaced with an identical piece of schedule 80 carbon steel pipe.
1 2 | Repair was completed, inspected, and the line was returned to service.

1 3 | _____

1 4 | _____ 80

1 5 | FACILITY STATUS E (28) % POWER 0 6 6 (29) OTHER STATUS N/A (30) METHOD OF DISCOVERY A (31) DISCOVERY DESCRIPTION Operator Observation (32)
7 8 9 | 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 6 | ACTIVITY RELEASED Z (33) CONTENT Z (34) AMOUNT OF ACTIVITY N/A (35) LOCATION OF RELEASE N/A (36)
7 8 9 | 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 7 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) TYPE Z (38) DESCRIPTION N/A (39)
7 8 9 | 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 8 | PERSONNEL INJURIES NUMBER 0 0 0 (40) DESCRIPTION N/A (41)
7 8 9 | 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) DESCRIPTION N/A (43) 8302160159 830201 PDR ADOCK 05000237 S PDR
7 8 9 | 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

2 0 | PUBLICITY ISSUED N (44) DESCRIPTION N/A (45) NRC USE ONLY
7 8 9 | 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

CP-O 817-926

SUPPLEMENT TO DVR

DVR NO.			
STA	UNIT.	YEAR	NO.
D - 12	- 2	- 82	- 52

PART 1	TITLE OF EVENT	OCCURRED	
	Pin Hole Leak in HPCI Drain Pot Drain Line	07/26/82	0100
		DATE	TIME
	REASON FOR SUPPLEMENTAL REPORT		
	To update corrective measures taken after original report was submitted.		
PART 2			
ACCEPTANCE BY STATION REVIEW	<u><i>E. Feigely</i></u>	<u><i>J. Brunner</i></u>	<u><i>Michael Wright</i></u>
DATE	<u>2-2-83</u>	<u>2/2/83</u>	<u>2-2-83</u>
SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION	<u><i>Douglas Neott</i></u>		<u>2/3/83</u>
	STATION SUPERINTENDENT		DATE