

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 CASOIS 2 00-000000-00 341111 45
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
01 REPORT SOURCE L 605000361 7072182 8082082 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 With the plant in Mode 4, 120 VAC Vital Bus 2Y03 was de-energized from its
03 associated inverter. Normal offsite power was available throughout the event,
04 hence there was no impact on health and safety of plant personnel or the public.
05
06
07
08

09 SYSTEM CODE ED 11 CAUSE CODE A 12 CAUSE SUBCODE C 13 COMPONENT CODE ZZZZZZ 14 COMP. SUBCODE Z 15 VALVE SUBCODE Z 16
17 LER/RO REPORT NUMBER 82 EVENT YEAR 82 SEQUENTIAL REPORT NO. 072 OCCURRENCE CODE 03 REPORT TYPE L REVISION NO. 0
18 X 19 Z 20 Z 21 Z 22 0000 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER Z 25 COMPONENT MANUFACTURER Z999 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The bus was immediately re-energized to its alternate power supply. After removal
11 of an inadvertently applied ground, the bus was re-energized from its associated
12 inverter. The ground was applied during equipment testing within Radiation
13 Monitoring System Panel 2L-103. The event was an isolated occurrence and further
14 corrective action is not deemed necessary.

15 FACILITY STATUS B 28 % POWER 000 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation 32

16 ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

17 PERSONNEL EXPOSURES NUMBER 000 37 TYPE Z 38 DESCRIPTION NA 39

18 PERSONNEL INJURIES NUMBER 000 40 DESCRIPTION NA 41

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

20 ISSUED N 44 DESCRIPTION NA 45

8209080308 820820
PDR ADOCK 05000361
S PDR

NAME OF PREPARER H. B. Ray PHONE: 714/492-7700