

SEABROOK STATION Engineering Office: 1671 Worcester Road Framingham, Massachusetts 01701 (617) - 872 - 8100

August 23, 1982

SBN- 317 T.F. Q 2.2.2

United States Nuclear Regulatory Commission Office of Inspection and Enforcement Region I 631 Park Avenue King of Prussia, PA 19406

Attention:

Mr. Richard W. Starostecki, Director Division of Resident and Project Inspection

References:

- (a) Construction Permit CPPR-135 and CPPR-136, Docket Nos. 50-443 and 50-444
- (b) PSNH Letter, dated November 13, 1981, "Response to IE Bulletin 81-02, Supplement 1, 'Failure of Gate-Type Valves to Close Against Differential Pressure'," W. P. Johnson to B. Grier
- (c) PSNH Letter, dated July 17, 1981, "Reportable 10CFR50.55(e) Item 4" through 18" Motor-Operated Gate Valves Interim Report," J. DeVincentis to Office of Inspection and Enforcement
- (d) PSNH Letter, dated May 1, 1981, "Reportable 10CFR50.55(e) Item - Westinghouse 3-Inch Motor-Operated Valves," J. DeVincentis to Office of Inspection and Enforcement

Subject:

Final 10CFR50.55(e) Report; Westinghouse Motor-Operated Gate Valves (4-Inch to 18-Inch)

Dear Sir:

Reference (b) and (c) committed to providing a final report on the corrective modifications made on Westinghouse manufactured 4-inch to 18-inch motor-operated gate valves which have failed to tightly seal against differential pressure when tested at their service conditions or through analytical methods.

Reference (b) provided the following information for the subject valves scheduled to be utilized in Seabrook Station Unit 1 and Unit 2:

- Valve Function
- . Valve Location Number
- W EMD Model Reference Number
- Maximum Delta P (psi) as Flow Approaches Zero
- . Consequence of Failure to Close



I.F.27

United States Nuclear Regulatory Commission Attention: Mr. Richard W. Starostecki

.

August 23, 1982 Page 2

I have attached Table 1 which provides the above information from Reference (b) and also includes the corrective modifications, if required.

Reference (d) provided the corrective modifications made to the 3-inch valves; however, two 3-inch valves were inadvertantly omitted. These valves and the corrective modifications are included in Table 1.

Very truly yours,

YANKEE ATOMIC ELECTRIC COMPANY

Le Unites

J. DeVincentis Project Manager

TABLE 1

100

	VALVE	W EMD		FINAL		
FUNCTION	NUMBER	REFERENCE	EQUIP:	REQUIREMENT	CONSEQUENCE OF FAILURE TO CLOSE	CORRECTIVE MODIFICATIONS
VCT Outlet	LCV-1128	4GM7 2 F B	200	100	Two valves in series; failure of either valve to close reduces redundancy of providing isolation. Alternate valve will provide isolation.	Torque switch adjustment
VCT Outlet	LCV-112C	4GM7 2FB	200	100	Two valves in series; failure of either valve to close reduces redundancy of providing isolation. Alternate valve will provide isolation.	None required
RWST to Suction of CCPs	LCV-112D,E	8GM7 2 F B	200	200	One MOV in each of two parallel paths from the RWST to suction of the CCPs failure reduces redundancy of providing isolation of RWST during the recirculation phase following a LOCA. Isolation will be provided by a check valve in series with the two paths.	Adjusted torque switch settings Changed gear ratio Changed torgue switch spring pack
RHR Suction Isolation, Inner	8701B	12GM88SE	700	700	Two valves in series; failure of inner isolation valve to close reduces redundancy of providing isolation. Isolation is provided by closing the outer valve.	Adjusted torque switch settings Changed gear ratio
	8702B	12GM885E	700	700	Two valves in series; failure of inner isolation valve to close reduces redundancy of providing isolation. Isolation is provided by closing the outer valve.	Adjusted torque switch settings Changed gear ratio
RHR Suction Isolation, Inner	8701A	12GM885E	700	700	Two valves in series; failure of outer isolation valve to close reduces redundancy of providing isolation. Isolation is provided by closing the inner valve.	Adjusted torque switch settings Changed gear ratio

3

2

TABLE 1

MAXIMUM P (ps1) AS FLOW APPROACHES ZERO

.

111.21	NALVE STAR	VALVE	W END MODEL	EQUIPTI	FINAL	The second	
Č., 5	FUNCTION	NUMBER	REFERENCE	SPEC	REQUIREMENT	CONSEQUENCE OF FAILURE TO CLOSE	CORRECTIVE MODIFICATIONS
		8702A	12GH885E	700	700	Two valves in series; failure of outer isolation valve to close reduces redundancy of providing isolation. Isolation is provided by closing the inner valve.	Adjusted torque switch settings Changed gear ratio
	RHR Discharge Cross Connect	8716A, B	8GM74FE	700	300	Failure of valve to close reduces redundancy of providing low head train separation during CL recirculation phase following a LOCA. Thain separation can be achieved by closing other valve.	Adjusted torque switch settings
	RHR HX Discharge to CCP Suction	8804A	8GM74FE	700	300	Valve is opened for recirculation phase following a LOCA. Failure of valve to close precludes realignment of RHRS for normal operation.	Adjusted torque switch settings
	RHR HX Discharge to SI Pump Suction	88048	8GM74FE	700	300	Valve is opened for recirculation phase following a LOCA. Failure of valve to close precludes realignment of RHRS for normal operation.	Adjusted torque switch settings
	RWST to SI Pump Suction	3806A, B	8GM72FB	200	200	Valve is closed for recirculation phase following a LOCA. If valve fails to close, backflow into RWST is prevented by check valve in line.	Adjusted torque switch settings Changed gear ratio Changed torque switch spring pack
	CCP Suction to SI Pump Suction Crossover	8807A,B	6GM72FB	200	200	Two valves in parallel (8807A,B) in series with one valve (8924); failure of any one valve to close will not preclude isolation.	None required
		8924	6GM72F8	200	200	Two valves in parallel (8807A,B) in series with one valve (8924); failure of any one valve to close will not preclude isolation.	Adjusted torque switch settings Changed gear ratio Changed torque switch spring pack

MAXIMUM P (psi) AS FLOW APPROACHES ZERO

TABLE 1

WOL	APPR(DACHES	ZERO	
and the second second	the second second second second	the second second second second second	A Design of the local data and the	-

.

101	VALVE	LOCATION NUMBER	MODEL REFERENCE	EQUIP. SPEC	FUNCTIONAL REQUIREMENT	CONSEQUENCE OF FAILURE TO CLOSE	CORRECTIVE MODIFICATIONS
	Accumulator Discharge	8808A, B, C, D	10GM38FN	2750	0	Value is closed to prevent RCS pressurization during cold shutdown operations. If the value fails to close, the accumulator may be depressurized by venting the N_2 to the containment.	None required
	RHR Pump CL Injection	8809A, S	8GM78FN	2750	200	Valve is closed for switchover from CL to HL recirculation. Failure of valve to close will degrade flow to HLs.	None required
	RWST to RHR Pump Suction	9812A,B	12GM74FE	700	100	Valve is closed for recirculation phase following a LOCA. If valve fails to close backflow into RWST is prevented by check valve in line.	None required
	Sump Suction	8811A,B	16GM74FE	700	100	Valve is opened for recirculation following a LOCA. Valve would be closed for containment isolation. Valve is encapsulated within a protective bousing which acts as the redundant containment isolation.	None required
	SI Pump	8821A, B	4GM7 7FH	1500	1500	Valve is closed for switchcc from CL to HL recirculation. If valve fails to close, Alternate Isolation Valve 8885 can be closed.	Adjusted torque switch settings Changed gear ratio Changed torque switch spring pack
	RHR HX Discharge to HL	8840A, B	8GM78	700	200	Valve is closed for switchover from HL to CL recirculation following a LOCA. If valve fails to close, isolation is provided by closing the RHR discharge cross connect valves.	None required

1

TABLE 1

MAXIMUM P (pst) AS FLOW APPROACHES ZERO

An or the other states	UATUE	VALVE	W EMD	FOILE	FINAL	(1) State of the second	
	FUNCTION *Chg. Line Isolation	NUMBER 8105,8106	REFERENCE 3CM99	SPEC 2750	REQUIREMENT 2750	CONSEQUENCE OF FAILURE TO CLOSE Two valves in series; failure of either valve to close reduces redundancy of providing isolation. Alternate valve will provide isolation.	CORRECTIVE MODIFICATIONS Replace valves
	*PORV Block	8000 A, B	36499	2750	2500	Valve is closed to isolate a leaking or stuck open PORV. Failure of the valve to close could result in a small break LOCA. This accident is bounded by the analysis presented in Cahpter 15 of the FSAR.	Replace valves
	*SI System	8923A, B	6GM7 2 F B	200	200	Valves are closed to provide S1 pump train separation. Two valves are present, failure of one valve to close will not preclude achieving separation.	Adjusted torque switch settings Changed gear ratio Changed torque switch spring pack
	*Boron Injecti Tank Isolatio	on 8801A,8 n	4gm8 8fn	2750	0	Valves are designed to open to perform their safety function. Failure to close would delay returning system to normal valve line-up.	Adjusted torque switch settings Changed gear ratio
	*Boron Injectio Tank Isolatio	on 8803A,8 n	4GM88FN	2750	0	Valves are designed to open to perform their safety function. Failure to close would delay returning system to normal valve line-up.	Adjusted torque switch settings Changed gear ratio

*Inadvertantly omitted from Reference (d)

-

4