LICENSEE EVENT REPORT

	CONTROL SLOCK: PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION
7 8	1 LICENSEE CODE 14 15 15 UICENSE NUMBER 25 26 LICENSE TYPE JO 57 CAT 56
O I	SOURCE L 6 0 5 0 0 0 2 3 7 7 0 1 1 2 8 3 3 0 2 0 4 8 3 9
0 2	During unit refueling outage, while local leak rate testing (LLRT), it was deter-
0 3	mined that the outboard MSIV 2-203-2B was leaking in excess of Tech. Spec. 4.7.A.2.
014	limits. This event had minimal effect on public safety since there was no leakage
0 5	from the respective inboard isolation valve. A similar event was reported by R.O.
06	82-02/03L on Docket #50-249.
0 7	
018	
0 9	SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
	TO LERINO EVENT YEAR SEQUENTIAL REPORT NO. SEQUENTIAL REPORT NO.
	ACTION FUTURE COMPONENT SHUTDOWN METHOD HOURS 22 ATTACHMENT PORM SUB. SUPPLIER COMPONENT MANUFACTURER - SUBMITTED FORM SUB. SUPPLIER MANUFACTURER - SUBMITTED NOR SUB. SUPPLIER SUBMITTED NOR SUB. SUPPLIER MANUFACTURER - SUBMITTED NOR SUB. SUPPLIER SUBMITTED NOR SUB. SUPPLIER SUBMITTED NOR SUBM
	The cause of occurrence was valve packing leakage. The packing was tightened and
1101	
	the valve retested satisfactorily. Final leakage was 6.59 SCFH. In addition, any
1 2	subsequent LLRT results which exceed Tech. Spec. limits will be reported by a sup-
1 3	plement to this report at the conclusion of LLRT.
1 4	
	STATUS OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 N/A B 31 Local Leak Rate Test
- RE	ILEASED OF RELEASE AMOUNT OF ACTIVITY 35
7 8	Z 33 Z 34 N/A N/A PERSONNEL EXPOSURES N/A 30
1 7	NUMBER OESCRIPTION (39)
7 8	PERSONNEL INJURIES 13 8302160198 830204 90 9DR ADDCK 05000237 9DR
7 3	LOSS OF OR DAMAGE TO FACILITY (42)
1 9	Z 42 N/A
2 0 "	PUBLICITY SSUED DESCRIPTION 45 NAC USE ONLY N/A
7 8	58 69 80.5
	NAME OF PREPARER Sang Rhee PHONE: 815-942-2920, X-548