	LICENSEE EVENT REPORT
	CONTROL BLOCK: [ ] [ ] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	N J S G S 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 6.
CON'T 0 1 7 8	REPORT LG 0 5 0 0 0 3 1 1 7 0 8 1 8 8 2 8 0 8 2 5 8 2 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  At 0220 hours, August 18, 1982, during routine operation, the Control Room Operator
0 3	discovered indication of leakage from No. 21 Containment Fan Coil Unit. At 0225 hours,
0 4	No. 21 CFCU was declared inoperable, isolated, and Technical Specification Action State-
0 5	ment 3.6.2.3a was entered. The NRC was notified by telephone with written confirmation
0 6	transmitted on August 18, 1982. A containment entry was made and it was discovered
0 7	that the fifth secondary coil from the bottom of the CFCU was leaking. Both contain-
0 8	ment spray systems were operable throughout the occurrence.
7 8	SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
10	The cause was erosion of the copper nickel piping. The leak was isolated and repaired.
11	No. 21 CFCU was satisfactorily tested and Action Statement 3.6.2.3a was terminated at
1 2	1650 hours, August 19, 1982. Design Change Request 2EC-0505 has been issued to
1 3	replace the cooling coils with a more erosion resistant material.
7 8	
1 5	ACILITY STATUS STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 DISCOVERY D
1 6 PE	LEASED OF RELEASE AMOUNT OF ACTIVITY (35)  Z 33 Z 34 NA  PERSONNEL EXPOSURES  AMOUNT OF ACTIVITY (35)  NA  LOCATION OF RELEASE (36)  NA  80
7 8	NUMBER TYPE DESCRIPTION (39)  O O O O O O O O O O O O O O O O O O O
1 8	d ol d@ NA
1 9	LOSS OF OR DAMAGE TO FACILITY 43  TYPE DESCRIPTION    Z   42   NA     9 10   8209080325 820825     9 10   8209080325 820825     9 10   8209080325 820825     10   820908080     10   8209080
, 8	9 10 68 69. 80 5 NAME OF PREPARER R. Heller PHONE: (609) 541-5900 629