LICENSEE EVENT REPORT

| CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) |
|--|
| 0 1 M I D C C 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 CAT 58 |
| SOURCE L 6 0 5 0 0 0 3 1 6 7 0 1 2 4 8 3 8 0 2 0 8 8 3 9 |
| EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (1) [0 2 DURING NORMAL OPERATION, NO. 3 S/G STOP VALVE DUMP VALVE, MRV-232, WAS REMOVED FROM] |
| SERVICE TO REPAIR SEAT LEAKAGE. THIS CONDITION PLACED NO. 3 S/G STOP VALVE IN A LESS |
| CONSERVATIVE CONFIGURATION THAN REQUIRED BY T.S. 3.7.1.5. THE REDUNDANT VALVE |
| REMAINED OPERABLE. ACTION REQUIREMENTS WERE MET. PUBLIC HEALTH AND SAFETY WERE NOT |
| [0] [AFFECTED. SIMILAR OCCURRENCES: RO'S 81-016, 81-069, 81-070, 82-038, 82-644 AND FOR] |
| O[7] DOCKET 050-315; 82-085, 82-017 AND 82-863. |
| 0 3 |
| SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBC |
| SEQUENTIAL REPORT NO. 17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32 ACTION FUTURE EFFECT SHUTDOWN COMPONENT |
| TAKEN ACTION ON PLANT METHOD HOURS (22) SUBMITTED FORM SUB. SUPPLIER MANUFACTURER A 18 Z 19 Z 20 Z 21 0 0 0 0 0 N 23 N 24 A 5 F 1 2 7 26 |
| CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) THE VALVE WAS REMOVED FROM SERVICE TO REPAIR SEAT LEAKAGE. THE VALVE STEM, PLUG, |
| CAGE, SEAT RING, AND GASKETS WERE REPLACED IN THE FISHER STYLE 657 EAS VALVE AND THE |
| VALVE WAS RETURNED TO SERVICE IN 2 HOURS AND 18 MINUTES. SEAT LEAKAGE IN VALVES IN |
| THIS TYPE OF SERVICE IS NOT TOTALLY AVOIDABLE. NO FURTHER ACTION IS PLANNED. |
| |
| FACILITY STATUS OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 OPERATOR OBSERVATION |
| ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 I 6 Z 33 Z 34 NA NA LOCATION OF RELEASE 36 |
| NUMBER TYPE DESCRIPTION 39 NA . |
| PERSONNEL INJURIES NUMBER DESCRIPTION 12 NA |
| LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA NA |
| PUBLICITY ISSUED DESCRIPTION (E) NA S PDR ADOCK 05000316 PDR ADOCK 05000316 |
| NAME OF PREPARER PAUL CARTEAUX PHONE 616-465-5901 |