

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | I | A | O | A | C | I | 2 | 0 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 1 | 1 | 4 | 5

CON'T  
0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 3 | 1 | 7 | 0 | 6 | 0 | 2 | 8 | 1 | 8 | 0 | 9 | 0 | 1 | 8 | 2 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  
0 2 | During reactor startup suppression chamber to drywell vacuum breaker val  
0 3 | ve. CV 4327H, did not close after torus inerting. Reactor taken to cold  
0 4 | shutdown complying with Tech Spec 3.7.A.4. Maintenance action completed  
0 5 | within 18 hours. No previous occurrences of this type have been reported  
0 6 |  
0 7 |  
0 8 |

0 9 | S | A | 11 | E | 12 | B | 13 | V | A | L | V | O | P | 14 | D | 15 | Z | 16

17 | LER/RO REPORT NUMBER | 8 | 1 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 | 48

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27  
1 0 | Valve inoperability caused by pneumatic cylinder piston sticking in mid-  
1 1 | position. Stuck piston and pistons of valves CV-4327A thru G lubed and t  
1 2 | ested-found sat. Valve is Model LD-240-208 made by General Precision Sys  
1 3 | tems, Inc. CV-4327H cylinder will be re-examined during next refueling o  
1 4 | utage to determine if valves require additional preventative maint.

1 5 | C | 28 | 0 | 3 | 7 | 29 | NA | 30 | B | 31 | Operator Observation | 32

1 6 | Z | 33 | Z | 34 | NA | 35 | NA | 36

1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39

1 4 | 0 | 0 | 0 | 40 | NA | 41

1 3 | Z | 42 | NA | 43

2 0 | N | 44 | NA | 8209130106 820907  
PDR ADOCK 05000331  
S PDR  
W. M. Bentley  
NRC USE ONLY  
PHONE: 319-851-5611