

CONTROL BLOCK: [] [] [] [] [] [] [] [] [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | P | A | S | E | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | [] | 5
7 8 9 14 15 23 26 30 37 38

CONT

0 1 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 8 | 7 | 7 | 0 | 8 | 1 | 1 | 8 | 2 | 8 | 0 | 9 | 0 | 1 | 8 | 2 | 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During initial fuel loading, it was determined that a sprinkler system did
0 3 | not exist in an area where both the Tech Specs and the Fire Protection Review
0 4 | Report listed a system. This event was determined reportable per Operating
0 5 | License Condition 2.G(a). For Unit 1, no redundant cables are in the area of
0 6 | concern, therefore, no adverse consequences existed.

0 7 |
0 8 |

0 9 | SYSTEM CODE: A B (11) CAUSE CODE: B (12) CAUSE SUBCODE: C (13) COMPONENT CODE: Z Z Z Z Z Z (14) COMP. SUBCODE: Z (15) VALVE SUBCODE: Z (16)
17 | LER/RO REPORT NUMBER: 8 2 (21) SEQUENTIAL REPORT NO.: 0 0 3 (24) OCCURRENCE CODE: 0 1 (27) REPORT TYPE: T (30) REVISION NO.: 1 (32)
ACTION TAKEN: X (33) FUTURE ACTION: F (34) EFFECT ON PLANT: Z (35) SHUTDOWN METHOD: Z (36) HOURS: 0 0 0 0 (37) ATTACHMENT SUBMITTED: Y (40) NPRD-4 FORM SUB.: N (42) PRIME COMP. SUPPLIER: A (43) COMPONENT MANUFACTURER: Z 9 9 9 (44)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The room where the cables are located will be reclassified as a separate
1 1 | fire zone. No sprinkler system needs to be installed for Unit 1 operation,
1 2 | because redundant cables are not in that zone. The Fire Protection Review
1 3 | Report and Tech Specs will be revised, and a review of as-built conditions will
1 4 | verify no other inconsistencies exist.

1 5 | FACILITY STATUS: B (28) % POWER: 0 0 0 (29) OTHER STATUS: n/a (30) METHOD OF DISCOVERY: B (31) DISCOVERY DESCRIPTION: observation (32)

1 6 | ACTIVITY CONTENT RELEASED: Z (33) Z (34) AMOUNT OF ACTIVITY: n/a (35) LOCATION OF RELEASE: n/a (36)

1 7 | PERSONNEL EXPOSURES NUMBER: 0 0 0 (37) TYPE: Z (38) DESCRIPTION: n/a (39)

1 8 | PERSONNEL INJURIES NUMBER: 0 0 0 (40) DESCRIPTION: n/a (41)

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE: Z (42) DESCRIPTION: n/a (43)

2 0 | PUBLICITY ISSUED: N (44) DESCRIPTION: n/a (45)

NAME OF PREPARER: D.G. Mitchell PHONE: (717) 542-2181 X524

LICENSEE EVENT REPORT 82-003/01T-1

On August 18, 1982, it was determined that a sprinkler system for Fire Zone 1-6A, listed in the Technical Specifications and the Fire Protection Review Report, was not installed in the plant. In accordance with Limiting Conditions for Operation 3.7.6.2, an hourly fire watch was established. Design reviews show that there are seven safety related conduits running through Room I-621 containing cables affecting redundant equipment in Unit 2, including common Division II Diesel Generators and switchgear. Because of the absence of redundant Unit 1 cables in Fire Zone 1-6A, there is no requirement to install a sprinkler system prior to Unit 2 operation. For Unit 2 operation, the necessary fire protection modifications will be installed, which will be reflected in the Unit 2 Technical Specifications. The Fire Protection Review Report and Technical Specifications will be revised to reflect the acceptable plant conditions.