

LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | 1 | | | | | | 6 | | | | | |

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M | A | P | P | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | | | 5

CON'T
0 1 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | - | 0 | 2 | 9 | 3 | 7 | 0 | 8 | 0 | 4 | 8 | 2 | 8 | 0 | 9 | 0 | 2 | 8 | 2 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 | On 8/4/82, during recovery from a scram, MOV #220-2 indicated an intermediate
0 3 | position. The redundant valve indicated and was verified to be in the correct closed
0 4 | position. The subject valve was declared inoperable and an investigation verified
0 5 | that the valve was closed. Therefore, this event caused no threat to the public
0 6 | health. The NRC was notified via ENS. These valves are 3" Velan gate valves with
0 7 | Model #SMBOCO Limatorque actuator.

0 9 | SYSTEM CODE | S | D | 11 | CAUSE CODE | E | 12 | CAUSE SUBCODE | B | 13 | COMPONENT CODE | V | A | L | V | O | P | 14 | COMP. SUBCODE | B | 15 | VALVE SUBCODE | Z | 16

(17) LER/RO REPORT NUMBER | 8 | 2 | 21 | 22 | SEQUENTIAL REPORT NO. | - | 0 | 2 | 8 | 24 | 26 | OCCURRENCE CODE | / | 0 | 3 | 27 | 29 | REPORT TYPE | L | 30 | REVISION NO. | - | 0 | 32

ACTION TAKEN | A | 18 | FUTURE ACTION | Z | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 22 | ATTACHMENT SUBMITTED | N | 23 | NPRD-4 FORM SUB. | N | 24 | PRIME COMP. SUPPLIER | A | 25 | COMPONENT MANUFACTURER | L | 2 | 0 | 0 | 0 | 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0 | Worn limit switch components in the Limatorque actuator caused the erroneous indication
1 1 | In addition, the valve stem nut was found to have worked loose from the stakes which
1 2 | could have contributed to the erroneous indication. The actuator components were re-
1 3 | placed, the stem nut re-staked, the valve and actuator tested satisfactorily and re-
1 4 | turned to service on 8/15/82. The loose stem nut is an isolated event.

1 5 | FACILITY STATUS | X | 28 | % POWER | 0 | 0 | 0 | 29 | OTHER STATUS | Scram Recovery | 30 | METHOD OF DISCOVERY | A | 31 | DISCOVERY DESCRIPTION | Operator Observation | 32

1 6 | ACTIVITY CONTENT RELEASED OF RELEASE | Z | 33 | Z | 34 | AMOUNT OF ACTIVITY | N/A | 35 | LOCATION OF RELEASE | N/A | 36

1 7 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | N/A | 39

1 8 | PERSONNEL INJURIES NUMBER | Z | Z | Z | 40 | DESCRIPTION | N/A | 41

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | N/A | 43

ISSUED | 2 | 0 | PUBLICITY | N | 44 | 8209130186 820903 PDR ADOCK 05000293 S PDR | N/A | NRC USE ONLY

GPO 91-7-926