

## LICENSEE EVENT REPORT

CONTROL BLOCK: 1 1 1 1 1 | 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1	A   D   A   C   1	2	0   0   -   0   0   0   0   0   0	-   0   0   0   0   0   0	3   4   1   1   1   1   1	4   0   0   0   0   0   0   0	5					
7 8	LICENSEE CODE	14 15	LICENSE NUMBER						25 26	LICENSE TYPE	20	57 CAT 56

CONT'

0 1	REPORT SOURCE	1   L   C   0   5   0   0   0   3   3   1	7   0   8   0   9   8   2   1   5   0   9   0   3   8   1   2   9										
7 8	50 51	61	DOCKET NUMBER						68 69	EVENT DATE	74 75	REPORT DATE	80

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

- 0 2 | During normal operation surveillance testing, drywell pressure switch PS  
 0 3 | -4312C tripped at 0.9 psig and would not reset properly upon decreasing  
 0 4 | pressure. Tech. Spec. Table 3.2-B requires trip setpoint between 1.0 and  
 0 5 | 2.0 psig. PS-4312C provides permissive for containment spray operation a  
 0 6 | nd terminates operation when pressure decreases below setpoint. Redundan  
 0 7 | t switches were tested satisfactorily. Eight previous similar occurrence  
 0 8 | s (see A0 74-5, R0 76-77, 78-6, 79-32, 80-7, 80-42, 80-56, and 82-27).  
 7 8 9

0 9	SYSTEM CODE	S B	11	CAUSE CODE	E	12	CAUSE SUBCODE	E	13	COMPONENT CODE	I N S T I R U	14	COMP. SUBCODE	S	15	VALVE SUBCODE	Z	16	
7 8	9 10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26		
(17) LER/R0 REPORT NUMBER	EVENT YEAR	18   21	22	SHUTDOWN METHOD	I	23	SEQUENTIAL REPORT NO.	10   15   2	24	OCCURRENCE CODE	10   3	25	REPORT TYPE	L	26	REVISION NO.	0	27	
ACTION TAKEN	FUTURE ACTION	E	18   21	22	EFFECT ON PLANT	Z	20	HOURS	10   0   0   0	21	ATTACHMENT SUBMITTED	N	23	NFR0-4 FORM SUB.	N	24	PRIME COMP. SUPPLIER	N	25
32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27																			

- 1 0 | Improper setpoint caused by instrument drift. Lack of reset caused by sw  
 1 1 | itch deadband greater than setpoint and is attributed to design misappli  
 1 2 | cation. PS-4312C is Static-O-Ring Model 6N-AA-21-(X9)-VSTT pressure swit  
 1 3 | ch. Switch recalibrated, manually reset, and tested satisfactorily. Desi  
 1 4 | gn change to replace PS-4312C and redundant switches will be pursued.  
 7 8 9

FACILITY STATUS	% POWER	OTHER STATUS	30	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION	32									
1 5   F	29   0   7   7   29   NA		30	B   31   Surveillance Test		32									
7 8 9	10 11	12 13	44	45	46	47									
ACTIVITY RELEASED OR RELEASE	CONTENT	AMOUNT OF ACTIVITY	35												
1 6   Z	33   Z	34   NA	35												
7 8 9	10 11	12 13	44												
PERSONNEL EXPOSURES															

NUMBER	TYPE	DESCRIPTION	39												
1 7   0   0   0	37   Z	38   NA	39												
7 8 9	10 11	12 13	44												
PERSONNEL INJURIES															

NUMBER	DESCRIPTION	41													
1 4   0   0   0	40   NA	41													
7 8 9	10 11	12 13	44												
LOSS OF OR DAMAGE TO FACILITY															

TYPE	DESCRIPTION	43													
1 9   Z	42   NA	43													
7 8 9	10 11	12 13	44												
PUBLICITY															

ISSUED	DESCRIPTION	45													
2 0   N	44   NA	45													
7 8 9	10 11	12 13	44												
NAME OF PREPARED										NRC USE ONLY					

8209130231 820903

PDR ADOCK 05000331

S PDR

PHONE: 319-851-5611

NAME OF PREPARED: David M. Varner