The Light company

South Texas Project Electric Generating Station P. O. Box 289 Wadsworth, Texas 77483 Houston Lighting & Power_

> March 28, 1994 ST-HL-AE-4751 File No.: G9.18 10CFR50 App A

U. S. Nuclear Regulatory Commission Attention: Document Control Desk Washington, DC 20555

South Texas Project Units 1 and 2 Docket Nos. STN 50-498; STN 50-499 Additional Information Regarding Performance of Main Cooling Reservoir and Essential Cooling Pond During and After Filling to Elevation + 45 Feet (TAC Nos. M86279 and M86280)

Reference: NRC Request for Addition Information Letter from Mr. Lawrence Kokajko of the NRC Staff to Mr. William T. Cottle dated February 10, 1994. (ST-AE-HL-93712)

Houston Lighting & Power Company (HL&P) herein submits additional information regarding performance on Main Cooling Reservoir (MCR) and Essential Cooling Pond (ECP) during and after filling to elevation + 45 feet as requested by Mr. Lawrence Kokajko of the NRC Staff in the referenced letter of February 10, 1994.

The attachment includes HL&P's response to the questions of the referenced letter, profile cross sections of the MCR embankment, and a plot of South Texas Project Electric Generating Station (STPEGS) Main Cooling Reservoir "Seepage Gradient vs Thickness of Top Clay Layer", and a table of calculations.

If there are further questions regarding this matter, please contact Mr. A. W. Harrison at (512) 972-7298 or me at (512) 972-8787.

9404040105 940328 PDR ADDCK 05000498

Cloninger Vice Pregident

Nuclear Engineering

Houston Lighting & Power Company South Texas Project Electric Generating Station

ST-HL-AE-4751 File No.: G9.18

Page 2

Attachment:

Response to the NRC Request For Additional Information letter of February 10, 1994 from Mr. Lawrence Kokajko of the NRC Staff to Mr. William T. Cottle.

Houston Lighting & Power Company South Texas Project Electric Generating Station ST-HL-AE-4751 File No.: G9.18 G25 Page 3

C

Regional Administrator, Region IV U. S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 400 Arlington, TX 76011

Lawrence E. Kokajko Project Manager U. S. Nuclear Regulatory Commission Washington, DC 20555 13H15

David P. Loveless Sr. Resident Inspector c/o U.S. Nuclear Regulatory Comm. P. O. Box 910 Bay City, TX 77404-910

J. R. Newman, Esquire Newman & Holtzinger, P.C., STE 1000 1615 L Street, N.W. Washington, DC 20036

K. J. Fiedler/M. T. Hardt City Public Service P. O. Box 1771 San Antonio, TX 78296

J. C. Lanier/M. B. Lee City of Austin Electric Utility Department 721 Barton Springs Road Austin, TX 78704

G. E. Vaughn/T. M. Puckett Central Power and Light Company P. O. Box 2121 Corpus Christi, TX 78403 Rufus S. Scott Associate General Counsel Houston Lighting & Power Company P. O. Box 61867 Houston, TX 77208

Institute of Nuclear Power Operations - Records Center 700 Galleria Parkway Atlanta, GA 30339-5957

Dr. Joseph M. Hendrie 50 Bellport Lane Bellport, NY 11713

D. K. Lacker
Bureau of Radiation Control
Texas Department of Health
1100 West 49th Street
Austin, TX 78756-3189

U. S. Nuclear Regulatory Comm. Attn: Document Control Desk Washington, D.C. 20555

RESPONSE TO NRC REQUEST FOR ADDITIONAL INFORMATION LETTER DATED FEBRUARY 10, 1994

Requested information:

- 1. Perform necessary investigations to determine if the high water table in the Main Cooling Reservoir (MCR) embankment sand core is a temporary phenomenon. If it is not a temporary phenomenon, plot the phreatic surface across the embankment section at a few representative locations and compare them with that assumed in the original embankment stability analysis, and determine the factor of safety of the embankment against failure for the high water table condition.
- 2. Determine the cause for the high seepage gradients across three cross sections of the MCR embankment. Evaluate the effects of such high gradients on the stability of the embankment and take suitable measures to reduce the high seepage gradients to acceptable levels.

Response to item 1:

Attached profiles 3, 19, and 31 are cross sections of the MCR embankment at locations with relatively high water tables in the sand core. The water table in the sand core has been remarkably stable since completion of construction.

The original embankment stability analysis assumed a phreatic surface extending from the maximum design reservoir elevation of +49 feet to the top of the +35 foot berm on the down-stream side of the embankment ("Evaluation of Strength Parameters and Stability, Main Cooling Reservoir Embankment", Harza Engineering Co., September, 1984, ST-XH-YB-013). As shown on the Profiles, the assumed phreatic surface for the stability analysis is conservatively above the water level in the sand core.

Factors of safety based on assumed piezometric levels are presented on attached table 2 from the above referenced report, ST-HX-YB-060. Although the phreatic surface in the sand core is higher than expected, it remains below the design parameters selected.

Response to item 2:

Attached Profile 9, is a MCR embankment cross section at an area with the highest seepage gradient, 7.4% overall (measured between piezometers P38 and P40). This seepage gradient was calculated with a reservoir pool elevation of 43.5 feet. The seepage gradient at the operating reservoir level of 45 feet has been calculated at 8.3%. The drained embankment core and seepage blanket under the down-stream half of the embankment effectively reduced this gradient to a maximum calculated value of 3.8% outside the down-stream toe of the embankment, (measured between piezometers P39 and P40).

Attachment ST-HL-AE-4751 Page 2

Attached is plot "STPEGS Main Cooling Reservoir, Seepage Gradient vs Thickness of Top Clay Layer" showing a very rough inverse correlation between the thickness of the surfical impermeable zone and seepage gradient. The stratigraphic information used in this plot is from information derived along the dam axis. The highly variable nature of the stratigraphy masks what should be a good inverse correlation. The 7.4% seepage gradient is probably in an area with a near surface permeable zone in the reservoir. This zone does not extend under the embankment.

With respect to embankment stability, piezometeric levels used to determine stability factors of safety are higher than measured piezometric levels. Therefore, there is no reason to recalculate factors of safety based on measured piezometeric levels.

Table 2. Summary of Stability Analysis Results

Factor of Safety

Section	Steady State	Drawdown from El. 49 to El. 39	Seismic
Station 20+00			
Upstream Downstream	1.82 1.72	1.50≠	1.34 * (0.1g) 1.25 (0.1g)
Station 105+00			
Upstream Downstream	1.76 1.72	1.41#	1.46 ≠ (0.05g) 1.25 (0.05g)
Station 250+00			
Upstream Downstream	1.81	1.48≠	1.49 (0.05g) 1.42 (0.05g)
Station 365+00			
Upstream Downstream	1.89 1.77	1.54≠	1.52 (0.05g) 1.49 (0.05g)

Same failure surface as critical surface using steady state conditions.






-20 00 20 00 80 00

PROFILE 9
EMBANKMENT STATION 160408
SOUTH TEXAS PROJECT
14825-001







-20 00 00 00 00 00 02-

100-928*4

6 20 40 00 80 00 12t ou




PROFILE 3: EMBANKMENT STATION 6:0+000 SOUTH TEXAS PROJECT :4925-001 0 or 40 co 80 co 120 co




STPEGS MAIN COOLING RESERVOIR

SEEPAGE GRADIENT VS THICKNESS OF TOP CLAY LAYER




SEEPAGE GRADIENT — CLAY THICKNESS




PROFILE 3
EMBANKMENT STATION 20+00
SOUTH TEXAS PROJECT
14925-001

0 00 40 00 80.00 120 00 SCALE IN FEET







9404040105-01



PROFILE 9
EMBANKMENT STATION 160+00
SOUTH TEXAS PROJECT
14926-001







ANSTEC APERTURE CARD


Also Available on Aperture Card

CD227.001



PROFILE 19
EMBANKMENT STATION 359+60
SOUTH TEXAS PROJECT
14926-001





ANSTEC APERTURE CARD


Also Available on Aperture Card


C0224.00





PROFILE 31
EMBANKMENT STATION 610+00
SOUTH TEXAS PROJECT
14926-001





ANSTEC APERTURE CARD

Also Available on Aperture Card

00826.00

9404040105-04