



Northern States Power Company

414 Nicolet Mall  
Minneapolis, Minnesota 55401-1977  
Telephone (612) 330-5500

March 31, 1994

10 CFR Part 50  
Section 50.73

U S Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555

PRAIRIE ISLAND NUCLEAR GENERATING PLANT  
Docket Nos. 50-282 License Nos. DPR-42  
50-306 DPR-60

Auto-start of No. 121 Cooling Water Pump on Low Header  
Pressure While Aligned for Safeguards Operation

The Licensee Event Report for this occurrence is attached. In the report, we made no new NRC commitments.

This event was reported via the Emergency Notification System in accordance with 10 CFR Part 50, Section 50.72, on March 1, 1994. Please contact us if you require additional information related to this event.

Roger O Anderson  
Director  
Licensing and Management Issues

c: Regional Administrator - Region III, NRC  
NRR Project Manager, NRC  
Senior Resident Inspector, NRC  
Kris Sanda, State of Minnesota

Attachment

10/1940

9404040127 940331  
PDR ADOCK 05000282  
S PDR

JE22

LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNRB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Prairie Island Nuclear Generating Plant U.1	DOCKET NUMBER (2) 05000 282	PAGE (3) 1 OF 4
--	--------------------------------	--------------------

TITLE (4) Auto-start of No. 121 Cooling Water Pump on Low Header Pressure While Aligned for Safeguards Operation

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
03	01	94	94	-- 01 --	00	03	31	94	Prairie Island U2	05000 306
									FACILITY NAME	DOCKET NUMBER
										05000

OPERATING MODE (9)	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11)									
	20.402(b)			20.405(c)			X 50.73(a)(2)(iv)			73.71(b)
	20.405(a)(1)(i)			50.36(c)(1)			50.73(a)(2)(v)			73.71(c)
	20.405(a)(1)(ii)			50.36(c)(2)			50.73(a)(2)(vii)			OTHER
	20.405(a)(1)(iii)			50.73(a)(2)(i)			50.73(a)(2)(viii)(A)			(Specify in Abstract below and in Text, NRC Form 366A)
20.405(a)(1)(iv)			50.73(a)(2)(ii)			50.73(a)(2)(viii)(B)				
20.405(a)(1)(v)			50.73(a)(2)(iii)			50.73(a)(2)(x)				

LICENSEE CONTACT FOR THIS LER (12)

NAME Arne A Hunstad	TELEPHONE NUMBER (Include Area Code) 612-388-1121
------------------------	--

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE).	X NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
---	------	-------------------------------	-------	-----	------

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

On March 1, 1994, both units were at 100% power. No. 11 Motor-driven Cooling Water Pump was running and supplying all cooling water loads. See Figure One. Technical Specifications allow a diesel cooling water pump to be removed from service with no Limiting Condition for Operation entry, provided that No. 121 Cooling Water Pump is aligned to supply the affected header. No. 121 Cooling Water Pump had been aligned for safeguards operation (valves C and D closed) in accordance with Technical Specification 3.3.D.1.a., in order to isolate No. 12 Diesel Cooling Water Pump for repair of a leaking lube oil fitting. After the repair was made, No. 12 pump was started locally to verify the leak had been fixed. The discharge valve for No. 11 pump was then slowly closed to allow No. 12 pump to gradually assume the header load, and No. 11 pump to be unloaded and shut down. After No. 12 pump had been run for 1 hour, No. 11 pump was restarted to assume the header load and No. 12 pump was shut down. When No. 12 pump was shut down locally, No. 11 pump did not pick up the header loads quickly enough, and the resultant decrease in header pressure was sufficient to cause No. 121 pump to start automatically at 1408 hours. This was a nonsafeguards actuation of an ESF component.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Prairie Island Unit 1	05000 282	94	-- 001 --	00	2 OF 4

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

EVENT DESCRIPTION

On March 1, 1994, both units were at 100% power. No. 11 Motor-driven Cooling Water Pump was running and supplying all cooling water loads. See Figure One. Technical Specifications allow a diesel cooling water pump to be removed from service with no Limiting Condition for Operation entry, provided that No. 121 Cooling Water Pump is aligned to supply the affected header. No. 121 Cooling Water Pump had been aligned for safeguards operation (valves C and D closed) in accordance with Technical Specification 3.3.D.1.a., in order to isolate No. 12 Diesel Cooling Water Pump for repair of a leaking lube oil fitting. After the repair was made, No. 12 pump was started locally to verify the leak had been fixed. The discharge valve for No. 11 pump was then slowly closed to allow No. 12 pump to gradually assume the header load, and No. 11 pump to be unloaded and shut down. After No. 12 pump had been run for 1 hour, No. 11 pump was restarted to assume the header load and No. 12 pump was shut down. When No. 12 pump was shut down locally, No. 11 pump did not pick up the header loads quickly enough, and the resultant decrease in header pressure was sufficient to cause No. 121 pump to start automatically at 1408 hours. This was a nonsafeguards actuation of an ESF component.

CAUSE OF THE EVENT

Cause of the event was inadequate procedures. Neither the work package nor the system operating procedure addressed the potential for auto-start of No. 121 Cooling Water Pump when swapping pumps. As a result of the previously reported auto-start (Unit 1 LER 93-006), the routine surveillance procedures and annual PM procedures were revised; the system operating procedure was not revised. Post-maintenance testing required only that integrity of the lube oil system piping be verified; the surveillance procedure was not required to be performed to prove operability. No. 12 pump was tested using the normal system operating procedure.

ANALYSIS OF THE EVENT

This was a non-ESF actuation of a dual function component. No. 121 motor-driven cooling water pump is used for both routine plant operation and for long-term accident mitigation. The automatic start on low header pressure is a response to a process action and is not used for accident mitigation. The pump, motor and switchgear are designed for thousands of starts. This one unplanned start had no deleterious effect on the equipment. The system was, at all times, available for its safeguards function. Health and safety of the public were unaffected. Nonetheless, the event is being reported pursuant to 10CFR50.73(a)(2)(iv).

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Prairie Island Unit 1	05000 282	94	-- 001 --	00	3 OF 4

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

CORRECTIVE ACTION

The system operating procedure has been revised.

Feasibility of applying a time delay to the start circuitry for No. 121 Cooling Water Pump will be considered.

FAILED COMPONENT IDENTIFICATION

None.

PREVIOUS SIMILAR EVENTS

One previous unplanned auto-start of No. 121 Cooling Water Pump was reported as Unit 1 LER 93-006.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Prairie Island Unit 1	DOCKET NUMBER (2) 05000 282	LER NUMBER (6)		PAGE (3) 4 OF 4
		YEAR 94	SEQUENTIAL NUMBER -- 001 --	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)




FIGURE ONE