



EDISON DRIVE
AUGUSTA, MAINE 04336
(207) 623-3521

February 17, 1983
MN-83-29

JHG-83-33

Director of Nuclear Reactor Regulation
United States Nuclear Regulatory Commission
Washington, D. C. 20555

Attention: Mr. Robert A. Clark, Chief
Operating Reactors Branch No. 3
Division of Licensing

Reference (a) License No. DPR-36 (Docket No. 50-309)

Subject: Main Feedwater System

Dear Sir:

This letter transmits information for the docket relating to resolution of the recent feedwater system event at the Maine Yankee Atomic Power Station.

This material is essentially what was presented at the meeting held on February 9, 1983 in the Commission's Bethesda, Maryland offices to review the event and Maine Yankee's program of corrective actions. Minor revisions have been made for editorial purposes. Commentaries have been added to reflect some of the discussion which took place during the February 9, 1983 meeting. The description of the water hammer test has been revised to reflect discussions with the staff which followed the February 9 meeting.

The staff is to be commended for their prompt attention and expedited handling of this matter.

We trust this information is satisfactory. If there are any questions, please do not hesitate to call.

Very truly yours,

MAINE YANKEE ATOMIC POWER COMPANY

John H. Garrity, Senior Director
Nuclear Engineering and Licensing

8302230554 830217
PDR ADOCK 05000309
S PDR

JHG:pjp

Enclosure (98 pages)

cc: Mr. Ronald C. Haynes
Mr. Paul A. Swetland

A001
Limited Dist

MAINE YANKEE ATOMIC POWER STATION FEEDWATER EVENT

TABLES OF CONTENTS

- 1) Introduction
- 2) General Description of Plant
- 3) Description of Feedwater System Flow Paths and Feedwater Piping,
Safe End and Steam Generator Nozzle Configuration
- 4) Description of Event, Photographs
- 5) Feedwater System Damage Mechanisms
- 6) Inspection and Repair
- 7) Modifications to Equipment and Procedures
- 8) Responses to NRC Staff Questions
- 9) Pre-Startup Tests
- 10) Justification for Return to Power

1) INTRODUCTION

On January 25, 1983, Maine Yankee experienced a feedwater line steam-water hammer event that caused the feedwater line adjacent to a steam generator to crack through and leak. This report describes the plant systems and components related to the event, its causes and consequences, the repairs and modifications that were made or planned, and provides a justification for continued power operation. Most of the material contained herein was presented to the NRC at a meeting held at their offices on February 9, 1983. It has been supplemented by commentary reflecting some of the technical comments made during the oral presentation.

2) GENERAL DESCRIPTION OF PLANT

- DESIGN CHARACTERISTICS
- CONTAINMENT PLAN
- CONTAINMENT ELEVATION
- STEAM GENERATOR VERTICAL SECTION AND
KEY ELEVATIONS

MYAPC

TABLE 1.3.1

MAINE YANKEE DESIGN CHARACTERISTICS

Plant

| | |
|---|-----|
| Net Electrical Power Output (MWe) @ 2,630 MWt | 825 |
| Gross Electrical Power Output (MWe) @ 2,630 MWt | 864 |
| Maximum Expected Gross Electrical Output (MWe) | 864 |

Nuclear Steam Supply System

| | |
|--|-------------------------|
| Core Thermal Output (MWt) | 2630 |
| Operating Pressure (psig) | 2235 |
| Design Pressure (psig) | 2485 |
| Reactor Coolant Inlet Temperature (F) | 532-550 |
| Reactor Coolant Outlet Temperature (F) | 532-600 |
| Pipe Size: Outlet (ID, inches) | 33-1/2 |
| (Wall Thickness, inches) | 3-1/4 |
| Inlet (ID, inches) | 33-1/2 |
| (Wall Thickness, inches) | 3-1/4 |
| Flow per Loop (lb/hr) | 44.87 x 10 ⁶ |
| Number of Loops | 3 |
| Number of Pumps | 3 |

| | |
|------------------------|---|
| Type | Vertical, Centrifugal Mechanical Seals |
| Design Flow/Pump (gpm) | 120,000 |

Core

| | |
|---|----------------------------------|
| Total Heat Output (Btu/hr) | 8.981 x 10 ⁹ |
| Heat Generated in Fuel (%) | 97.5 |
| DNB Ratio at Nominal Conditions | 1.903 |
| Minimum DNBR for Design Transients (W-3 Correlation) | 1.30 |
| Core Power Density (kW/liter) | 80.86 |
| Number of Fuel Assemblies | 217 |
| Number of Fuel/Poison Rods per Assembly | 176 |
| Fuel Rod Pitch (inches) | 0.580 |
| Fuel Clad Material | Zircaloy-4 |
| Fuel Clad Minimum Thickness (inches) | 0.024 |
| Number of Control Rods | 77 |
| CEA Pitch (inches) | 11.57 |
| Poison Materials | B ₄ C/stainless steel |
| Control Rod Drive Type | Magnetic Jack |
| Equivalent Core Diameter (inches) | 136 |
| Total Uranium (Mtu) | 80-83 |

MYAPC

TABLE 1.3.1
(continued)

MAINE YANKEE DESIGN CHARACTERISTICS

| | |
|--|--------------------|
| Feedwater Heater Stages | 6 |
| Condensate Pumps - Number | 3 Half-Capacity |
| Design Flow (gpm) | 9060 |
| Design Head (ft) | 960 |
| Feedwater Pumps - Electrical - Number | 2 Half-Capacity |
| Design Flow (gpm) | 14,000 |
| Design Head (ft) | 2038 |
| Feedwater Pump - Steam Driven - Number | 1 Full-Capacity |
| Design Flow (gpm) | 28,000 |
| Design Head (ft) | 2200 |
| Circulating Water Pumps - Number | 4 Quarter-Capacity |
| Design Flow (gpm) | 106,500 |
| Design Head (ft) | 26 |

Generator

| | |
|-----------------------|-----|
| Design Rating (Mva) | 900 |
| Power Factor | .90 |
| Terminal Voltage (kV) | 22 |

NSSS Auxiliary Systems

(a) Chemical and Volume Control System

| | |
|--------------------------------------|--------------------|
| Normal Letdown Flow Rate (gpm) | 80 |
| Maximum Letdown Flow Rate (gpm) | 200 |
| Charging Pumps - Number | 3 Fixed-Capacity |
| Design Flow (gpm) | 150 |
| Design Pressure (psig) | 2350 |
| Auxiliary Charging Pump - Number | 1 Variable Speed |
| Design Flow (gpm) | 10 to 30 |
| Design Pressure (psig) | 3700 |
| Regenerative Heat Exchanger - Number | 1 Full-Capacity |
| Design Heat Transfer (Btu/hr) | 10.0×10^6 |
| Letdown Heat Exchanger - Number | 1 Full-Capacity |
| Design Heat Transfer (Btu/hr) | 7.82×10^6 |
| Demineralizers - Number | 3 Purification |
| | 1 Deborating |
| Nominal Rating (gpm) | 80 |
| Maximum Flow (gpm) | 200 |
| Resin Volume (ft ³) | 32 |
| Filter - Number | 2 |
| Type | Cartridge |
| Design Rating (gpm) | 200 |
| Filter Size (microns) | 2 |

MYAPC

TABLE 1.3.1
(continued)

MAINE YANKEE DESIGN CHARACTERISTICS

(g) Spent Fuel Cooling System

| | |
|-----------------------------|------------------------|
| Spent Fuel Pool Capacity | 953 assys. |
| Volume (ft ³) | 59,116 |
| Pumps - Number | 2 |
| Rating, Each (gpm) | 772 |
| Head (ft) | 120 |
| Heat Exchanger - Number | 1 |
| Rating (Btu/hr) | 22.3 x 10 ⁶ |
| Filter - Number | 1 |
| Type | Cartridge |
| Rating (gpm) | 200 |
| Size (microns) | 2 |
| Demineralizer - Number | 1 |
| Resin Type | mixed bed |
| Bed Size (ft ³) | 32 |
| Nominal Flow (gpm) | 200 |

Conventional Plant Auxiliary Systems

(a) Service Water System

| | |
|------------------------------|-----------------|
| Service Water Pumps - Number | 4 Full-Capacity |
| Rating (gpm) | 10,000 |
| Head (ft) | 66 |


(b) Compressed Air System




| | |
|---------------------------|-----|
| Compressors - Number | 3 |
| Rating (scfm) | 300 |
| Discharge Pressure (psig) | 100 |

Containment

| | |
|-------------------------------------|---------------------|
| Type | Reinforced Concrete |
| Diameter (ft-inches) | 135-0 |
| Height (ft-inches) | 169-6 |
| Liner - Material Thickness (inches) | ASTM A516 Grade 60 |
| Wall | 3/8 |
| Dome | 1/2 |
| Floor | 1/4 |
| Design Pressure (psig) | 55 |
| Design Temperature (F) | 280 |
| Leak Rate (percent per day) | 0.1 |

11550-FM-1A





- NOTES:
- SCALE - 1/4" = 1'-0"
 - 6 x 6 MIN THICKNESS FOR MISSILE SHIELDING
 - (S) DENOTES REMOVABLE SLABS
 - ALL GRATING AT EL 46'-0" TO BE REMOVABLE
 - PROVIDE REMOVABLE GUARD RAILS AROUND CAVITY & HOISTING SPACE.
 - AN INSPECTION SPACE 6" WIDE MUST BE LEFT BETWEEN REACTOR AND INSULATED INNER WALL OF THE SHIELD TANK.
 - 6 MIN THICKNESS ALUMINUM FOR RADIATION PURPOSES
 - CEA DENOTES CONTROL ELEMENT ASSEMBLY
 - (G) DENOTES REMOVABLE GRATING
 - REFRESHED DRAWINGS:
 - MACH LOC - REACTOR PLANT IN 2 — FM-15
PLAN - EL 20'-0"
 - MACH LOC - REACTOR PLANT EL 5 — FM-12
PLAN - EL 0'-0" EL - 73' 6 1/2"
 - MACH LOC - REACTOR PLANT IN 4 — FM-10
SECTIONS A-A & C-C
 - MACH LOC - REACTOR PLANT IN 5 — FM-18
SECTIONS B-B, D-D & E-E
 - ROOF PLAN — FM-16





FIG. 5.H
REACTOR CONTAINMENT
PLAN, EL. 46'-0"
MAINE YANKEE ATOMIC PWR. CO.


THE INFORMATION ON THIS DRAWING MAY NOT BE COPIED OR USED FOR OTHER THAN THE CONSTRUCTION, MAINTENANCE OR REPAIR OF THE PLANT FACILITY IDENTIFIED IN THE TITLE BLOCK.

11550-FM-1D

0 1 2

4.0 DIA VENT






NOTES:
 SCALE: 1/4" = 1'-0"
 GENERAL NOTES OF REFERENCE DWGS PM-1A

FIG. 5.1-4
 CONTAINMENT ELEVATION
 MAINE YANKEE ATOMIC PWR. CO.

THE INFORMATION ON THIS DRAWING MAY NOT BE
 COPIED OR USED FOR OTHER THAN THE CONTRACTING
 OBLIGATION OR SERVICE OF THE PLANT FACILITY
 INDICATED IN THE TITLE BLOCK.

ILLUSTRATION OF STEAM GENERATOR SHOWING ACTUAL VS. INDICATED WATER LEVELS AT T = 532°F (HWP) FOR WIDE RANGE




1. High Water Level Trip - 91%
2. High Water Level Alarm - 77%
3. Normal Water Level - 66%
4. Low Water Level Alarm - 60%
5. Low Water Level Pre-Trip - 45%
6. Low Water Level Trip - 35%
7. Top of Tube Bundles - 33%

3) DESCRIPTION OF FEEDWATER SYSTEM FLOW PATHS

AND

FEEDWATER PIPING, SAFE END, AND STEAM

GENERATOR NOZZLE CONFIGURATION



3.2

S/G

#2

#3

P-25A

P-25C

P-25B

NEQ

DWST

Emergency Aux.
Feed Pumps

Turbine Drive
Aux. Feed Pump

NNS

P-2C

P-2B

P-2A

Main Feed Pumps

ByPass Vv.

Main FW
Control Vv.


#2

#3


#1 Feedwater Heaters

TURBINE
PLANT

SUPPORTS



SHOCK SUPPRESSOR



SPRING HANGER



SLIDING SUPPORT



ANCHOR

HSS

HORIZONTAL SHOCK SUPPRESSOR

LSS

LATERAL " "

ASS

AXIAL " "


SS


SLIDING SUPPORT


SH


SPRING HANGER

3.4










3.7

- A - ELBOW COUNTERBORE STRESS RISER
- B - SAFE END COUNTERBORE STRESS RISER
- C - SAFE END COUNTERBORE
- D - NOZZLE DIAMETER STEPS
- E - NOZZLE THERMAL SHIELD
- F - 90° DOWNTURNING ELBOW COUNTERBORE STRESS RISER
- G - NOZZLE TO SAFE END SHOP WELD



4) DESCRIPTION OF EVENT AND PHOTOGRAPHS

Maine Yankee Feedwater Line Leakage Event

At 1432 hours January 25, 1983, the Maine Yankee nuclear plant tripped from full load while isolating an electrical ground. Main feedwater flow was not available following the trip so steam generator level restoration was accomplished, as designed, by the auto start operation of the auxiliary feed pumps.

Approximately 15 minutes after the trip: a loud noise was heard in the plant machine shop which is located just below the main feed lines; a containment fire detector alarmed; and containment humidity began to rise. The containment was entered for inspection. The feed line was found to be leaking severely near the #2 steam generator inlet nozzle. Station cooldown was initiated to permit close access for inspection and to effect repairs.

Visual inspections conducted on January 26 revealed a feed line side crack had occurred adjacent to the pipe to steam generator nozzle weld on the upstream (feedwater) side of the weld, and that several feedwater line hangers exhibited deformation or other distress.

A program of inspection, analysis, repair and corrective modifications was initiated. The current status of each major aspect of the program follows:

Event Analysis

The leak occurred as a result of a water hammer event causing the ultimate failure of what was most probably an existing crack in the feed pipe. The crack was probably initiated by thermal cycling and non-uniform thermal effects working on a stress riser within the pipe. The water hammer event probably occurred when the outlet nozzle at bottom of the feed ring became submerged in the rising SG water level and the steam in contact with cold feedwater within the ring suddenly collapsed. The event and damage was typical of that experienced at other PWR's and as extensively described in NUREG's and other industry literature.

Plant records do not indicate the occurrence of any prior steam-water hammer events. This may be because all prior full load trips were followed by normal main feed flow providing warmer water for steam generator level restoration. Three prior trips during which loss of main feed occurred were at power levels of less than 50% so steam generator level shrinkage was far less. In two instances the auxiliary feed system was manually started and the flow rate was controlled by the operators. In one instance, the auxiliary feed system started automatically.

Feedwater Nozzles and Adjacent Pipe

All three steam generator configurations are the same. The nozzle is connected to a safe end, connected to a 20° el, connected to a 2' length of straight pipe, connected to a 90° down turning el. The connections were originally designed to minimize the horizontal run subject to possible steam-water hammer.

All pipe welds from the nozzle to and including both welds on the 90° el were radiographed (RT) on all steam generators (SGs). #2 SG's 20° el has been removed and examined. The external crack is located at the bottom of the el, right at the base of an internal stress riser. #3 SG radiograph indicated a similar crack existing at the same location propagating from the inside supporting the thermal cycle initiated crack postulation. #1 SG radiograph was inconclusive. Both #1 and #3 els were removed and the existence of similar cracks confirmed. All cracks are similar in location and magnitude extending from the 11 A.M. position to the 7 or 8 P.M. position looking into the SG.

The cracks occurred where one would expect: adjacent to the weld connecting the flexible pipe to the more rigid SG; at the bottom of the horizontal pipe section which is subject to the greatest amount of thermal cycling and distortion; at the base of an internal stress riser left in the pipes during installation, and close to the shock loads that occur with steam-water hammer.

Magnetic particle examination of the straight section of pipe internals where it attaches to the 20° el indicated a possible crack at the counterbore stress riser that was not evidenced by prior RT examination. All three pipe sections were removed to provide access to the 90° el horizontal end, which also contained a similar stress riser, and to the nozzles. The safe ends were examined by LP as part of the preparation for repair. In this examination two types of indications were observed. Circumferential indications were found at the counterbore stress riser. These were chased by grinding until they were clear as indicated by additional LP checks. Also, minor surface indications were found in the ID of the safe end counterbore. However, these indications were cleared by buffing the surface. Thus, the safe ends were determined to be satisfactory.

The steam generator nozzles expand into the steam generators in two steps. Visual and LP examination of the first step up in inner diameter revealed indications of cracking. These cracks were chased by grinding in accordance with CE material removal specifications, which allowed up to 1/8" of metal to be removed without necessitating repair by rewelding. The cracks were cleared before this metal removal limit was reached. The second step up in inner diameter is covered and protected by a thermal sleeve which precludes internal surface inspection.

All other feedwater piping welds back to the feedwater check valves were inspected by RT and found to be clear. In addition, the auxiliary feedwater connections to the feedwater piping (just downstream of the feedwater check valves) were inspected by mag particle and found to be clear.

On all three SG's, the 90° el horizontal end stress riser has been removed, the horizontal pipe and 20° el has been replaced with sections whose stress risers have been removed. The repair welds and transition will be radiographed, ultrasonically tested to establish a baseline, and the entire pipe hydro tested.

Steam Generator Internals

SG feed rings and attachments were inspected. Only minor deformation of a support was noted. The number two and three steam generator thermal sleeve appears to be somewhat expanded into the nozzle. The feed ring support will be repaired.

Each of the SG feed rings will be modified by closing off the 76 bottom 1" dia. nozzles and installing 28 top mounted J tubes (so-called) of 3" dia. This is a fix previously used at other PWR's that provides greater assurance that the feed ring will not empty and (300%) greater pressure equalization capability.

The expansion of the thermal sleeve into the nozzle will reduce the rate of ring draining in a loss of feed event which is helpful. However, it may reduce the number of lifetime thermal cycles permitted on the nozzle. An analysis will be completed prior to the next refueling outage and modifications made if warranted.

Feedwater Lines, Hangers & Support

Based upon support deformation and other evidence, it appears that the amount of line movement was not excessive. Support attachments to pipe were inspected and no evidence of overstress or deformation was found.

#2 & #3 feedwater line check valves have been opened and inspected. No damage was found.

Modification to Prevent Reoccurrence

1. Stress risers have been removed from the horizontal portions of the pipe, els and safe end.
2. J tubes have been installed on feed rings to prevent draining, reducing water hammer probability.
3. Operations instruction and guidance have been provided to reduce the probability of thermal cycling and feedwater hammer events.

PHOTOGRAPHS


1. #2 Feedwater pipe elbow showing counterbore and crack.
2. #2 elbow showing through wall crack at outside.
3. #2 elbow showing crack.
4. #2 elbow showing crack and ruler
5. #2 SG nozzle, safe end, 20° elbow, short horizontal pipe section, and 90° elbow to vertical. Also shown: pipe cotter in place and chem addition line.
6. #3 Feedwater line horizontal support.



#2 Feedwater pipe elbow showing counterbore and crack




#2 elbow showing through wall crack at outside




#2 elbow showing crack


ins clo:



#2 elbow showing crack and ruler



#2 56 nozzle, safe end, 20° elbow, short horizontal pipe section, and 90° elbow to vertical. Also shown: pipe cotter in place and chem addition line



#3 Feedwater line horizontal support

5) MAINE YANKEE FEEDWATER PIPE

DAMAGE MECHANISM


1. CAUSES OF CRACKING
 - A. CRACK INITIATION
 - B. CRACK PROPAGATION
2. STEAM CONDENSATION/WATERHAMMER INCIDENT
 - A. HOW IT HAPPENED
 - B. EXPLANATION OF DAMAGE

COMMENTARY:


1. Cracks are initiated by thermal cycling. Crack progression in excess of 0.1" is unlikely except where accompanied by non-uniform thermal condition. Non-uniform thermal conditions frequently occur in the steam generator nozzle and attached horizontal pipe sections during periods of low flow of cold feedwater.
2. The water hammer incident is similar to that experienced at other PWR's and probably caused the thermal sleeves in S.G. #2 and #3 to expand.
3. The expanded thermal sleeves are probably still 75% effective and adequate until the next refueling outage. A more detailed evaluation will be conducted prior to that outage.

CAUSES OF CRACKING

- A. CONFIGURATION OF PIPE TO NOZZLE JUNCTURE.
- B. INJECTING SMALL FLOW RATES OF COLD WATER THROUGH PIPE AND SUBSEQUENT 'STRATIFICATION' OF FLOW.
- C. TRADITIONAL THERMAL STRESS AND PIPE LOAD STRESS.




MAINE YANKEE 5.G. PIPE WELD GEOMETRY



STRATIFICATION IN FEEDWATER PIPE

MAINE YANKEE FEEDWATER PIPE
POTENTIAL STRESS DISTRIBUTION



AREAS OF TENSILE STRESS HAVE THE CAPACITY TO
PROPAGATE INITIATED CRACKS

TRADITIONAL THERMAL AND PIPE LOAD STRESSES

1. THERMAL STRESSES

- A. RADIAL GRADIENT "SKIN" STRESS-SLUG FEEDING
- B. FLUCTUATING HOT/COLD FLUIDS DUE TO UNSTABLE MIXING, STREAMING AND LEVEL FLUCTUATION


2. PIPE LOAD STRESSES

- A. THERMAL EXPANSION - HEATUP
- B. CHANGE IN THERMAL EXPANSION DUE TO:
 - (1) POWER CHANGES
 - (2) COLD FEEDING
 - (3) SUPPORT BINDING

STEAM CONDENSATION/WATERHAMMER INCIDENT
SEQUENCE OF EVENTS


1. REACTOR TRIP
2. TURBINE TRIP/COASTDOWN OF STEAM DRIVEN PUMPS
3. LOSS OF FEEDWATER TO S.G./LOW WATER LEVEL
4. INITIATION OF AUXILIARY FEEDWATER/REFILL
5. WATER LEVEL REACHES BOTTOM DISCHARGE NIPPLES
6. RAPID STEAM CONDENSATION INSIDE SPARGER
7. RAPID CONDENSATION IN PIPE
8. OPPOSITE WATER COLUMNS ACCELERATE AND COLLIDE
9. WATERHAMMER CAUSES PRESSURE SPIKE AND PRESSURE WAVE PROPAGATES THROUGH SYSTEM
10. DAMAGE OCCURS:
 - A. THERMAL LINER YIELDS AND EXPANDS
 - B. PIPE CRACK PROPAGATES THROUGH WALL (S.G.2)
 - C. PIPE HANGERS DAMAGED (S.G.3)

SCHEMATIC - MAINE YANKEE STEAM GENERATOR
REFILL - COLD AUXILIARY FEEDWATER FLOW




5.8


2074
SCHEMATIC - MAINE YANKEE STEAM GENERATOR
WATER LEVEL REACHES NIPPLES - AUX. FLOW



SCHEMATIC - MAINE YANKEE STEAM GENERATOR
RAPID CONDENSATION INSIDE SPARGER



SCHEMATIC - MAINE YANKEE STEAM GENERATOR
WATER HAMMER - PRESSURE SPIKE INSIDE SPARGER



6) INSPECTION AND REPAIR

- FEEDWATER PIPING
- SUPPORTS AND HANGERS
- NOZZLES
- STEAM GENERATOR INTERNALS

INSPECTION PLAN

I. Visual Inspection of Pipe Supports

- a. Inspect feedwater supports between the steam generators and the main feed valves.
- b. Inspect all auxiliary feedwater supports from the feedwater line tee, back to and including the containment penetrations.
- c. Inspect pipe in vicinity of supports for damage or distress.

II. Functional Test of Shock Suppressors

- a. Test the two suppressors that failed the visual inspection.
- b. Test an additional sample if one of the first two suppressors fails to operate properly.

III. Surface Examinations (MP, LP)

- a. Examine the pressure boundary welds at each anchor point in the feedwater system.
- b. Examine the pressure boundary welds attaching the distressed shock suppressors.
- c. Examine the inside diameter of the steam generator nozzle-to-safe end welds. (Includes safe end I.D. surfaces.)
- d. Weld prep surfaces.

IV. Visual Inspection of Check Valve Internals

- a. Feedwater valves FW-113, 213, and 313.

V. Radiographs of Feedwater Lines in Containment


- a. All butt welds, between the steam generators and the check valves.
- b. Welds that had previous indications.

VI. Class "B" Leak Test of Feedwater Penetrations

VII. Four Hour Hydro of the Steam and Feed System

- a. Steam generator and steam lines up to the excess flow check valves.
- b. Blowdown lines to the first isolation valves.
- c. Feedwater lines to the flow control valves.
- d. Auxiliary feedwater line to the first check valve.


VIII. Inspection for Wetted Insulation on S.S. Piping




Small dent where the pipe lug hit the outer support. The dent was on the steam generator side.


6.3

5.2





LOOP 3



6.5

5.4






fig. 201




| ITEM | NAME OF PART | QTY | MATERIAL | FINISH | REVISION | DATE |
|------|------------------|-----|--------------------|-------------|-----------|------|
| 1 | DISC | 1 | POWER ALLOY STEEL | A 314 A 1/2 | SPACE 7/8 | 277 |
| 2 | SEAT | 1 | CARBON STEEL | A 314 A 1/2 | SPACE 7/8 | 107 |
| 3 | WELDED HINGE PIN | 2 | STEEL | A 314 A 1/2 | SPACE 7/8 | 107 |
| 4 | FLY | 1 | CAST IRON | A 314 A 1/2 | SPACE 7/8 | 107 |
| 5 | COVER | 1 | COMMON FIELD PLATE | A 314 A 1/2 | SPACE 7/8 | 107 |
| 6 | WELDED HINGE PIN | 2 | STEEL | A 314 A 1/2 | SPACE 7/8 | 107 |
| 7 | WELDED HINGE PIN | 2 | STEEL | A 314 A 1/2 | SPACE 7/8 | 107 |
| 8 | WELDED HINGE PIN | 2 | STEEL | A 314 A 1/2 | SPACE 7/8 | 107 |
| 9 | WELDED HINGE PIN | 2 | STEEL | A 314 A 1/2 | SPACE 7/8 | 107 |
| 10 | WELDED HINGE PIN | 2 | STEEL | A 314 A 1/2 | SPACE 7/8 | 107 |
| 11 | WELDED HINGE PIN | 2 | STEEL | A 314 A 1/2 | SPACE 7/8 | 107 |
| 12 | WELDED HINGE PIN | 2 | STEEL | A 314 A 1/2 | SPACE 7/8 | 107 |
| 13 | WELDED HINGE PIN | 2 | STEEL | A 314 A 1/2 | SPACE 7/8 | 107 |
| 14 | WELDED HINGE PIN | 2 | STEEL | A 314 A 1/2 | SPACE 7/8 | 107 |

LEFT HAND HINGE SPRING COILS
SHOWN IN ASSEMBLY OF THIS MODEL



| REV. | DESCRIPTION | DATE |
|------|-----------------------------|---------|
| A | ADD W/L PER. S.W. LTR 10-29 | 1-27-70 |



| GENERAL DIMENSIONS | | | | | |
|--------------------|----|----|----|---|---------------|
| SIZE | A | E | BC | W | DEPTH IN LBS. |
| 0 | 19 | 9 | 10 | | 450 |
| 1 | 20 | 10 | 11 | | 500 |
| 2 | 22 | 12 | 13 | | 650 |
| 3 | 24 | 14 | 15 | | 850 |
| 4 | 26 | 16 | 17 | | 1100 |
| 5 | 28 | 18 | 19 | | 1400 |
| 6 | 30 | 20 | 21 | | 1800 |
| 7 | 32 | 22 | 23 | | 2300 |
| 8 | 34 | 24 | 25 | | 2900 |

SERVICE PARTS
 600 S CAST CARBON STEEL WEL
 HARD P.S.L. @ 300°F
 800 P.S.L. @ 550°F

ROCKWELL MANUFACTURING COMPANY
 RALEIGH PLANT - RALEIGH, NORTH CAROLINA

CAST STEEL HORIZONTAL AND VERTICAL
 TILT-UP AND CHECK VALVE OPERATING ASSEMBLY
 FIG 570BY

VISUAL EXAM OF VALVE BODY, BOLTING, WELDS, DISC,
 SEAT, ETC.
 BLUED DISC & SEAT
 M = CHECK ON HINGE PIN & PIN BORE

| E | D | C | B | A |
|---|---|---|---|---|
| | | | | |
| | | | | |
| | | | | |
| | | | | |

TAG: VCW-60A

J.O. N° 11550. P.O. N° MY-07


P-419253 REV. A

CUT 1053

FEBRUARY 1983


RADIOGRAPH

ID. NO.



#6 MP ONLY


SG-2



#6 MP ONLY


57

SG-3




#6 MP ONLY.

570




DETAIL E
NO SCALE


| ITEM NO. FV-IJ | A | B | C | D | E | F | G | H | J | K | L | T | W | α | φ |
|----------------|----------|-------|-----|-----------|-------|--------|--------|-----------|------|--------|----|----|--------|--------|---------|
| 66 | 10-4 1/2 | 3'-6" | 30" | 2'-5 1/2" | 7'-0" | 7" | 8 1/2" | 3'-5 1/2" | 3/4" | 1 1/2" | 3" | 2" | 1 1/4" | 12° 1' | 12" 50' |
| 53 | 8'-0 1/2 | 2'-6" | 14" | 13 1/2" | 5'-0" | 5 1/2" | 7 1/2" | 2'-2 1/2" | 1/2" | 3/4" | 2" | 1" | 1" | 12° 1' | 12" 50' |
| 55 | 9'-2 1/2 | 2'-6" | 14" | 2'-3 1/2" | 5'-0" | 5 1/2" | 7 1/2" | 2'-3 1/2" | 1/2" | 3/4" | 2" | 1" | 1" | 12° 1' | 12" 50' |
| 64 | 5'-2 1/2 | 3'-6" | 30" | 16 1/2" | 7'-0" | 7" | 8 1/2" | 3'-2 1/2" | 3/4" | 1 1/2" | 3" | 2" | 1 1/4" | 7° 11' | 7" 40' |
| 65 | 8'-7 1/2 | 3'-6" | 30" | 10 3/4" | 7'-0" | 7" | 8 1/2" | 3'-3 1/2" | 3/4" | 1 1/2" | 3" | 2" | 1 1/4" | 2° 23' | 2" 33' |
| 54 | 7'-4 1/2 | 2'-6" | 14" | 9 3/4" | 5'-0" | 5 1/2" | 7 1/2" | 2'-0 1/2" | 1/2" | 3/4" | 2" | 1" | 1" | 2° 23' | 2" 33' |



DETAIL K
NO SCALE



DETAIL L
NO SCALE




DETAIL M
NO SCALE

NOTES:
MATERIAL:

- CARBON STEEL PLATE-ASTM-A516-GR60 NORMALIZED (MIN NDT -20°F)
- CARBON STEEL FORGINGS ASTM-A350-GR1 & 2
- CARBON STEEL PIPES # ASTM-A333-GR1
- CARBON STEEL SLEEVES # ASTM-A333-GR1
- STAINLESS STEEL FORGINGS ASTM-A182 - F304
- STAINLESS STEEL PIPES # ASTM-A312 TYPE 304/316/316L
- TEST ANGLES & CHANNELS ASTM-A131 GR 2
- ALL SLEEVES & FORGED CAPS TO BE CARBON STEEL
- WELDING ELECTRODES:
 - CARBON STEEL TO CARBON STEEL ASTM-E7018
 - STAINLESS STEEL TO STAINLESS STEEL ASTM-E308
 - CARBON STEEL TO STAINLESS STEEL ASTM-E309
- WHERE PENETRATION SLEEVES HAVE A LONGITUDINAL WELDED SEAM, THAT PORTION OF THE SEAM EXTENDING INTO THE CONTAINMENT SHALL BE COVERED WITH A TEST CHANNEL SIMILAR TO THAT SHOWN IN DET K. WELDED SEAMS SHALL BE LOCATED ON BOTTOM VERTICAL C OF THE PENETRATION.
- SEAMLESS PIPES SHALL BE SUPPLIED FOR ALL PENETRATIONS EXCEPT ITEM NO. 52, 64, 65, 66, 67 FOR WHICH BUTTWELDED FULLY RADIOGRAPHED PIPE MAY BE SUPPLIED.

REFERENCE DWGS:
PENETRATION ITEM NUMBERS:
WELD END DETAILS

FOR FINAL ARRANGEMENT
& DETAILS SEE MFR
DRAWINGS (SEE FV-1F)




REACTOR CONTAINMENT-SH7
PIPING PENETRATIONS

ATOMIC POWER STATION
MAINE YANKEE ATOMIC POWER COMPANY
WISCASSET, MAINE

ATOMIC & WALKER ENGINEERING CORPORATION
BOSTON, MASS.

DRAWING NUMBER 11550-FV-1G



DETAIL G
PURGE AIR-ITEM 67 FV-IJ
NO SCALE

THE INFORMATION ON THIS DRAWING MAY NOT BE COPIED OR USED FOR OTHER THAN THE CONSTRUCTION, MAINTENANCE OR REPAIR OF THE PLANT FACILITY DESCRIBED IN THE TITLE BLOCK.


| DESCRIPTION | CHG | CHK | APP | DATE | PLT | ISSUE | DESCRIPTION |
|---|-----|-----|-----|------|-----|-------|----------------|
| TABLES FOR DET C, D, E, F, & G TO DET A 1G TO DET B | | | | | | 1 | ORIGINAL ISSUE |

PIPE INSPECTION AND REPAIRS


- * PIPING SYSTEM CONFIGURATION
- * INSPECTIONS
 - SELECTION CRITERIA FOR WELD JOINTS
- * FINDINGS OF INSPECTIONS
 - 79-13
 - POST EVENT
- * REPAIRS

STEAM GENERATOR FEED WATER NOZZLES AFTER REMOVAL OF PT INDICATIONS

2/4/83
100 HRS




1. NO APPRECIABLE METAL REMOVAL FROM 9:00-3:00
2. POROSITY PER ATTACHED SHEET
3. APPEARS DEEPEST BETWEEN 6:30 & 7:30. GROOVE BLENDED & FLAPPER WHEELED. DEEPEST PART $\approx 1/4"$ RAD.




J.H. 2-5-83

2/4/83
1300 HRS



NO MATERIAL REMOVED



2/4/83
1200 HRS

MAXIMUM

NOZZLE INSPECTION & REPAIRS


- * PRE-EVENT CONFIGURATION -
 - NOZZLE DETAILS
 - WELD 1A JOINT CONFIGURATION
 - WELDING PROCESS - ORIGINAL
 - MATERIALS -

- * INSPECTIONS -
 - CONSTRUCTION RT
 - 79-13 INSPECTION
 - POST EVENT INSPECTIONS
 - RT RESULTS
 - SURFACE EXAMS

- * INSPECTION FINDINGS
 - SKETCHES OF CRACK EXTENT
 - AREA OF THRU CRACK

- * REPAIRS
 - COUNTERBORE CONFIGURATION
 - WELDING

0° IS TOP DEAD CENTER
LOOKING INTO STEAM GENERATOR.




PIPE


INDICATION

HEAVIEST
INDICATION

#1 EL



2 EL



3 EL

5-15

DETAILS OF STEAM
GENERATOR INSPECTIONS

AT

MAINE YANKEE

1/28/83, 1/29/83, 1/30/83 & 1/31/83

LIST OF FIGURES

| <u>Figure No.</u> | <u>Description</u> |
|-------------------|---|
| 1 | STEAM GENERATOR # 1 FEED RING CONDITION |
| 2 | STEAM GENERATOR # 2 FEED RING CONDITION |
| 3 | STEAM GENERATOR # 3 FEED RING CONDITION |
| 4 | STEAM GENERATOR # 1 THERMAL SLEEVE |
| 5 | STEAM GENERATOR # 2 THERMAL SLEEVE |
| 6 | STEAM GENERATOR # 3 THERMAL SLEEVE |
| 7 | STEAM GENERATOR # 1 THERMAL SLEEVE I.D. |
| 8 | STEAM GENERATOR # 2 THERMAL SLEEVE I.D. |
| 9 | STEAM GENERATOR # 3 THERMAL SLEEVE I.D. |


FIGURE 1

SG # 1
DATE 1/30/83

BY *William M. ...*
CE


STRAIGHT
BACKING BAR

SLEEVE LOOKS NORMAL
THIS PAD NOT IN
CONTACT WITH NOZZLE
(GAP GREATER THAN .015")



LOWER 2 PADS IN
CONTACT WITH
NOZZLE


VIEW FROM
NUT SIDE



2 TACK WELDS PER
BOLT HEAD & 2 PER NUT

BOLT HEAD
THIS SIDE

ALL BOLT HEADS
& NUTS IN CONTACT
WITH PLATES



0 1 2 3 4 5 6
APPROX SCALE
INCHES

NO INDICATION
OF REBOUND

NOTE:
ALL U BOLT NUT
TACK WELDS
STILL INTACT

NOTE: SEVERAL TACKS BROKE (ONE AT LEAST -
LOOKS LIKE ITS BEEN GONE AWHILE;
THE WHOLE WELD IS GONE)

FIGURE 2

SG # 2
DATE 1/28/83

BY W. M. S. CE

BEND (PREVIOUSLY NOTED IN MAY 1981 PHOTO)

THIS PORTION OF OD VISIBLE FROM INSIDE (S/G CALL AROUND) (ESTIMATED BULGE: 5/16")



NO BACKUP BAR NOTED

THIS WHOLE ID VISIBLE FROM INSIDE FEED-WATER NOZZLE

WELD PAD

THIS PLATE NOT VISIBLY BULGED

VIEW FROM NUT SIDE




2 TACK WELDS PER BOLT HEAD & 2 PER NUT

BOLT HEAD THIS SIDE



THESE 2 TACK WELDS CRACKED



LEFT SIDE OF BOLT HEADS LABELED A & B ABOVE ARE LIFTED AWAY FROM THE PLATE ABOUT .010" THE OTHER TWO, A LESSER AMOUNT, SAME SIDE

FIGURE 3

SG # 3
DATE 1/29/83

BY Abner M...
CE

SEVERAL DOTS
(W/IS) TOP HALF
OF BACK PLATE

THIS PLATE FEELS
DISHED IN SLIGHTLY
IN THE DIRECTION
ARROW


STRAIGHT
BACKING BAR

THIS PORTION OF OD USIBLE
FROM INSIDE $5/16$ (ALL
AROUND)
(ESTIMATED BULGE: $3/8$ IN.)



FEED RING
LOOKS ROUND

(SLIGHT DIMPLE ON
INSIDE OD OF RING
ABOUT $1/2$ WAY ALONG
ONE RING $1/2$ PROB.
FROM FABRICATION.)

WELD
PAD




THIS BOLT BROKEN AT
UNDERSIDE OF NUT. NUT
HELD BY PART OF 1 TACK
BOTH PIECES REMOVED



NOTE: MANY TACK WELDS BROKEN

NOTE:
ALL U BOLT NUT
TACK WELDS
STILL INTACT

FIGURE 4




S/G # 1
DATE 1/30/83 ~ 1730
W. MARTEL
CE

THermal SLEEVE
SECTION THROUGH
WELD PADS.

FIGURE 3

WELD PAD SPACER (TYP 3) I.D. OF S/G FEEDWATER NOZZLE



S/G# 2
 DATE 1/28/83 (~1450)
 BY W. MARTEL
 CF

THE THERMAL SLEEVE SECTION THROUGH WELD PADS

NOTE: In both cases, the sleeve is pressed out against the nozzle closer to the weld pad on side A than side B.

FIGURE 6

I.D. OF 5/8 FEEDWATER NOZZLE

WELD PAD SPACER (TYP 3)

LESS THAN .015 CLEARANCE ALL AROUND (REFERENCE APPROX 5/16" PER DRAWING)

THERMAL SLEEVE (.312 WALL)

APPROX MAX. BULGE (1/2 WAY BETWEEN 5/8 INNER WALL AND THE DISTRIBUTION BOX.)

IN ALL 6 PLACES SLEEVE IS PRESSED IN CLOSER TO WELD PAD IN 5/8 # 3 THAN IN 5/8 # 2.

S/G# 3


DATE 1/29/83

BY Walter R. Wood CE

THEMAL SLEEVE SECTION THROUGH WELD PADS

NOTE- THIS SECTION TAKEN THRU WELD PADS. ONE-HALF WAY FROM 5/8 WALL TO INSIDE END OF SLEEVE THE BULGE WAS GREATER THAN THE (PROJECTED) I.D. OF THE FEEDWATER NOZZLE, SEE ELEVATION VIEW & OUTER DASHED LINE ON THIS SKETCH.

SK # 1
 DATE 1/31/82
 BY W. Martel Jr.
 CE



6.25

ONE AREA
 HERE .0015"
 WENT IN
 ABOUT 1 1/2"

NOTE FOR GAPS ABOVE:
 USED .0015, .005 & .015"
 FEELER GAGES. DUE TO
 DIFFICULT CONDITIONS
 GAP MEASUREMENTS ARE
 APPROX.



| MEASUREMENT | APPROX LOCATION | | | | |
|----------------|-----------------|--------|--------|--------|--------|
| | A | B | C | D | E |
| X (HORIZONTAL) | 13.181 | 13.169 | 13.194 | 13.144 | 13.128 |
| Y (VERTICAL) | 13.120 | 13.133 | 13.138 | 13.151 | 13.191 |

(PHOTOS TAKEN: 35 MM)

INSIDE MIC. # 61-038

FIGURE 8

6/5 # 2
 DATE 1/30/63
 BY Walter R. Mott
 CE



GAP MORE THAN .015 ABOUT 2+ IN. DEEP

GAP ABOUT .025\" (ESTIMATED)

(PHOTOS TAKEN: 110 SIZE)

| MEASUREMENT | APPROX LOCATION | | | | |
|----------------|-----------------|--------|--------|--------|--------|
| | A | B | C | D | E |
| X (HORIZONTAL) | 13.143 | 13.769 | 13.596 | 13.638 | 13.030 |
| Y (VERTICAL) | 13.136 | 13.717 | 13.729 | 13.778 | 13.330 |

NOTE:
 THE MOUNDS CAUSED BY EACH WELD PAD ARE CLEARLY VISIBLE ON SLEEVE I.D.


ESTIMATED ACCURACY ±.005\"
 DUE TO SURFACE CONDITION

INSIDE MIC. # 61-038

FIGURE 9

NOTE: MOST OF THE OUTWARD BULGE MORE THAN THE (PROJECTED) I.D. OF THE NOZZLE (I.E. AT LOCATION D) IS AT THE TOP


SA # 3
 DATE 1/31/83
 BY Wm. R. W...
CE



NOTE: THE MOUNDS CAUSED BY WELD PADS ARE CLEARLY VISIBLE ON SLEEVE I.D.

(PHOTOS TAKEN: 35 MM)

| MEASUREMENT | APPROX LOCATION | | | | |
|----------------|-----------------|-------|-------|--------|--------|
| | A | B | C | D | E |
| X (HORIZONTAL) | 13.136 | 13761 | 13792 | 13,963 | 12.862 |
| Y (VERTICAL) | 13.120 | 13739 | * | ** | 13.492 |




GREATER THAN .015" (MORE THAN 9" DEEP - MAX LENGTH OF FEELER GAGE)

* This dimension taken from 11:00 to 5:00 vs. exactly vertical due to the weld pad bulge at the 12:00 position.
 ** This dimension approx. (and minimum) was beyond capacity of I.D. mic. Est. range 14.275 - 14.050


INSIDE MIC. # 61-038

7) MODIFICATIONS

- BLENDING TO REMOVE STRESS RISERS
- J VENTS
- OPERATIONAL GUIDANCE



ALL DIMENSIONS ARE APPROXIMATE



DETAIL "A"
NOT TO SCALE




DETAIL "B"
NOT TO SCALE

NOTE


ALL COUNTERBORES TO BE GROUND OUT SMOOTH WITH A MINIMUM TAPER OF 4 TO 1.

SKETCH #2

AS-LEFT CONDITION



ALL DIMENSIONS ARE APPROXIMATE



DETAIL "A"
NOT TO SCALE




DETAIL "B"
NOT TO SCALE

SKETCH # 1

AS-FOUND CONDITION

SCHMATIC - MAINE YANKEE STEAM GENERATOR
REFILL - COLD AUXILIARY FEEDWATER FLOW - WITH J-TUBES



FEEDWATER SYSTEM OPERATION GUIDANCE

DISCUSSION:

Steam generator feedwater rings and adjacent piping have experienced damage as a result of thermal cycling, non uniform thermally induced stresses, and water hammering. The most adverse conditions often exists during post trip recovery but some thermal cycling may occur during normal hot shutdown or standby conditions.

Post Trip Recovery

Following a trip from power, steam generator water level drops and feedwater flow is reduced to about 5% by main and by-pass feedwater regulator valve operation. Feedwater temperature drops as the main feedwater pumps refill the generator with the residual heated feedwater in the system. The temperature cycle is comparatively slow and uniform within the feedwater ring and adjacent pipe. Auxiliary feed, if automatically initiated during the event, will inject colder water into the feed flow making the thermal transient somewhat more severe. Appropriate immediate operator action would be to assure main feed is operating and securing the auxiliary feed. While SG level is being restored, auxiliary feed should be lined up through the #1 feedwater heaters and auxiliary steam to the heater placed in operation. After the SG level has been restored to above the feed ring (40%), heated auxiliary feed flow should be started and the main feed pumps shut down.

If main feed is not operating following a trip from power, the auxiliary feed flow should be maintained to keep the feed pipe and ring full. While the thermal cycle is greater, maintaining flow reduces the probability of more damaging non-uniform thermal stress and steam-water hammering. While SG level is being restored, auxiliary feed should be lined up through the #1 feedwater heaters and auxiliary steam to the heater placed in operation. After the SG level has been restored above the feed ring (40%), auxiliary feed flow may be directed thru the #1 heater.

If all feedwater flow is lost for more than several minutes, the ring and adjacent pipe may drain via the thermal sleeve clearance and fill with 520° steam. Subsequent initiation of cold feedwater could chill the bottom of the feed pipe causing non-uniform thermal stress. In addition, the steam void within the ring and pipe could collapse suddenly causing steam-water hammer shock.

Since the emergency auxiliary feed system is powered from the safeguards bus, loss of all feedwater flow could occur if a loss of both on-site and off-site power occurred which is an event of extremely low probability. However, appropriate operator action under such circumstances is to restore feed flow slowly ramping to 200 gpm per steam generator over several minutes using the turbine drive aux. feed pump or one of the motor driven pumps when power is restored. Again, routing auxiliary feed flow through #1 feedwater heter is a preferred path when time permits.

If a total loss of condensate pump flow occurs, some of the entrained feedwater in the system will flash to steam. Injecting coldwater into the system could cause the steam water. Do not reroute aux flow through the #1 heater until one hour after stable secondary plant conditions have been re-established. Auxiliary feed pressure should be applied to the system gradually to slowly collapse any steam voids that may be present.

Normal Power Operation

During normal power operation with less than two motor driven main feed pumps in operation, one MDFP should be maintained in the auto-start mode. This will ensure that the residual heated water in the feed train is used to the best advantage. To ensure that aux. feed supply is as warm as practical, maintain Demineralized Water Tank temperature between 80°F and 100°F.

During these periods feedwater requirements are low. If the aux. feed system is taking water from the DWST thermal cycling ranging between 90°F and 520°F may occur in the S.G. nozzle, feed ring and adjacent pipe when flow is intermittently stopped then restored. The magnitude of cycling can be reduced by maintaining some minimum flow when possible and by routing flow through the #1 FW heaters (with aux. steam supplied).

GUIDE OUTLINE

Post Trip

- A. Condition - Reactor Trip from Power
Main Feed Flow System Operating
Aux. Feed Flow System Starts Auto
- Action - 1. Trip off both Aux. Feed Pumps
2. Restore normal level via Bypass Regulating Valves
3. Transfer to Aux. Feed via #1 Heater when time permits
- B. Condition - Reactor Trip from Power
Main Feed Flow System not Operating
Aux. Feed Flow System Starts Auto
- Action - 1. Trim to one Aux. Feed Pump
2. Control Flow at 200 to 300 gpm per SG until level exceeds 40%
3. If Condensate System is operating, transfer aux. feed thru #1 Heater when time permits
- C. Condition - Reactor Trip from Power
Loss of On-Site and Off-Site Power
- Action - 1. Switch Aux. Feed to Manual; Ramp controllers closed
2. Start Turbine Driven Aux. Feed Pump (or Motor Driven Aux. Feed Pump if power is Restored)
3. Increase Aux. Feed Flow gradually over 5 minute period to between 200 and 300 gpm per steam generator
4. When SG Level exceeds 40%, adjust Aux. Feed Flow to maintain same constant flow to each SG

Normal Operation

- A. Condition - Plant power level in excess of 2%
- Action - 1. Maintain one MDFP in operating or auto start mode
2. Maintain DWST between 80°F and 100°F
3. Maintain aux. feed routing through #1 FW heater and aux. steam supply to #1 FW heater in a standby operable status
4. Maintain aux. feed in emergency auto start direct feed mode

Hot Standby Operations

- A. Condition - RCS above 400°F
Power level less than 2%
- Action - 1. Maintain some aux. feed flow to each SG if possible
2. Route aux. feed flow through #1 FW with steam controller set at about 10 psi.

8) RESPONSES TO NRC STAFF QUESTIONS

QUESTIONS FOR MAINE YANKEE
RE: FEEDLINE CRACK EVENT OF 1/25/83

1. Q. Have there been any other water hammer events since June 1979 in Main or Aux Feedwater system?
A. Not to our knowledge.
2. Q. Any evidence of failure of feedwater check valves to perform their function?
A. No.
3. Q. Was there anything unusual about plant operating conditions before the trip?
A. Yes. Both motor-driven main feedwater pumps were out of service, so normal feedwater flow was stopped at the time of the trip.
4. Q. Is there relevant data in the following parameters:
 - a) Steam Generator Water Level A: See attached level traces.
 - b) Steam Generator Pressure A: See tabulations.
 - c) Containment Temperature A: See tabulations.
 - d) Containment Pressure A: See tabulations.
 - e) Containment Humidity A: See tabulation (dew pt.)
 - f) Containment Sump Water Level A: See tabulations.
 - g) RCS Parameters A: Normal post-trip.
See tabulations.
5. Q. Describe operation of aux. feed system during event. What are temperatures, flowrates? How long was aux. feed operated, and what manual operations were taken after initiation?
A. Immediately after the trip SG levels dropped to below the aux. feed pump start initiation level of 35% and both P25-A and P25-C started (see attachment Q5). The initial flow rate was 400 gpm per SG which was soon cut back by operator action to 200 gpm/SG. The pumps draw water from the Demineralized Water Storage tank which was at 60°F.

Seven minutes after the trip P25-C was shut off, discharge rerouted thru the #1 feedwater heater, and restarted. About that time water level was up to the feed ring in #2 and a pipe noise was heard in the plant.

Indicated feedwater temperature decreased from 420°F to 100°F about 22 minutes after the trip.

P25-A was realigned to supply water through the first point heater 43 minutes after the trip. Feed to #2 SG was stopped 87 minutes after the trip.

6. Q. Describe the normal mode of operation of the main feedwater system with the new turbine driven main feedwater pump following a reactor trip/turbine trip at power. Compare system operation during the event with the normal mode (normal mode is electric pump on standby).
- A. Normal mode of operation is to have one motor-driven feed pump in the auto start mode. Following a trip, after assuring main feed pump is on and level is rising, auxiliary feed pumps are turned off.
7. Q. Describe the rupture of the main feedwater line (e.g. crack location, crack description, effective break flow area). Describe the damage to piping supports and hangers.
- A. The crack in the main feed line occurred in the counterbore transition of the first field weld of the main feed system upstream of the #2 SG nozzle. The joint is a standard 37° weld prep from the transition ring on the steam generator nozzle to a 20° elbow of A234WPB specification.

Visual, magnetic particle, and RT examination of the failed joint indicate a precracked condition existed in the transition area of the counterbore. The break occurred when the crack was continued through the wall of the pipe. The ID crack on steam generator #2 is approximately 35 inches in length. The location is shown on attached figure Q.7. The through-wall crack is 11 inches in length. The average width of the through-wall crack is approximately 1/16-inch with a 2-inch length in the center of the crack about 3/32 wide.

The counterbore was machine cut using a single point tool, parallel to the OD surface. It was then ground on a taper to the original ID of the pipe. The maximum depth of the counterbore in the through-wall direction is approximately 1/8 inch. It was noted that there was a definite tool mark at the transition area from straight to tapered section.

8. Q. Discuss your evaluation of the cause of the rupture.
- A. In the fabrication of the Maine Yankee Feedwater pipe to Steam Generator safe-end weld, a stress riser was left in the pipe when it was counterbored to accommodate the I.D. of the safe-end. Thermal and mechanical cycling over the years has caused cracks to originate at this stress riser. The presence of these cracks was difficult to detect with conventional NDE techniques because of the artifacts caused by the stress riser itself.

The water hammer event of January 25, 1982, caused the failure of the #2 feedwater line at the location of this cracking.

9. Q. Did you analyze impact of thermal stresses alone on piping and piping supports?
- A. Normal thermal analysis, as required by Power Piping Code (ANSI/ASME B31.1), has been performed on this system and these thermal loads are included in the design of the system's pipe supports.
10. Q. Describe modifications intended to prevent event from reoccurring (Procedural and hardware modifications). Explain how modifications cover remaining uncertainties in the understanding of the event.
- A. 28 top-mounted J tubes of 3" diameter have been installed on the Steam Generator feed rings in place of the 76 bottom-mounted 1" nozzles. The tubes will provide greater assurance that the feed ring will remain full, minimizing both the probability of steam-water hammer and the occurrence of the non-uniform thermal condition in the horizontal pipe when auxiliary feed water is introduced. The J tube location will provide assurance that a trapped steam condition will not exist. The J tubes will also increase the pressure equalization area about 300%, minimizing any pressure surge that may occur. Procedural modifications will provide operator guidance to minimize the occurrence of thermal cycling and feed ring draining.
11. Q. Explicitly describe results of reviews of all prior NDE inspections on safe-end to elbow and safe-end to pipe welds on all three steam generators. Include details on test techniques. Also for safe-end to nozzle welds. Describe results of current UT inspection on these welds.
- A. The review of NDE data on steam generator #2 weld 1A (safe-end to elbow) consisted of a review of the original construction radiograph, the radiograph taken as part of the USNRC Bulletin 79-13 program, and the radiography performed prior to removal of the elbow.

The original radiograph was shot using a S&W procedure which was equivalent to ASME Section I, Criteria, about 1968 Edition. The procedure required an IR-192 source, allowed AA type film, with a qualifying sensitivity of 4T.

The radiographs taken in 1979 and 1983 were to ASME Section III, NB (Section V RT with Section III Penetrameter requirements). The source was IR-192, the film EKC type T, with 2T sensitivity on the #15 penetrameter and 4T sensitivity on the #12 penetrameter.

The review of the construction radiograph shows a dull line at the transition area of the counterbore on steam generator #2. The line was not described on the original reader sheet. There were no other significant indications.

11. A. (Con't)

A review of the 79-13 radiographs indicated a darker, somewhat sharper area in the counterbore transition. There was no branching and the indication was very straight. Review of the 79-13 radiograph against the original construction suggested that the higher sensitivity associated with the type T film only enhanced the "tool mark" at the counterbore transition.

The 1983 radiographs show the indication of a crack which is approximately 35 inches in length on the ID of the pipe (length determined by mag. particle inspection on ID surface), originating in the counterbore transition. Except for areas of local tearing associated with the failure, all cracking was confined to this counterbore transition area.

The review of welds in steam generators #3 and #1 shows less density in the counterbore transition area in the 79-13 radiographs. The welds are, in fact, cracked in the same areas at steam generator #2 and at about the same magnitude, i.e., lengths of about 29 to 35 inches.

UT examination of safe-end to nozzle welds was performed as an expeditious means of gathering data on further cracking. It was not performed as part of the formal evaluation of these joints. There was no UT performed on these joints as part of the ISI program. The Class 2 portion of the ISI program is only 3 years old at MY, and to date these welds were not part of the schedule.

12. Q. Describe the conditions that lead to the previous installation of load spreaders on feedwater pipe supports.

A. During inspections of the feedwater system in 1973, hanger no. H-14 on #3 Steam Generator Feedline was observed to have spalled concrete behind the baseplate. An evaluation of the integrity of the support was attempted but it was not possible to determine the condition of the anchor bolts which are located behind the baseplate and inaccessible for NDE. It was decided to augment the existing anchor bolts with additional anchors having equivalent shear and pull-out load capability. The load spreaders provided this capability.

13. Q. Question Deleted

14. Q. Supply mechanical property (including toughness) information on the safe-ends, 15° elbows, and straight pipe (on No. 3 S.G.).

A. The safe-ends were supplied by C.E. The safe-end to S/G nozzle weld was a shop weld performed by C.E. The safe-end to 15° elbow weld is a field weld performed by S&W. The safe-end material is to Mat'l Spec. SA-508, Class 1. The 15° elbow is to Mat'l Spec. SA-234, Gr. WPB.(SMLS).

14. A. (Con't)

Safe Ends - SA 508 - Class 1

| | |
|-------------------|------------|
| Tensile Strength | 76,000 psi |
| Yield Strength | 51,000 psi |
| Elongation in 2" | 35% |
| Reduction in Area | 74.5% |
| Charpy Impact | +10°F |

Three Specimen ft-Lb (137/121/142)

Elbows - SA 234 Gr WPB (SMLS)

| | |
|-------------------|------------------|
| Tensile Strength | 60,000 psi (min) |
| Yield Strength | 35,000 psi (min) |
| Elongation in 2" | 22% (min) |
| Reduction in Area | 38% (min) |

Pipe - SA 106 Gr B

| | |
|------------------|------------------|
| Tensile Strength | 60,000 psi (min) |
| Yield Strength | 35,000 psi (min) |

15. Q. Is there any other pressure or temperature time history data available to support the "water hammer" event.

A. No.

16. Q. Show results of your stress displacement calculations on feedwater piping. (Suggested presentation is curves of stress levels vs. length). Do the force levels inferred by the damage to supports and snubbers correspond to the model results.

A. The attached tables Q.16.1 - Q.16.3 list the calculated thermal displacements at the various support points, the corresponding stresses at these points (B31.1, eq. #14) and the observed displacements recorded subsequent to the feedwater system event. As illustrated by these tables, the observed deformations are consistently below those displacements expected due to normal thermal growth. The damage reported to supports and snubbers is consistent with the relatively small displacements observed.

This review was conducted primarily to aid in identifying areas requiring detailed inspection.

17. Q. Does your inspection and repair program adequately address all potential causes of this event: water hammer, thermal stresses, fatigue cracking, as-built defects.

A. Yes. The stress risers have been blended out of the replacement els. See also response to #10.

18. Q. Was any pressure surge or transient associated with realignment of aux. feed water to first point heaters?

A. Industry experience and literature regarding steam-water hammer indicates that it is probably caused by rapidly condensing steam in the ring and/or adjacent pipe sections causing a rapid pressure change, first negative then positive, where the surging water impacts. We think this occurred at Maine Yankee just as the feed ring nozzles became covered by the rising level. The expanded thermal sleeve sections are evidence of the positive pressure surge which probably extended the existing crack in the pipe.

However, it is possible to postulate that the introduction of auxillary feed into the feed line just prior to the first point heater could cause a water-hammer type event or initiate a preliminary surge that precipitates the larger, more classical surge. The mechanism follows.

At the time of the trip, feedwater downstream of the first point heater is 1200 psi and 440°F. Loss of flow would trap the feed in the line between pump discharge check and the S.G. check. The pressure in the line would drop due to a 1" orificed warming line to saturation for 440°F, (367 psi) or the discharge head of the condensate pumps which is greater than 400 psi. If the condensate pumps were off or because of elevation differences the effective condensate pump pressure just below the last check was below saturation then a steam bubble would form in the line just below the last check. As aux. feed flow, 1200 psi, is introduced it would compress the existing 440°F steam bubble into a super saturated condition and force it thru the last check where it would contact the cold aux. feed. The collapsing super saturated steam would cause feedwater flow to surge, possibly initiating steam-water hammer in the ring and adjacent pipe.

The condensate pumps were on in this case and the elevation difference is inadequate. Nonetheless, our revised operating instructions will address this possibility to prevent its occurrence.

19. Q. When was last walk through of feedlines and supports in the containment?

A. During the 1982 refueling outage, the shock suppressors and some hangers and supports were walked through as part of the 1982 service inspection.

A complete walk through was conducted during the 1980 refueling outage.

20. Q. Were snubbers damaged by rapid application of load in excess of their load capacity, or because of the pipe displacement in excess of the capacity of the snubber displacement?

A. It appears that the failure modes for displacement and excessive load are identical. Our belief, based on reported pipe movement, is that failure was due to excessive load. The component that deformed appears to be the weakest link in the assembly.

21. Q. Does any data on the No. 3 steam generator support a more severe event on that feedline?

A. The #3 steam generator feedwater loop could have experienced a more severe event than the other loops from pipe support perspective due to the following geometric and support differences:

- 1) Horizontal length of feedwater line in the annulus area is approximately 224 feet in loop #3, 69 feet in loop #2 and 25 feet in loop #1.
- 2) Only loop #3 has a mid-span anchor (H-13).
- 3) Only loop #3 has a change in elevation as it runs along the annulus. Either a pressure wave or water slug passing along this line and through the pair of back-to-back 30° bends just upstream of the anchor could account for the observed distress. However, it cannot be proven that this occurred.

t=0 @ 1433⁰²

Q4

| t, MIN | STM (SN) PRESSURE, PSIG | | | CONTAINMENT PRESSURE | | GMT SUMP LEVEL, FT | GMT DEN PT. TEMPS, OF | | | GMT VAP P, PSIA |
|--------|-------------------------|-------|-------|----------------------|-------|--------------------|-----------------------|---------|---------|-----------------|
| | #1 | #2 | #3 | PSIA | IN HG | | MPX 3H | MPX 350 | MPX 738 | |
| 0 | 840.0 | 838.8 | 837.1 | 16.03 | 32.52 | 0.710 | 73.7 | 71.2 | 73.7 | 0.84 |
| 1 | 894.9 | 892.2 | 894.5 | - | - | - | - | - | - | - |
| 2 | 882.7 | 877.9 | 882.9 | - | - | - | - | - | - | - |
| 3 | 875.4 | 872.5 | 874.9 | - | - | - | - | - | - | - |
| 4 | 869.9 | 867.6 | 870.0 | - | - | - | - | - | - | - |
| 5 | 866.2 | 864.0 | 866.4 | - | - | - | - | - | - | - |
| 9 | 864.4 | 861.6 | 864.0 | 16.01 | 32.53 | 0.729 | 73.3 | 71.3 | 73.3 | 0.83 |
| 19 | 876.7 | 873.8 | 876.2 | 16.49 | 33.24 | 2.615 | 76.8 | 83.3 | 76.8 | 0.93 |
| 22 | 876.4 | 874.0 | 876.2 | 16.55 | 33.44 | 2.780 | 80.1 | 89.8 | 80.1 | 1.03 |
| 28 | 875.6 | 872.9 | 875.3 | 16.73 | 33.58 | 2.980 | 85.5 | 98.5 | 85.5 | 1.23 |
| 43 | 871.8 | 868.9 | 871.3 | 16.74 | 33.39 | 3.281 | 90.5 | 98.7 | 90.5 | 1.44 |
| 47 | 873.6 | 870.9 | 873.3 | 16.74 | 33.32 | 3.333 | 90.3 | 98.1 | 90.3 | 1.43 |
| 51 | 875.6 | 872.8 | 875.2 | 16.68 | 33.27 | 3.416 | 90.1 | 97.1 | 90.1 | 1.42 |
| 63 | 873.0 | 870.1 | 873.1 | 16.61 | 33.01 | 3.490 | 90.2 | 94.3 | 90.2 | 1.43 |

6.8

CONTAINMENT ZONE TEMPERATURES, OF

| t, MIN | ZN #1, 28' | ZN #2, 28' | ZN #3, 28' | ZN #4, 30' | ZN #5, 30' | ZN #6, 30' | ZN #7, 30' | ZN #8, 30' |
|--------|------------|------------|------------|------------|------------|------------|------------|------------|
| 0 | 98.3 | 94.4 | 99.4 | 101.4 | 104.2 | 94.3 | 107.0 | 101.8 |
| 1 | - | - | - | - | - | - | - | - |
| 2 | - | - | - | - | - | - | - | - |
| 3 | - | - | - | - | - | - | - | - |
| 4 | - | - | - | - | - | - | - | - |
| 5 | - | - | - | - | - | - | - | - |
| 9 | 98.3 | 94.5 | 99.3 | 101.5 | 104.1 | 94.1 | 106.9 | 101.8 |
| 19 | 99.0 | 95.8 | 100.2 | 101.7 | 105.1 | 95.5 | 118.7 | 101.8 |
| 22 | 100.0 | 97.2 | 101.2 | 101.7 | 106.2 | 96.3 | 124.4 | 102.2 |
| 28 | 101.6 | 99.2 | 102.5 | 102.1 | 107.7 | 97.7 | 130.6 | 103.3 |
| 43 | 103.6 | 98.8 | 104.1 | 104.0 | 109.2 | 99.6 | 118.9 | 105.9 |
| 47 | 103.3 | 98.7 | 103.6 | 104.1 | 109.2 | 99.1 | 124.1 | 105.9 |
| 51 | 102.9 | 98.6 | 102.9 | 104.2 | 109.3 | 99.5 | 117.4 | 106.1 |
| 63 | 101.4 | 97.9 | 102.2 | 104.2 | 109.0 | 100.2 | 111.1 | 106.2 |

Q 4

CONTAINMENT ZONE TEMPERATURES, °F

| t, MIN | CONTAINMENT ZONE TEMPERATURES, °F | | | | | GMT AIR TEMP OF |
|--------|-----------------------------------|-------------|-------------|-------------|--------------|-----------------|
| | ZN #9, 60' | ZN #10, 60' | ZN #11, 60' | ZN #12, 60' | ZN #13, 110' | |
| 0 | 100.7 | 102.8 | 105.3 | 82.0 | 150.1 | 101.9 |
| 1 | - | - | - | - | - | - |
| 2 | - | - | - | - | - | - |
| 3 | - | - | - | - | - | - |
| 4 | - | - | - | - | - | - |
| 5 | - | - | - | - | - | - |
| 9 | 100.6 | 103.0 | 105.6 | 81.7 | 150.1 | 102.0 |
| 19 | 102.2 | 103.5 | 125.4 | 90.1 | 150.1 | 107.5 |
| 22 | 103.5 | 104.3 | 133.8 | 94.0 | 150.1 | 110.3 |
| 28 | 105.1 | 105.8 | 122.7 | 93.9 | 150.1 | 109.0 |
| 43 | 106.5 | 108.3 | 117.6 | 95.1 | 150.1 | 108.9 |
| 47 | 106.4 | 108.3 | 117.5 | 94.7 | 150.1 | 108.9 |
| 51 | 106.1 | 108.2 | 117.2 | 94.0 | 150.1 | 108.6 |
| 63 | 105.4 | 106.4 | 115.1 | 92.4 | 150.1 | 107.4 |

(OFFSCALE HIGH)


| t, MIN | SYM GEN FEED WATER T, °F | | | PRESSURIZER P, PSIG | PCS LOOP Tc, °F | | |
|--------|--------------------------|-------|-------|---------------------|-----------------|-------|-------|
| | #1 | #2 | #3 | | #1 | #2 | #3 |
| 0 | 439.5 | 444.3 | 439.7 | 2232.9 | 551.2 | 546.7 | 546.7 |
| 1 | - | - | - | 1904.3 | 541.7 | 634.9 | 535.3 |
| 2 | - | - | - | 1880.2 | 536.5 | 531.3 | 531.7 |
| 3 | - | - | - | 1886.3 | 535.4 | 530.2 | 530.6 |
| 4 | - | - | - | 1906.7 | 534.3 | 529.4 | 529.8 |
| 5 | - | - | - | 1930.8 | 534.0 | 528.7 | 529.1 |
| 7 | 438.3 | 440.4 | 439.0 | 1986.6 | 534 | 532 | 532 |
| 19 | 437.4 | 439.0 | 434.9 | 2032.2 | 534 | 532 | 532 |
| 22 | 434.9 | 431.2 | 433.1 | 2015.7 | 534 | 532 | 532 |
| 28 | 428.7 | 374.5 | 423.0 | 2085.8 | 534 | 532 | 532 |
| 43 | 428.1 | 201.1 | 379.7 | 2217.8 | 534 | 532 | 532 |
| 47 | 428.6 | 186.5 | 377.9 | 2218.7 | 534 | 532 | 532 |
| 51 | 426.2 | 163.2 | 333.8 | 2220.2 | 534 | 532 | 532 |
| 63 | 139.6 | 91.5 | 104.7 | 2237.2 | 534 | 532 | 532 |

FROM Tc TRACES (APPROX.)

8.10


Q5

STEAM GENERATOR NO. 1
LEVEL VS. TIME



Q5

STEAM GENERATOR NO. 2
LEVEL VS. TIME




LEVEL %
N. R. 30 8.12

FEED RING APPROX.


Q5

STEAM GENERATOR NO. 3
LEVEL VS. TIME




LEVEL % N.30 R. 8.13


0° IS TOP DEAD CENTER
LOOKING INTO STEAM GENERATOR.



#1 EL



2 EL



3 EL

TABLE 16.1

STEAM GENERATOR FEEDWATER - LOOP #1
 14"-WFDD-4-601 MKS-102A1-3

| SUPPORT NO. | NODE | STRESSES (PSI) EQ. 14 ALLOW. = 37,500 | THERMAL DEFLECTIONS *(IN.) | | | OBSERVED DEFLECTIONS |
|------------------------|------|---|----------------------------|------------|------------|---|
| | | | ΔX | ΔY | ΔZ | |
| PEN. #53 | 54 | 23,138. | 0.050 | 0.150 | 0.350 | No observed deformation |
| M-328 S.W | 50 | 12,600. | 0.086 | 0.506 | 0.165 | Slight gap on wall plate (< 1/8") (Appears old) |
| H-329 S.H. 155. | 45 | 9,973. | 0.890 | 0.699 | 1.686 | Sliding plate indicates 1/2"-1" movement |
| LS3-202 SNUBBER | 41 | 5,833. | 0.850 | 1.528 | 1.739 | No observed deformation |
| ASS-201 AXIAL SNUB. | 62 | 15,329. | 0.890 | 1.594 | 1.732 | No observed deformation |
| STM. GEN. NOZZLE | 59 | 22,146. | 1.000 | 2.490 | 2.180 | Offset piece indicated cracks, being replaced |

SOURCE: CYGNA CALCULATION SET PI-007 FILE 82006-17F, REV. 0

*THERMAL DEFLECTIONS INCLUDE THERMAL ANCHOR MOVEMENTS

TABLE 16.2

STEAM GENERATOR FEEDWATER - LOOP #2

14"-WFDD-8-601 MKS-102E1-3

| SUPPORT NO. | NODE | STRESSES (PSI) EQ. 14 ALLOW = 37,500 | THERMAL DEFLECTIONS *(IN.) | | | OBSERVED DEFLECTIONS |
|---------------------|------|--|----------------------------|------------|------------|---|
| | | | ΔX | ΔY | ΔZ | |
| PEN. 55 | 215 | 9,974. | -0.080 | 0.156 | 0.349 | No observed deformations |
| H-6 (S.H.) | 183 | 8,441. | -0.193 | 0.301 | 0.068 | No observed deformations |
| H-5 (Vert.) | 145 | 7,759. | -0.903 | 0.209 | 0.616 | No observed deformations |
| LSS-206 | 135 | 7,939. | -1.451 | 0.213 | 0.668 | Loose bushing, minor surface spalling of concrete |
| LSS-205 | 125 | 5,833. | -1.610 | 0.214 | 0.649 | No observed deformation |
| H-4 (S.S) | 115 | 9,402. | -1.723 | 0.209 | 0.623 | No observed deformation |
| H-3 (S.S) | 100 | 9,421. | -2.269 | 0.209 | 0.205 | No observed deformation |
| LSS-203 LSS-204 | 90 | 8,020. | -2.332 | 0.378 | 0.005 | Loose bushings |
| N-2 (S.H.) | 80 | 7,925. | -2.291 | 0.915 | -0.396 | No observed deformation |
| H-327 (S.H.) | 70 | 10,018. | -2.209 | 1.176 | -0.534 | No observed deformation |
| 110 ZELE @ E-1-2 | 5 | 15,170. | -2.160 | 2.078 | -0.157 | Offset piece cracked, being replaced |

SOURCE: CYGNA CALCULATION SET PI-008 FILE 82006-17F, REV. 0

*THERMAL DEFLECTIONS INCLUDE THERMAL ANCHOR MOVEMENTS

TABLE 16.3

STEAM GENERATOR FEEDWATER - LOOP #3

16"-WFDD-10-601 MKS-102NI-3

| SUPPORT NO. | NODE | STRESSES (PSI) EQ. 14 ALLOW = 37,500 | THERMAL DEFLECTIONS *(IN.) | | | OBSERVED DEFLECTIONS |
|--------------------|------|--|----------------------------|------------|------------|---|
| | | | ΔX | ΔY | ΔZ | |
| PEN. 54 | 2 | 12,187. | -0.016 | 0.146 | 0.549 | No observed deformation |
| H-18 (S.H.) | 14 | 10,403. | -0.078 | 0.290 | 0.133 | No observed deformation |
| H-19 (S.S) | 28 | 8,369. | -0.695 | 0.183 | 1.444 | 1/4" (TANG.); 1" (Radial Sliding observed support ok) |
| LSS 216 | 32 | 9,593. | -1.103 | 0.168 | 1.804 | No deformation observed |
| LSS 215 | 36 | 9,549. | -1.353 | 0.170 | 1.956 | No deformation observed |
| H16 (S.S) | 40 | 10,840. | -1.842 | 0.183 | 2.091 | No deformation observed |
| H-15 (S.S) | 46 | 9,041. | -2.143 | 0.183 | 1.447 | Small slide (1/4" TANG.); 1/4-3/8" Gap on right side of base plate |
| LSS-213 LSS-214 | 52 | 8,062. | -1.778 | 0.193 | 0.950 | No deformation observed |
| H-14 (VERT-S.S.) | 56 | 7,471. | -1.254 | 0.183 | 0.539 | Bottom slide 1/4"-1/2" (TANG.) Top slide =1/2" anchor bolts only finger tight |
| H-13 (Anc) | 68 | 13,054. | -0.311 | 0.199 | -0.082 | Spalled concrete (<1/2" deep) at W10 imbedment |

SOURCE: CYGNA CALCULATION SET PI-009 FILE 82006-17F, REV. 0

*THERMAL DEFLECTIONS INCLUDE THERMAL ANCHOR MOVEMENTS

TABLE 16.3

(Continued)

STEAM GENERATOR FEEDWATER - LOOP #3

14"-WFDD-10-601 MKS-102-J1-3

| SUPPORT NO. | NODE | STRESSES (PSI) EQ. 14 ALLOW = 37,500 | THERMAL DEFLECTIONS *(IN.) | | | OBSERVED DEFLECTIONS |
|--------------------|------|--|----------------------------|------------|------------|--|
| | | | ΔX | ΔY | ΔZ | |
| H-12 (S.S.) | 4 | 7,455. | -0.250 | 0.209 | -0.715 | No observed deflection |
| LSS 211 LSS 212 | 4 | 7,433. | -0.250 | 0.209 | -0.715 | LSS 212 shows small quantity of spalled concrete |
| H-11 (S.S.) | 7 | 7,507. | -0.134 | 0.209 | -1.452 | Slide Tang. 1/4" (approximately) |
| H-10 (S.S.) | 10 | 7,882. | 0.256 | 0.209 | -2.023 | No observed deflection |
| LSS 209 LSS 210 | 11 | 7,591. | 0.317 | 0.213 | -2.065 | LSS-209 Slight buckling of snubber eye bolt |
| H-9 (S.S.) | 13 | 9,486. | 0.824 | 0.209 | -2.172 | No observed deflection |
| LSS 207 LSS 208 | 16 | 9,979. | 1.368 | 0.209 | -1.869 | No observed deflection |
| H-8 | 16 | 9,979. | 1.368 | 0.209 | -1.869 | Slight slike (1/8") in opposite direction? |
| H-7 (S.H.) | 20 | 10,567. | 1.676 | 0.956 | -1.332 | No observed deflection |
| Nozzle @ E-1-3 | 29 | 16,974. | 1,424 | 2.078 | -1.584 | Offset piece indicated |

SOURCE: CYGNA CALCULATION SET PI-J10 FILE 82006-17F, REV.0

*THERMAL DEFLECTIONS INCLUDE THERMAL ANCHOR MOVEMENTS

9) STARTUP TESTS

- HYDROSTATIC TEST
- WATER HAMMER TEST

MAIN STEAM & FEED SYSTEM HYDROS

ASME SECTION XI, SUBSECTION IWC-5000, HYDRO

The following systems will be pressurized for four hours and inspected for evidence of leakage:

Main Feed - From reg. valves to the Steam Generators

Main Steam - SG's to the excess flow checks

Blowdown - SG's 1 & 2 to the CIS valves

SG 3 to the first isolation valve

Aux. Feed - SG's to the check valves

Pressure: 1188 to 1288 psig

Temperature: greater than or equal to 100°F

STEAM-WATER HAMMER TEST PROGRAM

OUTLINE

Prestart Conditions:

1. Plant in Hot Shutdown Condition.
2. Feedwater supplied using motor driven aux feed pump P-25-A via #1 heater, with steam supply on.
3. #2 Steam Generator Feed Line monitored for temperature, movement, sound.
4. #2 Steam Generator Aux Feed Control Valve open, #1 and #3 Aux Feed Control Valve Closed.

Test:

1. Reduce #2 Steam Generator level by blowdown and steaming to below auto start set point for auxiliary feed pumps (35% NR) while maintaining minimum flow.
2. Stop heated feed flow to #2 Steam Generator.
3. Start Motor Driven Aux Feed Pump P-25-C and establish 300 gpm max flow to #2 Steam Generator.
4. Record temperature, pressure, level, noise, pipe movement.

10) JUSTIFICATION FOR RETURN TO POWER

- SHORT TERM

- LONG TERM

10) JUSTIFICATION FOR OPERATION

SHORT TERM - RETURN TO POWER

1. Problem has been identified:
 - a) Stress risers in SG nozzle and adjacent horizontal pipe.
 - b) Thermal cycling and distortion causing cracks at stress risers.
 - c) Steam-water hammer causes existing crack to fail.
2. Problem has been adequately addressed:
 - a) Cracks repaired in nozzle and safe end.
 - b) Horizontal pipe and 20° els replaced with new pipe without stress risers.
 - c) Stress risers ground out of horizontal end of 90° el and safe ends.
 - d) All pipe upstream of check valves has been NDE inspected and base line data recorded.
 - e) Internal damage to feed ring repaired.
 - f) Expanded thermal sleeves have been evaluated as adequate for restart.
 - g) J tubes have been installed on feed rings to reduce the likelihood of steam-water hammer and somewhat mitigate non-uniform thermal stresses.
 - h) Damaged hangers and supports have been repaired.
 - i) Support attachments to pipe has been examined and found undamaged.
 - j) Highest stress weld joint adjacent to support has been RT and is satisfactory.
 - k) Pipe movement has been evaluated and determined not to be excessive.
 - l) Pipe returned to original position indicating no probable yielding at any point.
 - m) Feedwater check valves inspected and found to be distortion free.
 - n) Feedwater system from feed control station through SGs will be given a four-hour 120% pressure hydro test.
 - o) Revised feedwater system operational guidance has been issued. Reduces the propability of steam-water hammer and reduces thermal effects.
 - p) Operators have been trained in new guidance.
 - q) Pre-startup operations will include a steam-water hammer test.

LONG TERM

1. Further measures will be taken prior to startup from the 1984 refueling outage to assure continued safe operation:
 - a) All modified pipe welds and sections will be UT and compared to present baseline data.
 - b) The inservice inspection program will be modified to revise the frequency and scope of inspection applied to the SG nozzle and horizontal pipe.
 - c) All remaining pipe between feedwater check valves and steam generators will be modified to remove any stress risers that may exist.
 - d) A more detailed evaluation of the expanded feed ring thermal sleeves shall be made. If warranted, the thermal sleeves shall be repaired or replaced.
 - e) Further modifications to the system or its operations will be investigated.