

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	D	C	C	N	1	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4				5		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40
LICENSEE CODE								LICENSE NUMBER										LICENSE TYPE				CAT 58											

0	1	L	6	0	5	0	0	0	3	1	7	7	0	1	0	7	8	3	8	0	2	0	4	8	3	9
7	8	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84
CON'T		REPORT SOURCE		DOCKET NUMBER										EVENT DATE				REPORT DATE								

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2	During normal operation at 1330, it was discovered that #11 ECCS pump																												
0	3	room fan discharge damper was only partially open. As there was no as-																												
0	4	surance that the ECCS pump room ventilation could perform its design																												
0	5	function with the damper throttled, it was declared inoperable																												
0	6	(T.S. 3.7.7.1). The damper was immediately opened to the full open posi-																												
0	7	tion and operability to the ECCS pump room ventilation restored.																												
0	8	Similar events: None.																												
7	8	9																												

0	9	A	A	11	D	12	Z	13	V	A	L	V	E	X	14	N	15	D	16								
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21													
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE													
17	LER/RO REPORT NUMBER	8	3	21	22	0	0	7	0	3	28	29	L	30	0	32											
EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.																			
X	18	G	19	Z	20	Z	21	0	0	0	0	N	23	N	24	A	25	Z	9	9	9	26					
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	Investigation has not yielded the party responsible for throttling the																												
1	1	damper. This damper and similar ECCS pump room ventilation dampers will																												
1	2	be locked open by locking the damper handle mechanism in the fully																												
1	3	open position. Surveillance shall be performed monthly by adding the																												
1	4	damper to the locked valve surveillance test procedure.																												
7	8	9																												

1	5	E	28	0	9	5	29	NA	30	D	31	Resident Inspector Observation												32																													
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION																																													
1	6	Z	33	Z	34	NA	35	NA	36																																												
ACTIVITY RELEASED		CONTENT		AMOUNT OF ACTIVITY		LOCATION OF RELEASE																																															
1	7	0	0	0	37	Z	38	NA	39																																												
PERSONNEL EXPOSURES		TYPE		DESCRIPTION																																																	
1	8	0	0	0	40	NA	41																																														
PERSONNEL INJURIES		DESCRIPTION																																																			
1	9	Z	42	NA	43																																																
LOSS OF OR DAMAGE TO FACILITY		DESCRIPTION																																																			
2	0	N	44	NA	45																																																
PUBLICATION DESCRIPTION		8302230701 830204										PDR ADOCK 05000317										S PDR										NRC USE ONLY																					