



UNITED STATES
NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-0001

April 1, 1994

MEMORANDUM FOR: Those on Attached List

FROM: Leif J. Norrholm, Chief
Vendor Inspection Branch
Division of Reactor Inspection
and Licensee Performance
Office of Nuclear Reactor Regulation

SUBJECT: MONTHLY UPDATE OF VENDOR INSPECTION BRANCH PART 21 TRACKING
SYSTEM - MONTH OF MARCH, 1994

Attached is the March update of the Part 21 database maintained by the Vendor Inspection Branch (VIB). It identifies those new Part 21 issues appended to the database during the month of March. In addition to formal Part 21 submittals, it also contains LER, Part 50.55(e), and Part 50.72 issues as well as other communications that were determined to possibly address Part 21 type matters that require review. If you are aware of any Part 21 type matters that are not included in the database, or if you need additional information regarding the Part 21 issues assigned to your branch or the Part 21 review program itself, please contact Walter Haass at 504-3219.

It should be noted that the entries shown in the monthly frequently represent the early/initial notification of the component defect or failure to comply in accordance with Part 21 requirements. If no closure acronym is shown, the notification remains under review and the root cause of the problem, the corrective action to repair the defect and assure nonrecurrence, and the affected licensees have not been identified at the time of report issuance. In this light, the notifications should be primarily considered as a "heads up" with action expected, in general, only upon the subsequent issuance of specific information from the vendor and/or the NRC.

Leif J. Norrholm, Chief
Vendor Inspection Branch
Division of Reactor Inspection
and Licensee Performance
Office of Nuclear Reactor Regulation

Enclosure:
Part 21 Tracking System and Monthly Update

9404050125 940401
PDR PT21 NRCZ
GENERAL PDR

Handwritten initials/signature

10 CFR PART 21 TRACKING SYSTEM

VENDOR INSPECTION BRANCH
DIVISION OF REACTOR INSPECTION AND LICENSEE PERFORMANCE

LOG #	SUB	REPORT	ACCESSION	ASSIGNED	CLOS	DESCRIPTION
		AND	NUMBER		OUT	
		VEND			CODE	
		CODE				
94049	DOE	02/04/94		RVIB: K. NAIDU		DEPARTMENT OF ENERGY REPORTS FAILURE OF 3 WEST SEALED CIRCUIT BREAKERS OUT OF 55 TESTED DUE TO DEFECTIVE OR FAILED PARTS. C/B# ARE 600V, 3-POLE, 15 AMP & 700 AMP. AGE & NORMAL WEAR WERE CITED AS ROOT CAUSES. NORMAL SERVICE LIFE IS 12 YRS.
		W120				
				DUE BY: 5/2/94		
94050	NYPA	02/28/94		RVIB: L. CAMPBELL		NEW YORK POWER AUTHORITY/IP-3 REPORTS PURCHASE & RECEIPT OF CAT I PIPING FROM INTERSTATE STEEL WHO IS NOT A QUALIFIED VENDOR OF THIS PRODUCT. PIPING WAS OBTAINED FROM TIOGA AS COMM GRADE. VENDOR CLAIMS NO OTHER LICENSEE HAS PURCHASED SUCH PIPING.
		I163				
		T361				
				DUE BY: 5/2/94		
94051	DPC	02/03/94	9402180066	EMCB: J. DAVIS		DUKE POWER/OCONEE-2 REPORTS EXCESSIVE LEAKAGE FROM RC PUMP SEAL SUPPLY FLOW THROTTLE VALVE DUE TO FAILURE OF PACKING GLAND STUDS. STUD FAILURE DUE TO H-2 EMBRITTLEMENT OCCURRING DURING MFTRG.
		K085				
				DUE BY: 6/3/94		
94052	U009	09/30/94	9310050161	RVIB: W. HAASS	INIS	MRC-REGION III REPORTS IN AN IR INTERMITTENT FAILURE OF VARIOUS PROCESS CONTROL UNITS DUE TO DEFICIENCIES IN DESIGN/MNFCTRNG OF ELECTRICAL SOCKETS BY AUGAT, INC. SOCKETS WERE REPLACED. IN 94-04 ISSUED ON 1/14/94 TO ALL LICENSEES.
		B455				
		IME				
				DUE BY: 5/2/94		
94053	CEC	10/20/94	9310270153	SRXB: R. JONES	CTBI	CONSOLIDATED EDISON/IP-2 REPORTS ON RECEIPT OF NSAL-93-018 & 018K DATED 9/21/93 FROM WEST REGARDING POTENT ISSUE OF MODELING OF SI FLOW IN ANALYSIS SBLOCA USING NOTRUMP COMPUTER CODE. WEST HAS NOTIFIED APTD LICENSEES.
		W120				
				DUE BY: 3/8/94		
94054	IEL	03/01/94		RVIB: R. McINTYRE		IES INDUSTRIES/DUANE ARNOLD EC REPORTS FAILURE OF RHR PUMP TO MEET DISCHARGE PRESS ROMNT. CAUSE IS LOWERING OF PUMP IMPELLOR & SHAFT DUE TO SHAFT NUT WASHER NOT BENT TO ENGAGE MOTOR NUT DURING OVERHAUL AT GE.
		G080				
				DUE BY: 5/2/94		
94055	C628	02/21/94	9403110242	RVIB: W. HAASS	CTBI	COOPER-BESSEMER PROVIDES CORRECTION OF PART NUMBERS PREV REPORTED REGARDING CRACKING OF SUBCOVERS FOR DSRV & DSR DIESEL ENGINES. SEE LOG#93453.
				DUE BY: 5/2/94		
94056	N007	03/02/94	9403100007	RVIB: R. FRAHM		NAMCO CONTROLS PROVIDES FURTHER INFO REGARDING FAILURE OF OPERATING LEVERS ON EA740-86700 LIMIT SWITCHES TO RETURN TO THEIR INITIAL POSITION. CAUSE ATTRIB TO REACTION OF LUBE OIL & O-RING. O-RING MATL MAY BE PROBLEM. SEE LOG#94037/94087.
		CWE				
				DUE BY: 5/3/94		
94057	W170	03/02/94		RVIB: R. PETTIS		WHITING CORP REPORTS SIGNIFICANT OVERSTRESS ON BOLTED CONNECTIONPOINTS OF TROLLEY MAIN HOIST COMPONENTS & OVERSTRESS CONDITION OF STRUC COMPONENTS IN GIRDER ENDS. FAILURE/DROPPED LOAD CAN RESULT. ALL APTD LICENSEES INFORMED.
				INFO: EMEB		
				DUE BY: 5/3/94		

10 CFR PART 21 TRACKING SYSTEM

VENDOR INSPECTION BRANCH
DIVISION OF REACTOR INSPECTION AND LICENSEE PERFORMANCE

LOG #	SUB REPORT AND DATE VEND CODE	ACCESSION NUMBER	ASSIGNED	CLOS OUT CODE	DESCRIPTION
94058	APS 03/02/94 V030		EMCB:G.HORNSETH INFO: RVI DUE BY: 6/10/94		ARIZONA PS/PALO VERDE 2 REPORTS IDENTIFICATION OF CRACKS IN VALVE BODY OF TWO SOLENOID-OPERATED VALVES USED FOR RCS HOT-LEG SAMPLING. VALVE BODIES ARE 4-INCH SQUARE S/S BLOCKS. SRI DOING FAILURE ANALYSIS. LOW CYCLE THERMAL FATIGUE MAY BE CAUSE.
94059	GPU 12/13/93 L200	9312200319	RVI: D.BREWER DUE BY: 5/3/94		GENERAL PUBLIC UTILITIES/THREE MILE ISLAND-1 REPORTS DIFFICULTIES IN ASSEMBLING VALVE OPERATORS WHEN REPLACING DECLUTCH LEVERS TO CORRECT POSS MALFUNCTION DURING SEISMIC EVENT. PROCEDURAL DEFICIENCY CITED.
94060	CWE 03/05/94 C665		EMEB:SCARBROUGH DUE BY: 4/8/94		COMMONWEALTH EDISON/QUAD CITIES-1 REPORTS FAILURE OF INBOARD RCIC STEAM ISOLATION VALVE TO CLOSE. VALVE FACTOR AS HIGH AS .85 BASED ON EPRI TESTING MAY BE CAUSE SINCE ASSUMED FACTOR WAS .447.SEE LOG# 94065/94082.
94061	TUG 02/16/94 P104	9403020022	RVI: W.HAASS DUE BY: 5/9/94		TU ELECTRIC/COMANCHE PEAK UNITS 1/2 PROVIDES ANALYSIS OF BOLTING FAILURES IN PAPCO GRAVITY DAMPERS. FAILURE ATTRIBUTED TO BENDING UNDER DYNAMIC LOADING CONDITIONS DUE TO OVERSIZED HOLES & NO LOCK WASHERS. REPLACED WITH HIGHER STRENGTH BOLTS. SEE LOG#94025.
94062	S637 02/08/94 NYPA	0902160303	RVI:M.WATERMAN DUE BY: 5/9/94		SORRENTO ELECTRONICS REPORTS THAT MEMORY LOCATIONS USED FOR MEMORY STACK DATAS IN MICROPROCESSORS FOR WIDE RANGE GAS MONITOR CAN OVERWRITE A PRESET STACK SIZE LIMIT CAUSING UNANTICIPATED SUBROUTINE CALLS/ACTIVITIES. RM 80 CONFIG AFYTD.
94063	W185 02/03/94 NSP		RVI: R.WILSON DUE BY: 5/9/94		WHITTAKER ELECTRONIC RESOURCES REPORTS ON LACK OF PROPER SENSITIVITY OF H-2 SENSORS PROVIDED TO PRAIRIE ISLAND FOR CONT ATMOS MONITORING. GENERIC TO ROBINSON & SAN ONGFRE.
94064	WCNO 02/02/94		RVI: K.NAIDU DUE BY: 5/10/94		WOLF CREEK NUC REPORTS FAILURE OF INDICATING LAMPS BY SHORT CIRCUIT CAUSING LOSS OF CHARGING PUMP ROOM COOLER. POTENT EXISTS FOR COMMON MODE FAILURE & MULTIPLE INOP. SAFETY SYSTEMS. POSSIBLE MISAPPLICATION OF LAMPS.
94065	CWE 03/09/94		EMEB:SCARBROUGH DUE BY: 5/2/94		COMMONWEALTH EDISON/DRESDEN 3 REPORTS HPCI VALVES WILL NOT FULLY CLOSE IN A BLOWDOWN CONDITION AS A RESULT OF HIGH FRICTION AS INDICATED BY EPRI TESTS. SEE LOG#94060/94082.
94066	F236 03/08/94 APS		EMEB: J.NORBERG DUE BY: 3/17/94		FURMANITE AMERICA REPORTS RESULTS OF SETPOINT COMPARATIVE TESTING OF MSSV ₆ BETWEEN THEIR TRAVITEST & OVER PRESS TESTING. RESULT IS THAT MEAN SEAT AREA SHOULD BE CHANGED FROM 24.626 SQ.IN TO 23.046 TO REDUCE OFFSET. SEE LOG# 94069/94073/94084.

10 CFR PART 21 TRACKING SYSTEM

VENDOR INSPECTION BRANCH
DIVISION OF REACTOR INSPECTION AND LICENSEE PERFORMANCE

LOG #	SUB	REPORT	ACCESSION	ASSIGNED	CLOS	DESCRIPTION
		AND DATE	NUMBER		OUT	
		VEND			CODE	
		CODE				
94058	APS	03/02/94		EMEB: G. HORNSETH		ARIZONA PS/PALO VERDE 2 REPORTS IDENTIFICATION OF CRACKS IN VALVE BODY OF TWO SOLENOID-OPERATED VALVES USED FOR RCS HOT-LEG SAMPLING. VALVE BODIES ARE 4-INCH SQUARE S/S BLOCKS. SRI DOING FAILURE ANALYSIS. LOW CYCLE THERMAL FATIGUE MAY BE CAUSE.
		V030		INFO: RVIB		
				DUE BY: 6/10/94		
94059	GPU	12/13/93	9312200319	RVIB: D. BREWER		GENERAL PUBLIC UTILITIES/THREE MILE ISLAND-1 REPORTS DIFFICULTIES IN ASSEMBLING VALVE OPERATORS WHEN REPLACING DECLUTCH LEVERS TO CORRECT POSS MALFUNCTION DURING SEISMIC EVENT. PROCEDURAL DEFICIENCY CITED.
		L200				
				DUE BY: 5/3/94		
94060	CWE	03/05/94		EMEB: SCARBROUGH		COMMONWEALTH EDISON/QUAD CITIES-1 REPORTS FAILURE OF INBOARD RCIC STEAM ISOLATION VALVE TO CLOSE. VALVE FACTOR AS HIGH AS .85 BASED ON EPRI TESTING MAY BE CAUSE SINCE ASSUMED FACTOR WAS .447. SEE LOG# 94065/94082.
		C665				
				DUE BY: 4/8/94		
94061	TUG	02/16/94	9403020022	RVIB: W. HAASS		TU ELECTRIC/COMANCHE PEAK UNITS 1/2 PROVIDES ANALYSIS OF BOLTING FAILURES IN PAPCO GRAVITY DAMPERS. FAILURE ATTRIBUTED TO BENDING UNDER DYNAMIC LOADING CONDITIONS DUE TO OVERSIZED HOLES & NO LOCK WASHERS. REPLACED WITH HIGHER STRENGTH BOLTS. SEE LOG#94025.
		F104				
				DUE BY: 5/9/94		
94062	S637	02/08/94	0902160303	RVIB: M. WATERMAN		SORRENTO ELECTRONICS REPORTS THAT MEMORY LOCATIONS USED FOR MEMORY STACK DATAS IN MICROPROCESSORS FOR WIDE RANGE GAS MONITOR CAN OVERWRITE A PRESET STACK SIZE LIMIT CAUSING UNANTICIPATED SUBROUTINE CALLS/ACTIVITIES. RM 80 CONFIG APFTD.
		NYFA				
				DUE BY: 5/9/94		
94063	W185	02/03/94		RVIB: R. WILSON		WHITTAKER ELECTRONIC RESOURCES REPORTS ON LACK OF PROPER SENSITIVITY OF H-2 SENSORS PROVIDED TO PRAIRIE ISLAND FOR CONT ATMOS MONITORING. GENERIC TO ROBINSON & SAN ONOFRE.
		NSP				
				DUE BY: 5/9/94		
94064	WCNO	02/02/94		RVIB: K. NAIDU		WOLF CREEK NUC REPORTS FAILURE OF INDICATING LAMPS BY SHORT CIRCUIT CAUSING LOSS OF CHARGING PUMP ROOM COOLER. POTENTIAL EXISTS FOR COMMON MODE FAILURE & MULTIPLE INOP. SAFETY SYSTEMS. POSSIBLE MISAPPLICATION OF LAMPS.
				DUE BY: 5/10/94		
94065	CWE	03/09/94		EMEB: SCARBROUGH		COMMONWEALTH EDISON/DRESDEN 3 REPORTS HPCI VALVES WILL NOT FULLY CLOSE IN A BLOWDOWN CONDITION AS A RESULT OF HIGH FRICTION AS INDICATED BY EPRI TESTS. SEE LOG#94060/94082.
				DUE BY: 5/2/94		
94066	F236	03/08/94		EMEB: J. NORBERG		FURMANITE AMERICA REPORTS RESULTS OF SETPOINT COMPARATIVE TESTING OF MSSVs BETWEEN THEIR TRAVITEST & OVER PRESS TESTING. RESULT IS THAT MEAN SEAT AREA SHOULD BE CHANGED FROM 24.626 SQ. IN TO 23.046 TO REDUCE OFFSET. SEE LOG# 94069/94073/94084.
		APS				
				DUE BY: 3/17/94		

10 CFR PART 21 TRACKING SYSTEM

VENDOR INSPECTION BRANCH
DIVISION OF REACTOR INSPECTION AND LICENSEE PERFORMANCE

LOG #	SUB REPORT AND DATE VEND CODE	REPORT AND DATE	ACCESSION NUMBER	ASSIGNED	CLOSURE DESCRIPTION
94067	C470 VEP	01/21/94	9402090063	RVIB: W.HAASS	VASU COLTEC INDUSTRIES PROVIDES UPDATE ON PREV REPTD DEFECT OF AIR START DISTRIBUTOR CAM DUE TO CRACKING FROM ARC MARKING. NEW PROCEDIS SCRIBING, BUT POUND IN SOME INSTANCES COLD CHISEL ALSO USED WHICH IS NOT ACCEP. ALL LICENSEES NOTIFIED. SEE LOG# 94004. DUE BY: 5/10/94
94068	SCE MDCC	01/25/94		RVIB:U.POTAPOVS	SOUTHERN CALIFORNIA EDISON PROVIDES ROOT CAUSE ANALYSIS REPORT FOR FAILURE OF ROTO TEST SWITCH BOLTS. FAILURE ATTRIB TO USE OF EXTRA HARD TYPE BRASS WHICH IS EXTREMELY BRITTLE. PROB ISOLATED TO ONE LOT. SEE LOG# 93470/93451/93445. DUE BY: 5/11/94
94069	CWE F236	03/10/94		EMEB: J.NORBERG	COMMONWEALTH EDISON/BYRON/BRAIDWOOD REPORTS ERROR IN MEAN SEST AREA OF MSSV _s FOR TEST PURPOSES MAY HAVE LEFT LIFT SETPOINT OUTSIDE TECH SPEC REQNTS. FURMANITE CORRECTING TREVITESTING PARAMETERS & HAS NOTIFIED AFFTD LICENSEES. SEE LOG# 94066/94073/94084. DUE BY: 3/18/94
94070	SOC C470 MD40	02/09/94		RVIB: K.NAIDU	SOUTH CAROLINA E&G/SUMMER 1 REPORTS LEVEL SWITCHES FOR EDG DAY TANKS MAY NOT BE SEISMICALLY QUALIFIED. COLTEC/FMED PROVIDED SWITCHES AS SIEMIC QUAL. BUT CANNOT PRODUCE DOCUMENTATION. DUE BY: 5/11/94
94071	IPC W120	11/19/94	9312080036	RVIB: ALEXANDER	ILLINOIS POWER REPORTS FAILURE OF C/B FOR SHUTDOWN SERVICE WATER SYSTEM PUMP TO RECLOSE UPON RESTORATION OF BUS VOLTAGE DUE TO FAILURE OF ANTI-PUMP COIL TO DROP OUT WHEN C/B TRIPPED INITIALLY. TIGHT TIMING SEQUENCE TOLERANCE MAY BE PROB. DUE BY: 5/11/94
94072	W120	02/28/94	9403090195	SRXB: F. ORR	VASU WESTINGHOUSE PROVIDES FINAL REPORT ON EVALUATION OF SMALL BREAK LOCA/LOCTA-IV BURST & BLOCKAGE MODELS. CONCLUDES THAT PCT EFFECTS WILL NOT CREATE A SSE. SEE LOG# 91125/92115. DUE BY: 3/21/94
94073	PGE F236	03/12/94		EMEB: J.NORBERG	PACIFIC G&E/DIABLO CANYON 2 REPORTS MSSRV _s ARE AS MUCH AS 31 OUTSIDE THEIR NOMINAL SETPOINT DUE TO IMPROPER TESTING BY FURMANITE. SEE LOG# 94066/94069/94084. DUE BY: 3/21/94
94074	GPU R369	02/23/94		EMEB: M.HARTZMAN	GENERAL PUBLIC UTILITIES/TMI-1 PROVIDES UPDATE ON PROBLEM OF THERMOWELL STRESSES CALC TO EXCEED ASME PIPING CODE ALLOWABLES. REVIEW INDICATES B&W HAD DOCUMENT. TO SUPPORT DESIGN EXCEPTION FOR THE INSTRUMEN. SEE LOG#94045. DUE BY: 5/30/94
94075	CWE P070	03/09/94		RVIB:U.POTAPOVS	COMMONWEALTH EDISON REPORTS POSSIBILITY OF SOME PNEUMATIC CYLINDRS, USED AS SEC CONT DAMPER ACTUATORS, COULD FAIL DUE TO ADDITION OF AN ANTI-OXIDANT INSTEAD OF GREASE. VENDOR AWARE OF PROBLEM. DUE BY: 5/16/94

10 CFR PART 21 TRACKING SYSTEM

VENDOR INSPECTION BRANCH
DIVISION OF REACTOR INSPECTION AND LICENSEE PERFORMANCE

LOG #	SUB	REPORT	ACCESSION	ASSIGNED	CLOS	DESCRIPTION
	AND	DATE	NUMBER		OUT	
	VEND				CODE	
	CODE					
94076	BEC	03/14/94		EMEB: SCARBROUGH		BOSTON EDISON/PILGRIM 1 REPORTS FAILURE OF A HPCI/MOV IN CLOSED POSITION DUE TO SHEARING OF TORQUE SWITCH ROLL PIN IN SMB-0 ACTUATOR. EVALUATION UNDERWAY MAY BE RELATED TO PRIOR ROLL PIN FAILURES ON SMB-00 TORQUE SWITCHES. SEE LOG#90131.
	L200					
				DUE BY: 6/1/94		
94077	WEP	12/20/93	9312300171	RVID: K.NAIDU		WISCONSIN ELECTRIC POWER/POINT BEACH 1 REPORTS FAILURE OF WEST TYPE HFA 30-AMP MCCBS TO MEET TRIPPING TIME REQNTS & TO CLOSE DURING TESTING DUE TO AGE-RELATED GREASE SOLIDIFCTR IN TRIPPING MECHANISM. SEE IN 93-26.
	W120					
				DUE BY: 5/16/94		
94078	WEP	12/22/93	9401040256	RVID: K.NAIDU		WISCONSIN ELECTRIC POWER/POINT BEACH 1 REPORTS FAILURE OF STLO-2 RELAY IN STARTING CIRCUIT OF EDG DUE TO STICKY RESIDUE ON PLUNGER. FURTHER EVALUATION OF CAUSE UNDERWAY. RELAY MFGCTD BY SQUARE D CO.
	S345					
				DUE BY: 5/16/94		
94079	NYPA	12/01/93	9312080166	SRXB: G.SCHWENK	CTBI	NEW YORK POWER AUTHORITY/IP-3 REPORTS DISCREPANCY BETWEEN TECH SPEC & WEST ANALYSIS REGARDING 540F MINIMUM T-AVG FOR CRITICALITY. CAUSE ATTRIB TO PERSONNEL ERROR INVOLV MISJUDGEMENT & MISINTERPETATION OF INFO. SEE LOG# 93413.
	W120					
				DUE BY: 3/31/94		
94080	GPC	11/18/93	9311300065	RVID: K.NAIDU		GEORGIA POWER/VOGTLE EGP-2 REPORTS EXCESSIVE SENSITIVITY OF SPEED MONITOR FOR TURBINE-DRIVEN APW PUMP TO NOISE RIPPLES IN 125V DC POWER SUPPLY DUE TO OPERATION OF DC MO VALVES CAUSED TRIPPING OF PUMP.
	D245					
				DUE BY: 5/16/94		
94081	PGC	12/22/93	9401060376	RVID: G.CWALINA	LISU	PORTLAND GENERAL ELECTRIC/TROJAN PROVIDES SUPPLE INFO ON INAPPROPRIATE/DEGRADED SEALS IN CONTAINMENT ELEC PENE ASSEMBLIES. SEE LOG# 91073.
	P075					
				DUE BY: 5/16/94		
94082	CYA	01/03/94	9401140128	EMEB: SCARBROUGH		CONNECTICUT YANKEE APC/HADDAM NECK REPORTS MAIN FW ISOLATION MOVs MAY NOT BE ABLE TO CLOSE AGAINST DESIGN BASIS DIFF PRESS DUE TO USE OF NONCONSERV VALVE FACTORS BASED ON EPRI DATA. SEE LOG #94060/94065.
	L200					
	A391					
				DUE BY: 5/2/94		
94083	DPC	12/11/93	9312200202	SRXB: C.Y.LIANG		DUKE POWER/McGUIRE-3 REPORTS POSSIBILITY OF VAPOR BINDING OF RHR PUMPS DURING ACCIDENT CONDITIONS DUE TO LACK OF COOLING OF SUCTION PIPING. WEST ISSUED NSAL-93-004 & CONCLUDED ISSUE NOT REPORTABLE. POTENT AFTD PLANT IDENT.
	W120					
				DUE BY: 3/24/94		
94084	F236	03/16/94		EMEB: G.HAMMER		FURMANITE AMERICA PROVIDES IDENTIFICATION OF LICENSEES AFTD BY MEAN SEAT AREA CHANGE FOR MSSV TESTED/SET BY USING TREVITEST LIFT ASSIST DEVICE. SEE LOG#94066/94069/94073.
				DUE BY: 3/30/94		

10 CFR PART 21 TRACKING SYSTEM

VENDOR INSPECTION BRANCH
DIVISION OF REACTOR INSPECTION AND LICENSEE PERFORMANCE

LOG #	SUB	REPORT	ACCESSION	ASSIGNED	CLOS	DESCRIPTION
		AND DATE	NUMBER		OUT	
		VEND			CODE	
		CODE				
94085	C498	03/07/94	9403160145	RVIB: G.CWALINA VASU		COMPUTER PRODUCTS REPORTS RTP UNIVERSAL IN/OUT CONTROLLER INTER FACE CARD USED IN UIOC DOES NOT MEET ELEVATED OPERATING TEMP SPECS. CIRCUIT ANOMALIES CAN OCCUR ABOVE AMBIENT TEMP OF 90F. SEE LOG# 94088. AFTD LICENSEES NOTIFIED & CORR ACTION SPECIFIED.
				DUE BY: 5/17/94		
94086	HLP	03/17/94		SRXB: R.JONES		HOUSTON L&P/SOUTH TEXAS 2 REPORTS DETACHMENT OF BURNABLE POISON RODLETS. FASTENING LOCK NUTS SEEM TO BE MISSING. CAUSE NOT KNOWN. MAY AFFECT OTHER ROD ASSEMBLIES & RCCAs.
				DUE BY: 3/28/94		
94087	NOO7	03/17/94	9403180144	RVIB: R.FRAHM		NAMCO CONTROLS PROVIDES FURTHER INFO ON FAILURE OF OPERATING LEVERS TO RETURN TO INITIAL POSITION. CAUSE DUE TO ENLARGMENT OF O-RING BY LUBE OIL. O-RING MTL BEING CHECKED. SEE LOG# 94037/94056.
				DUE BY: 5/23/94		
94088	C498	03/07/94	9403160131	RVIB: G.CWALINA CTBI		COMPUTER PRODUCTS PROVIDES ADDTL INFO REGARDING AFFECTED LICENSEES FOR I/O CONTROLLER INTERFACE CARD NOT MEETING ELEVATED OPER TEMP SPEC. COMANCHE PEAK AFTD. SEE LOG# 94085.
				DUE BY: 5/23/94		
94089	PEG	03/21/94		EMCB:STROSNIDER		PUBLIC SERVICE E&G/HOPE CREEK 1 REPORTS CONDUCT OF CONTROL ROD BLADES INSPECTIONS PER ABB SERVICE LIFE GUIDELINES FOR CR-82 BLADES & FINDS 6 BLADES WITH CRACK INDICATIONS. BLADES REPLACED. SEE LOG# 91040 FOR PRIOR RESOLUTION.
				DUE BY: 3/29/94		
94090	X002	03/11/94	9403170240	RVIB: W.HAASS VASU		XOMOX CORP REPORTS POSSIBLE SUPPLY OF TUFLINE VALVES WITH DIAPHRAGM SEALS MADE OF LO DENSITY POLYETHYLENE RATHER THAN ULTRA HI MOLECULAR WT POLYETHYLENE. ALSO PARTS ORDERS FOR SEALS MAY BE AFTD. KNOWN CUST NOTIFIED.
				DUE BY: 5/23/94		
94091	PEG	12/30/93	9401110199	EMCB:STROSNIDER		PUBLIC SERVICE E&G/SALEM 2 PROVIDES INFO ON FAILURE OF FLANGE PORTION OF 3R CYLINDER LINER IN 2C EDG. FAILURE ATTRIB TO LACK OF FLANGE FLATNESS & PERPENDICULARITY, UNDERSIZED O-RING GROOVE, & POSSIBLE FLAW. DEDCTN PROCESS TO BE CORRECTED. SEE LOG#93449.
				DUE BY: 3/30/94		
94092	NEU	03/22/94		EMCB:STROSNIDER		NORTHEAST UTILITIES/MILLSTONE 1 REPORTS RECEIPT OF INFO FROM GE REGARDING REDUCTION OF EXPCTD SRVCE LIFE OF DURALIFE MODEL 120 &140 CONTROL RODS DUE TO CREVICE CORR CRACKING. RESULTS IN REDUCTION OF DEPLETION WORTH OF RODS. GE MAY ISSUE SIL.
				DUE BY: 3/30/94		
94093	HLP	11/18/93	9312010222	RVIB: K.NAIDU		HOUSTON L&P/SOUTH TEXAS 2 REPORTS AUTO-START OF STANDBY DG 21 DUE TO FAILURE OF TRANSISTOR CAUSING DEGRADATION OF VARISTORS. VARISTORS ARE MODEL 68D100000 & TRANSISTORS ARE TYPE 2N3439 HI VOLT SILICON NPN.
				DUE BY: 5/23/94		

10 CFR PART 21 TRACKING SYSTEM

VENDOR INSPECTION BRANCH
DIVISION OF REACTOR INSPECTION AND LICENSEE PERFORMANCE

LOG #	SUB REPORT AND DATE VEND CODE	REPORT AND DATE	ACCESSION NUMBER	ASSIGNED	CLOS DESCRIPTION OUT CODE
94094	L200	03/23/94	9403280164	EMEB: J. NORBERG	LIMITORQUE CORP REPORTS THAT LICENSEES HAVE EXPERIENCED TORQUE SWITCH FAILURES IN SMB/SB/SBD 0,2,3,4,4T,5,5T & 5XT VALVE ACTUATORS DUE TO ROLL PIN SHEARING. SUGGEST UTILITY TASK FORCE BE FORMED TO PERFORM ROOT CAUSE ANALYSIS.
				DUE BY: 3/31/94	
94095	NBP K182	03/24/94		RVIB: G.CWALINA	NORTHERN STATES POWER/MONTICELLO 1 REPORTS POOR CORRELATION BETWEEN MAGNETIC TRIP DIAL SETTING & ACTUAL TRIP SETPOINT FOR CLASS 1E KLOCKNER MOELLER MCCB, MODEL ZM6-33-200.0B1-CNA PURCH IN 1982. OTHERS OF SAME VINTAGE SBOWED SIMILAR BEHAVIOR.
				DUE BY: 5/25/94	
94096	GPC S390	03/24/94		EMEB: J. NORBERG	GEORGIA POWER/HATCH 2 REPORTS FAILURE OF AXLE ON A REFUELING BRIDGE CRANE CAUSING A WHEEL TO FALL OFF. ONE QUADRANT OF BRIDGE DROPPED 2". LICENSEE PLANS TO REPLACE C/S AXLES WITH S/S ONES.
				DUE BY: 4/1/94	
94097	ENOP B015	03/24/94		EMCB: STROSNIDER	ENTERGY OPERATIONS/WATERFORD 3 REPORTS FAILURE OF AN INCONEL 690S/G PLUG THAT WAS INSTALLED IN 1991. SIMILAR PLUG RECENTLY FAILED AT SO TEXAS PROJECT. THESE PLUGS REPLACED PREV USED INCONEL 600 PLUGS.
				DUE BY: 4/1/94	
94098	PGE U069	02/08/93	9302180070	RVIB: W. HAASS	INIS PACIFIC G&E/DIABLO CANYON 1 REPORTS UNPLANNED MAIN TURBINE LISU ACCELERATION DURING SHUTDOWN OPERATIONS PARTIALLY DUE TO STICKING OF PS-22B AUTO STOP PRESS SWITCH RESULTING FROM GALVANIC CORR. PRESS SWITCHES REPLACED & CONTROL SYS REDESIGNED. IN 94-11 ISSUED.
				DUE BY: 5/31/94	
94099	C503 PEG M302	03/02/94	9403100324	RVIB: R. WILSON	COMSIP, INC (NOW CEGELEC AUTOMATION) PROVIDES CLARIFYING INFO REGARDING QUALIFIED LIFE DEFICIENCY OF PTW-5300DC MICROSWITCHES. SEE LOG# 93323.
				DUE BY: 5/31/94	
94100	MYA G080	03/28/94		RVIB: G.CWALINA	MAINE YANKEE AP/MAINE YANKEE 1 REPORTS FAILURE OF HPSI C/B TO CLOSE DURING TESTING DUE TO PARTIAL DETACHMENT OF LIMIT SWITCH FROM ADJACENT UPPER SWITCH. MOUNTING SCREW NOT PROPERLY FASTENED. RECENT GE OVERHAUL ONSITE MAY BE INVOLVED.
				DUE BY: 5/31/94	
94101	B455 P297 LPL	03/16/94	9403280205	RVIB: B. ROGERS	ABB COMB ENG EXPANDS THE AFFECTED LOT OF MOTOR-DRIVEN RELAYS TO INCLUDE THOSE WITH DATE CODES OF 9232 TO 9349. LICENSEE HAS BEEN INFORMED. SEE LOG# 93469.
				DUE BY: 5/31/94	
94102	SCC M040	03/11/94	9403280195	RVIB: G.CWALINA	SOUTH CAROLINA E&G/SUMMER REPORTS INABILITY TO VERIFY SEISMIC QUALIFICATION OF LEVEL SWITCHES THAT PROVIDE AUTO CONTROL OF FUEL OIL DAY TANK LEVEL. SWITCHES REPLACED WITH SEISMICALLY QUAL ONES.
				DUE BY: 5/31/94	

10 CFR PART 21 TRACKING SYSTEM

VENDOR INSPECTION BRANCH
DIVISION OF REACTOR INSPECTION AND LICENSEE PERFORMANCE

LOG #	SUB REPORT AND DATE VEND CODE	ACCESSION NUMBER	ASSIGNED	CLOS OUT CODE	DESCRIPTION
94103	ENOP 03/29/94 A499 G080		RVIB: PETROSINO		ENERGY OPERATIONS/GRAND GULF 1 REPORTS SLOW CONTROL ROD DRIVE SCRAM TIMES 49 OF 176 WERE SLOW. ALL WERE REPLACED IN NOV 1993 DURING OUTAGE. SOV8 BEING REPLACED. DUE BY: 5/31/94
94104	WFP 03/30/94 G080		RVIB: PETROSINO		WASHINGTON PUBLIC POWER/WNP-2 REPORTS CONTROL ROD FAILURE TO SCRAM AND OTHERS TO INSERT SLOWLY DUE TO BUNA-N RUBBER DIAPHRAGM INSOLENOID PILOT VALVE FAILURE. FAILURE OF DIAPHRAGM ATTRIBUTED TO THERMAL AGING/EMBRITTEMENT. SEE IN 78-14 & GE SILS. DUE BY: 5/31/94
94105	HLP 03/01/94 W120		RSXB: T. COLLINS		HOUSTON L&P/SOUTH TEXAS 1/2 REPORTS ERROR IN CALS FOR INITIATION OF HOT LEG RECIRC AS DETERMINED BY WEST. MAX TIME TO INITIATE RECIR REDUCED FROM 10.5 TO 6.5 HRS. TECH SPEC CHANGES MADE TO INCREASE BORON CONCS TO COMPENSATE. DUE BY: 4/7/94

Addressees - Memorandum dated 4/1/94

Luis A. Reyes, Acting Associate Director, ADPR
Ashok C. Thadani, Associate Director, ADT
Charles E. Rossi, Director, DRIL
Brian K. Grimes, Director, DORS
Brian W. Sheron, Director, DE
Martin J. Virgilio, Acting Director, DSSA
Frank J. Congel, Director, DRSS
Jack W. Roe, Director, DRPW
Steven A. Varga, Director, DRPE
Dennis M. Crutchfield, Associate Director, ADAR
Jack R. Strosnider, Branch Chief, EMCB
James A. Norberg, Branch Chief, EMEB
Goutam Bagchi, Branch Chief, ECGB
Jared S. Wermiel, Branch Chief, HICB
Carl H. Berlinger, Branch Chief, EELB
Conrad E. McCracken, Branch Chief, SPLB
Timothy E. Collins, Acting Branch Chief, SRXB
Alfred E. Chaffee, Branch Chief, OEAB
Kathy Gray, OEAB/NRR
Andrew J. Kugler, Acting Branch Chief, OGCB
Gregory Cwalina, Section Chief, RIS-2, VIB
Eugene V. Imbro, Branch Chief, RSIB
James W. Johnson, Acting Branch Chief, SPSB
Lemoine Cunningham, Branch Chief, PSRPB
Anthony T. Gody, Branch Chief, ILPB
Donald R. Haverkamp, Chief, TSS, Region I
Ellis W. Merschoff, Director, DRP, Region II
Stephen J. Vias, Chief, TSS, Region II
Robert A. Hasse, Chief, TSS, Region III
A. Bill Beach, Director, DRSS, Region IV
Stuart A. Richards, Acting Director, DRSP, Region V
R. Lee Spessard, Director, DOA/AEOD
Gary M. Holahan, Director, DSP/AEOD
Scott F. Newberry, Branch Chief, PDLR
Richard J. Barrett, Branch Chief, SCSB