

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | A | R | A | N | O | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

7 8 9 14 15 25 26 30 37 38 39 40 41 42 43 44 45 46 47 48 49

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

CON'T

0 1 | L | 0 | 5 | 0 | 0 | 0 | 3 | 1 | 3 | 7 | 0 | 8 | 1 | 7 | 8 | 2 | 8 | 0 | 9 | 1 | 0 | 8 | 2 | 9

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On 8/17/82 while at 6% full power, the condensate storage tank (T-41)

0 3 | level decreased to 15.25 feet which is less than the T.S. 3.4.1.3 limit

0 4 | of 16.3 feet. Use of the condensate storage tank water was limited, and

0 5 | generation of make-up water for the tank was initiated. The service water

0 6 | system was operable and available as a redundant water supply. This oc-

0 7 | currence is reportable per T.S. 6.12.3.2.b. A similar occurrence was

0 8 | reported in LER-78-027.

7 8 9 80

0 9 | W | F | 11 | A | 12 | A | 13 | Z | Z | Z | Z | Z | Z | 14 | Z | 15 | Z | 16

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE

17 LER-RO REPORT NUMBER 21 EVENT YEAR 22 23 24 SEQUENTIAL REPORT NO. 27 ATTACHMENT SUBMITTED 28 OCCURRENCE CODE 29 30 REPORT TYPE 31 32 REVISION NO.

18 ACTION TAKEN 33 19 FUTURE ACTION 34 20 EFFECT ON PLANT 35 21 SHUTDOWN METHOD 36 22 HOURS 37 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

40 41 42 43 44 45 46 47

ATTACHMENT SUBMITTED NPHD-4 FORM SUR PRIME COMP SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | During plant start-up, an abnormally high condensate demand resulted from

1 1 | end-of-cycle dilution requirements, start-up boiler operation, and multiple

1 2 | condensate polisher regenerations occurring simultaneously. Supplementary

1 3 | condensate makeup is available from a contractor's temporary auxiliary

1 4 | equipment, but the contractor's equipment was not in service prior to the

(Continued on Attachment)

Operator Observation

7 8 9 80

1 5 | C | 28 | 0 | 0 | 0 | 6 | 29 | N/A | 30 | A | 31 | Operator Observation | 32

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

1 6 | Z | 33 | Z | 34 | NA | 35 | NA | 36

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

ACTIVITY RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

1 7 | 0 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

1 8 | 0 | 0 | 0 | 0 | 40 | NA | 41

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

PERSONNEL INJURIES NUMBER DESCRIPTION

1 9 | Z | 42 | NA | 43

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

2 0 | N | 44 | NA | 45

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

PUBLICITY ISSUED DESCRIPTION NRC USE ONLY

LER NO. 50-313/82-019/03L-0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (CONTINUED)

occurrence. Due to high simultaneous condensate usage rates, the decreasing tank level was not discovered in time to prevent tank level from decreasing below the Technical Specification limit. Immediately following noting the out-of-specification condition, the contractor's water production was initiated assisting in restoring tank level. The shift supervisors were instructed to ensure that the water generation contractor be available during plant heatup and startup.