

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | 1 | L | Q | A | D | 1 | 2 | 0 | 0 | 0 | - | 0 | 0 | 0 | - | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

CON'T
01 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 5 | 4 | 7 | 0 | 8 | 2 | 6 | 8 | 2 | 8 | 0 | 9 | 0 | 9 | 8 | 2 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | On August 26, 1982, at 0055 hours, the I-1001-65D Residual Heat Removal System (RHRS) Service Water Pump was removed from service to repair (preventative maintenance) the I-1001-188D RHR room cooler isolation valve. The valve was becoming stiff and difficult to operate. This did not affect the operation of the RHR Service Water Pump. All surveillances, as required by Technical Specification 3.5.B.2 were successfully performed prior to the removal of the I-1001-65D pump. This RHRS Service Water Pump is one of two 100% redundant pumps, thus there were no safety implications associated with this occurrence.

09 | SYSTEM CODE | C | F | 11 | CAUSE CODE | X | 12 | CAUSE SUBCODE | Z | 13 | COMPONENT CODE | P | U | M | P | X | X | 14 | COMP SUBCODE | B | 15 | VALVE SUBCODE | Z | 16 | LER-RO REPORT NUMBER | 17 | EVENT YEAR | 8 | 2 | 21 | 22 | SEQUENTIAL REPORT NO. | 0 | 2 | 4 | 23 | 24 | OCCURRENCE CODE | 0 | 3 | 27 | 28 | REPORT TYPE | L | 30 | REVISION NO. | 0 | 32 | ACTION TAKEN | B | 18 | FUTURE ACTION | Z | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 22 | ATTACHMENT SUBMITTED | N | 23 | NRC-4 FORM SUB | N | 24 | PRIME COMP. SUPPLIER | N | 25 | COMPONENT MANUFACTURER | 1 | 0 | 7 | 5 | 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The ID RHRS Service Water Pump was removed from service to perform preventative maintenance on an associated room cooler isolation valve. Following the completion of this maintenance, the ID RHRS Service Water Pump was returned to service by 1145 hours on August 26, 1982. No operability tests were run on the ID RHRS Service Water Pump after this maintenance because the valve maintenance did not affect operation of the pump.

15 | FACILITY STATUS | E | 28 | % POWER | 0 | 5 | 5 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | B | 31 | DISCOVERY DESCRIPTION | Operator Observation | 32

16 | ACTIVITY CONTENT | Z | 33 | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36

17 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | NA | 39

18 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41

19 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43

20 | PUBLICITY ISSUED DESCRIPTION | N | 44 | 8209240337 820909 PDR ADOCK 05000254 PDR

NAME OF PREPARER C. Brown PHONE 309-654-2241, ext. 188