

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | V | A | S | P | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5  
6 9 14 15 25 26 30 37 44 51 58 65 72 79 86

CONT  
01 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 8 | 0 | 7 | 0 | 8 | 2 | 4 | 8 | 2 | 8 | 0 | 9 | 2 | 1 | 8 | 2 | 9  
6 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
012 | On August 24, post reactor trip specific activity samples of the reactor coolant  
013 | system indicated a dose equivalent I-131 level greater than the T.S.3.1.D.3 limit.  
014 | Since the RCS average temperature was reduced to less than 500°F and the integrity  
015 | of the steam generator tubes was maintained, the health and safety of the public  
016 | were not affected. This event is reportable per T.S.6.6.2.b(2) and the special  
017 | reporting requirements of T.S.3.1.D.4.

09 | R | C | 11 | E | 12 | C | 13 | F | U | E | L | I | X | X | 14 | Z | 15 | Z | 16  
9 10 11 12 13 18 19 20  
17 | 8 | 2 | 21 | 0 | 8 | 5 | 26 | 0 | 3 | 28 | L | 30 | 0 | 32  
21 22 23 24 25 26 27 28 29 30 31 32  
18 | X | 19 | C | 20 | Z | 21 | 0 | 0 | 0 | 0 | 40 | Y | 23 | N | 24 | N | 25 | W | 1 | 2 | 0 | 26  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
10 | The event was caused by fuel defects in the reactor core. Post trip conditions  
11 | enhanced the release of fission products to the reactor coolant system, resulting  
12 | in an Iodine Spike. RCS temperature was reduced below 500°F until the I-131 was  
13 | less than the T.S.3.1.D.3 limit. An accelerated sampling frequency was implemented  
14 | until RCS specific activity returned to less than the T.S.3.1.D.2 limit.

15 | G | 28 | 0 | 0 | 0 | 29 | N/A | C | 31 | Post trip Chemistry Sample  
9 10 12 13 44 45 46 80

16 | Z | 33 | Z | 34 | N/A | N/A | 36  
9 10 11 44 45 80

17 | 0 | 0 | 0 | 37 | Z | 38 | N/A | 39  
9 11 12 13 80

18 | 0 | 0 | 0 | 40 | N/A | 41  
9 11 12 80

19 | Z | 42 | N/A | 43  
9 11 12 80

20 | N | 44 | N/A | 45  
9 10 80

ATTACHMENT 1  
SURRY POWER STATION, UNIT NO. 1  
DOCKET NO: 50-280  
REPORT NO: 82-085/03L-0  
EVENT DATE: 08-24-82

TITLE OF THE EVENT: High Dose Equivalent I-131 in RCS

1. DESCRIPTION OF THE EVENT:

On August 24, 1982 at 1715 hours, following a reactor trip from 100% power, the specific activity sample of the reactor coolant showed a peak dose equivalent I-131 level of 10.53 microcuries/cc. From 1415 hours on 8/24/82 until 2325 hours on 8/25/82, the dose equivalent I-131 exceeded the T.S.3.1.D.2 limit of < 1.0 microcuries/cc., and exceeded the 10 microcuries/cc limit of T.S.3.1.D.3 from 1520 hours until 2115 hours on 8/24/82. This event is reportable per T.S.6.6.2.b(2) and the special reporting requirements of T.S.3.1.D.4.

2. PROBABLE CONSEQUENCES and STATUS of REDUNDANT EQUIPMENT:

The limitations on the specific activity of the primary coolant ensure that the resulting 2 hour dose at the site boundary will not exceed an appropriately small fraction of the 10 CFR 100 limits following a postulated steam generator tube rupture. With the specific activity of the reactor coolant greater than 10 microcuries/cc., the reactor was shut down and the RCS cooled to less than 500<sup>0</sup>F within the time span specified in Tech. Specs. When the specific activity fell to less than 10 microcuries/cc., the reactor coolant gross activity was below the value analyzed in the FSAR for a tube rupture and 1% failed fuel. Therefore, the health and safety of the public were not affected.

3. CAUSE of the EVENT:

The Iodine Spike was caused by known, but not specifically located, fuel element defects in the reactor core. Post trip conditions enhanced the release of fission products, specifically I-131. This caused an increase of the reactor coolant specific activity level.

4. IMMEDIATE CORRECTIVE ACTION:

The immediate corrective action was to implement the actions required by T.S. Table 4.1-2B. Specifically, the level of the dose equivalent I-131 was monitored every four hours until the level returned to less than 1.0 microcurie/cc.

5. SUBSEQUENT CORRECTIVE ACTION:

The RCS was cooled and maintained at less than 500<sup>0</sup>F until the dose equivalent I-131 dropped below 10 microcuries/cc.

6. ACTIONS TAKEN TO PREVENT RECURRENCE:

The specific activity of the reactor coolant will continue to be monitored as required by T.S. Table 4.1-2B.

7. GENERIC IMPLICATIONS:

None.

SUPPLEMENTAL INFORMATION:

The supplemental information as required by T.S.3.1.D.4 "Special Report" is included as follows:

1. Reactor Power history 48 hours prior to these events:

August 22, 1982	24 hours at 100% power
August 23, 1982	24 hours at 100% power
August 24, 1982	1315 hours - Reactor trip and Safety Injection

2. Fuel burnup by core region as of August 24, 1982:

FUEL BATCH:	4A: 23,761 MWD/MTU
	6B: 22,473 MWD/MTU
	4C: 29,855 MWD/MTU
	6C: 32,802 MWD/MTU
	7A: 23,543 MWD/MTU
	7B: 28,829 MWD/MTU
	8A: 14,570 MWD/MTU
	8B: 12,256 MWD/MTU
CYCLE 6 BURNUP:	11,695 MWD/MTU

3. Prior to the trip, the letdown flowrate had been established at 111 gpm.
4. De-gassing operations were not being performed.
5. Duration of I-131 spike:

August 24, 1982:	0835 hours - Pre Trip Sample 0.138 microcuries/cc.
	1415 hours - Post Trip Sample 5.76 microcuries/cc.
	1520 hours - Post Trip Sample 10.04 microcuries/cc.
	1715 hours - Post Trip Sample 10.53 microcuries/cc.
	1915 hours - Post Trip Sample 10.06 microcuries/cc.
	2018 hours - RCS Temperature less than 500°F.
	2115 hours - Post Trip Sample 7.97 microcuries/cc.
	2215 hours - Post Trip Sample 7.35 microcuries/cc.
	2245 hours - Commenced heat up of RCS temperature to 520°F.
	2315 hours - Post Trip Sample 7.16 microcuries/cc.

5. Duration of I-131 Spike (continued)

August 25, 1982:      0315 hours - Post Trip Sample 6.04 microcuries/cc.  
                          0723 hours - Post Trip Sample 4.70 microcuries/cc.  
                          1115 hours - Post Trip Sample 2.85 microcuries/cc.  
                          1255 hours - Post Trip Sample 2.41 microcuries/cc.  
                          1525 hours - Post Trip Sample 1.80 microcuries/cc.  
                          1925 hours - Post Trip Sample 1.05 microcuries/cc.  
                          2325 hours - Post Trip Sample 0.785 microcuries/cc.

The dose equivalent I-131 level was greater than 10 microcuries/cc for approximately 6 hours. Total duration of the iodine spike was 33 hours, 10 minutes. RCS temperature was less than 500<sup>0</sup>F for 2 hours, 27 minutes during the spike.