LICENSEE EVENT REPORT

	CONTROL BLOCK: [] [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	O H D B S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 57 CAT 58 5
CON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 3 4 6 7 0 8 2 3 8 2 8 0 9 2 1 8 2 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	(NP-33-82-45) On August 23, 1982, during the performance of ST 5074.01, operations
0 3	personnel attempted to start CCW Pump 1-3. The circuit breaker installed in cubicle
0 4	AD108 did not close, the pump did not start, and the station entered the action state-
0 5	ment of Technical Specification 3.7.3.1. CCW Pump 1-2 was started and the station
0 6	was removed from the action statement. There was no danger to the health and safety
07	of the public or to station personnel. The redundant CCW train was fully operational.
08	80
09	SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
	SEQUENTIAL OCCURRENCE REPORT NO. LERIRO EVENT YEAR REPORT NO. OCCURRENCE REPORT TYPE NO. OCCURRENCE REPORT TYPE NO.
	NUMBER 21 22 23 24 26 27 28 29 30 31 32 ACTION FUTURE EFFECT SHUTDOWN COMPONENT SORNALIS SUBSTITUTE SUBSTITUTE SORNALIS SUBSTITUTE SUBSTITUTE SORNALIS SUBSTITUTE SUB
[1]0	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The circuit breaker in cubicle AD108 would not stay closed and was tripping free. An
	interlock in the breaker control circuitry would not allow the breaker to remain
	a closed because of an adjustment between the floor closing interlock lever and the
1 2	This can was adjusted per MWO 82-2241. This adjustment will be
1 3	checked on all breakers when racking in per Revision 1 to Maintenage Instruction
7 8	FACILITY SOUND OTHER STATUS (30) METHOD OF DISCOVERY DESCRIPTION (32)
1 5	C 28 0 0 0 29 NA A 44 45 46 During the performance of ST 5074.01.
1 6	ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36 NA
7 8	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
1 7	9 PERSONNEL INJURIES 13 80
1 8	NUMBER DESCRIPTION (41) NA DESCRIPTION (41) NA
	8 9 11 12 LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION (43)
1 9	B209300343 B20921 PDR ADDCK 05000346
2 0	PU LICITY S PDR NRC USE ONLY ISSUED DESCRIPTION (45) PDR

TOLEDO EDISON COMPANY DAVIS-BESSE NUCLEAR POWER STATION UNIT ONE SUPPLEMENTAL INFORMATION FOR LER NP-33-82-45

DATE OF EVENT: August 23, 1982

FACILITY: Davis-Besse Unit 1

IDENTIFICATION OF OCCURRENCE: Failure of 4160 VAC circuit breaker AD108.

Conditions Prior to Occurrence: The unit was in Mode 3 with Power (MWT) = 0 and Load (Gross MWE) = 0.

Description of Occurrence: During the performance of the Component Cooling Water (CCW) Monthly Surveillance Test ST 5074.01, which involved the racking in and out of breakers, operations personnel attempted to start CCW Pump 1-3. The circuit breaker installed in cubicle AD108 did not close, the pump did not start, and the station entered the action statement of Technical Specification 3.7.3.1. CCW Pump 1-2 was started immediately, and the station was removed from the action statement.

Designation of Apparent Cause of Occurrence: The apparent cause of this occurrence was an interlock in the breaker control circuitry which would not allow the breaker to remain closed because of an adjustment between the floor closing interlock lever and the closing trigger.

Analysis of Occurrence: There was no danger to the health and safety of the public or to station personnel. The redundant CCW train was fully operational.

Corrective Action: The gap between the floor closing interlock lever and the closing trigger was adjusted per Maintenance Work Order 82-2241. The breaker was racked in and cycled numerous times prior to declaring it operable on August 30, 1982. This adjustment which is sensitive to the number of times the breaker is racked in and out, will be checked on all breakers when racking in per Revision 1 to Maintenance Instruction E-80.

Failure Data: Previous occurrences of a CCW pump failing to start due to a breaker problem were reported in Licensee Event Reports NP-33-79-144 (79-124) and NP-33-82-07 (82-006).

LER #82-040