	LICENSEE EVENT REPORT
4	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	N J S G S 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5.
CON'T 0 1 7 8	SOURCE L 6 0 5 0 0 0 3 1 1 7 0 8 3 1 8 2 8 0 9 1 6 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2	On August 31, 1982, radiography surveillance revealed that the disc was not in place
0 3	in Valve 21 MS46, a check valve in the steam line to No. 23 Auxiliary Feedwater Pump
0 4	(AFP). No. 23 AFP was declared inoperable and Action Statement 3.7.1.2a was entered
0 5	at 1724 hours.
0 6	
07	
08	9 SYSTEM CAUSE CAUSE COMP VALVE
0 9	CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
	TO REPORT NUMBER 2 23 23 24 25 27 26 27 26 27 26 27 28 28 29 29 29 29 29 29 29 29 29 29 29 29 29
	ACTION FUTURE SEFECT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. SUPPLIER WANUFACTURER V 0 8 5 26 37 40 41 23 42 43 43 45 44 47
10	The stud which attaches the valve disc to the hanger had sheared off. The hanger
11	and disc assembly were replaced and the valve was tested satisfactorily. No. 23 AFP
1 2	was declared operable and Action Statement 3.7.1.2a was terminated at 0045 hours,
13	September 3, 1982. An engineering analysis is being conducted.
7 8	80
1 5	ACILITY DISCOVERY DESCRIPTION 32 E 28 0 8 2 29 NA C 31 Radiographic Surveillance
	LEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
7 8	Z 33 Z 34 NA
1 7	NUMBER O O O O O O O O O O O O O O O O O O O
1 8	PERSONNEL INJURIES NUMBER DESCRIPTION 41
1 9	LOSS OF OR DAMAGE TO FACILITY 43 B210010047 B20916 PDR ADDCK 05000311 PDR PDR
8	PUBLICITY SSUED DESCRIPTION 45 NRC USE ONLY
2 0	N (44) NA S S S S S S S S S S S S S S S S S S
	NAME OF PREPARER R. Heller PHONE 609/935-6000 Ext 3078