## LICENSEE EVENT REPORT

	EICENSEE EVENT HEFORT
	CONTROL BLCCK:           (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	N J S G S 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 1 6 5 CAT 58
O 1 8	SOURCE   1 6 0 5 0 0 0 3 1 1 0 0 8 3 1 8 2 8 0 9 1 6 8 2 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2	At 1835 hours, August 31, 1932, the Control Room Operator received indication of
03	low service water flow on No. 23 Containment Fan Coil Unit (CFCU). No. 23 CFCU was
0 4	declared inoperable and Action Statement 3.6.2.3a was entered at 1835 hours.
0 5	
0 6	
0 7	
08	1 80
0 9	SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
	LER RO REPORT NO.  17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 31 32 32 32 32 32 32 32 32 32 32 32 32 32
[1]2]	The cause was silt build up in the cooling coils. The flow control valve was cycled
111	and the CFCU tested satisfactorily. No. 23 CFCU was declared operable and Action
1 2	Statement 3.6.2.3a was terminated at 1022 hours, September 1, 1982.
13	
14	<u> </u>
	STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 B 31 Routine Surveillance
	STIVITY CONTENT 12 13 44 45 46 LOCATION OF RELEASE 36
7 8	Z (33) Z (34) NA
1 7	NUMBER   TYPE   DESCRIPTION (39)
1 8	PERSONNEL INJURIES NUMBER DESCRIPTION 41  d ol ol 0 NA
1 9	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION  Z 42 NA
7 8	PUBLICITY   45   PDR   ADOCK 05000311   NRC USE ONLY   SSUED   DESCRIPTION   45   PDR   ADOCK 05000311   PDR     10   68   69   80   5   69   69   69   69   69   69   609   69   6