



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401-1927
Telephone (612) 330-5500

October 1, 1990

10 CFR Part 50
Section 50.73

Director of Nuclear Reactor Regulation
U S Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket Nos. 50-282 License Nos. DPR-42
50-306 DPR-60

Inadvertent Mispositioning of the Control Switch
of 11 Shield Building Ventilation Heater Control

The Licensee Event Report for this occurrence is attached.

Please contact us if you require additional information related to this event.

Thomas M Parker
Manager
Nuclear Support Services

c: Regional Administrator - Region III, NRC
NRR Project Manager, NRC
Senior Resident Inspector, NRC
MPCA
Attn: Dr J W Ferman

Attachment

9010120158 901001
PDR ADOCK 05000282
S FDC

IE22
11

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (F-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555 AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) **Prairie Island Nuclear Generating Plant Unit 1** DOCKET NUMBER (2) **0 5 0 0 0 2 8 2** PAGE (3) **1 OF 0 4**

TITLE (4) **Inadvertent Mispositioning of the Control Switch of 11 Shield Building Ventilation Heater Control**

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0 8	3 0	9 0	9 0	0 1 3	0 0	1 0	0 1	9 0	Prairie Island Unit 2		0 5 0 0 0 3 0 6
											0 5 0 0 0

OPERATING MODE (9) **N**

POWER LEVEL (10) **1 0 0**

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)

<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.406(a)	<input type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)
<input type="checkbox"/> 20.406(a)(1)(iii)	<input type="checkbox"/> 50.38(a)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(a)
<input type="checkbox"/> 20.406(a)(1)(ii)	<input type="checkbox"/> 50.38(a)(2)	<input type="checkbox"/> 50.73(a)(2)(vi)	<input type="checkbox"/> OTHER (Specify in Abstract below and in Text, NRC Form 266A)
<input type="checkbox"/> 20.406(a)(1)(iii)	<input checked="" type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)	
<input type="checkbox"/> 20.406(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)	
<input type="checkbox"/> 20.406(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)

NAME **Arre A Hunstad** TELEPHONE NUMBER **6 1 2 3 8 8 - 1 1 2 1**

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS

SUPPLEMENTAL REPORT EXPECTED (14) YES (If yes, complete EXPECTED SUBMISSION DATE) NO

EXPECTED SUBMISSION DATE (15) MONTH DAY YEAR

ABSTRACT (Limit to 1400 words, i.e., approximately fifteen single-space typewritten lines) (16)

On August 30, 1990, Unit 1 was at 100% power. Surveillance procedure SP1172, Ventilation System Monthly Operation, was in progress. During the test, at 1804, the control room operator noticed that the monitor light indicating proper operation of No. 11 Shield Building Vent Filter Heater was not lit. Investigation showed that the local control switch for the heater was in the OFF position. The switch was immediately returned to the ON position.

It is known that the switch was in its proper position on August 22, so the heater could have been inoperable for 8 days. From the investigation of the event, it is concluded that the switch was moved inadvertently and unknowingly by a workman in the area.

Corrective action will include the installation of protective covers over this switch and those with similar function to prevent inadvertent operation.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (F-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Prairie Island Unit 1	DOCKET NUMBER (2) 0500028290	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		90	013	0	02	OF 04

TEXT (if more space is required, use additional NRC Form 305A's) (17)

EVENT DESCRIPTION

On August 30, 1990, Unit 1 was at 100% power. Surveillance procedure SP1172, Ventilation System Monthly Operation, was in progress. During the test, at 1804, the control room operator noticed that the monitor light indicating proper operation of No. 11 Shield Building Vent Filter Heater was not energized. Investigation showed that the local control switch (EIIS Component Identifier HS) for the heater was in the "OFF" position. The switch was immediately returned to the "ON" position.

It is known that the switch was in its proper position on August 22, 1990, so the heater could have been inoperable for 8 days.

CAUSE OF THE EVENT

Investigation of work records showed that no work was done on the system which would have resulted in changing the switch position.

A search of the component tagging record system showed that no equipment control tags were issued for this switch.

The switch position is not changed as part of any routine operations procedures.

Personnel who would have had a reason to be in the area were interviewed; no one was aware of repositioning of the switch.

A change in switch position is not annunciated, so inadvertent movement would not be noticed by local operators or control room operators.

From the above investigation, it is concluded that the switch was moved inadvertently and unknowingly by a workman in the area.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Prairie Island Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 2 8 2	LER NUMBER (3)			PAGE (3)	
		YEAR 9 0	SEQUENTIAL NUMBER 0 1 3	REVISION NUMBER 0 0	0 3	OF 0 4

TEXT (if more space is required, use additional NRC Form 305A's) (17)

ANALYSIS OF THE EVENT

If a Safety Injection Signal had been actuated, both trains of the Shield Building Ventilation System would have started automatically, but the heater for one train of filtration would not have been energized. The heater is used to maintain relative humidity below 70% as air is drawn through the filter. With the heater off, the charcoal filter would have lost some of its effectiveness in removing iodine. The heater was not capable of performing its related support function; therefore, one train of the Shield Building Ventilation System was inoperable. The redundant train was operable.

Prairie Island Technical Specification 3.6.H.1 requires both Shield Building Ventilation System trains to be operable when reactor coolant system temperature is above 200°F. Technical Specification 3.6.H.2 allows one train of Shield Building Ventilation System to be inoperable up to seven days. Conservatively assuming that the filter heater control switch was off for the entire period of 8 days, this Technical Specification was violated. Therefore, this event is reportable pursuant to 10CFR50.73(a)(2)(i)(B).

Assuming a reduced iodine removal efficiency for the charcoal filter, a preliminary evaluation was performed. This evaluation concluded that the site boundary dose (0-2 hours) and the low population zone dose (0-30 days) would have been less than the 10 CFR Part 100 guidelines in the event of a LOCA. A more detailed evaluation will be performed to verify these results. This evaluation will be completed by November 30, 1990.

CORRECTIVE ACTION

Upon discovery, the switch was returned to the "ON" position and the heater verified to be energized. Switches in similar applications (7 others) were inspected and found to be in their proper positions.

An investigation was begun immediately, and an independent investigation was undertaken by the plant's Error Reduction Task Force.

Protective covers will be installed over the 8 switches to prevent inadvertent operation. Until that time, daily verification of proper switch position is being done.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20545, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Prairie Island Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 2 8 2 9 0	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		9 0	0 1 3	0 0	0 4	OF 0 4

TEXT (if more space is required, use additional NRC Form 306A's) (17)

FAILED COMPONENT IDENTIFICATION

None.

PREVIOUS SIMILAR EVENTS

There have been other instances of inadvertent switch operation, but none reported on this system.