

LICENSEE EVENT REPORT

CONTINUE

CONTROL BLOCK: 01361711210

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1	P	I	A	B	V	S	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4	D	5
7	6	8	LICENSEE CODE	14	15	LICENSE NUMBER	25	26	28	LICENSE TYPE	30	32	CAT	58													

7/14
5/4

0 1	REPORT SOURCE	L	6	0	5	0	0	0	3	3	4	7	0	2	1	1	9	8	1	8	0	3	2	0	8	1	9
7	8	40	81	DOCKET NUMBER	48	69	EVENT DATE	74	75	REPORT DATE	80																

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During power operation, the results of a surveillance test at 1100 hours indicated reactor coolant leakage of 2.09 gpm. A subsequent test at 1410 hours indicated leakage of 1.62 gpm. The source of the leak was identified as the valve packing on Loop A Hot Leg RTD Manifold Outlet Isolation Valve [RC-20]. The plant was placed in Hot Standby within 6 hours in accordance with Technical Specification 3.4.6.2. The health and safety of the general public were not jeopardized since the leakage was contained within the containment building.

7	8	9	SYSTEM CODE	C	B	11	CAUSE CODE	E	12	CAUSE SUBCODE	B	13	COMPONENT CODE	V	A	L	V	E	X	14	COMP. SUBCODE	F	15	VALVE SUBCODE	D	J	16			
17	LER/RO REPORT NUMBER	8	1	21	22	23	SEQUENTIAL REPORTING NO.	0	2	8	24	25	OCCURRENCE CODE	0	1	3	28	29	REPORT TYPE	L	30	REVISION NO.	0	32	COMPONENT MANUFACTURER	E	10	9	5	26
33	ACTION TAKEN	F	18	Z	19	A	20	A	21	36	37	38	HOURS	0	0	3	8	40	ATTACHMENT SUITTED	Y	23	N RD-4 FORM SUB	M	24	PRIME COMP. SUPPLIER	N	25	42	43	44

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of the leak was a failure of the gland flange on the valve. A split gland flange was used as a modification to repair the valve and reduce the possibility of another failure. The work was completed on 2/21/81.

1 1

1 2

1 3

1 4

7	8	9	FACILITY STATUS	E	28	% POWER	0	7	6	29	OTHER STATUS	N/A	30	METHOD OF DISCOVERY	A	31	DISCOVERY DESCRIPTION	Personnel observation	32
---	---	---	-----------------	---	----	---------	---	---	---	----	--------------	-----	----	---------------------	---	----	-----------------------	-----------------------	----

1	6	ACTIVITY CONTENT	Z	33	Z	34	AMOUNT OF ACTIVITY	35	N/A	44	45	46	LOCATION OF RELEASE	N/A	36
---	---	------------------	---	----	---	----	--------------------	----	-----	----	----	----	---------------------	-----	----

1	7	PERSONNEL EXPOSURE NUMBER	0	0	0	37	TYPE	Z	38	DESCRIPTION	39	N/A	44
---	---	---------------------------	---	---	---	----	------	---	----	-------------	----	-----	----

1	8	PERSONNEL INJURIES NUMBER	0	0	0	40	DESCRIPTION	41	N/A	44
---	---	---------------------------	---	---	---	----	-------------	----	-----	----

1	9	LOSS OF OR DAMAGE TO FACILITY TYPE	Z	42	DESCRIPTION	43	N/A	44
---	---	------------------------------------	---	----	-------------	----	-----	----

1	10	PUBLICITY ISSUED DESCRIPTION	N	44	N/A	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
---	----	------------------------------	---	----	-----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

1	8	NAME OF PREPARER	W. S. Lacey	80	PHONE	412-643 3525
---	---	------------------	-------------	----	-------	--------------

NPC USE ONLY
F23504
80-757-040-040

Hook
Add.
M. Collins
LF-1210

036114

*Attachment To LER 81-028/03L
Beaver Valley Power Station
Duquesne Light Company
Docket No. 50-334

No further information is available or needed to satisfy the reporting requirement.