

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M | D | C | C | N | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 14 15 25 26 30 57 58

CON'T
0 1 | L | 0 | 5 | 0 | 0 | 0 | 3 | 1 | 8 | 0 | 8 | 2 | 6 | 8 | 2 | 0 | 9 | 2 | 4 | 8 | 2 | 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 0310 during performance of a surveillance test procedure, an exces-
0 3 | sive leak rate past the containment personnel air lock outer door gasket
0 4 | was discovered (T.S. 3.6.1.3). The leak was located and repaired at
0 5 | 1045. The inner door remained shut throughout the event.
0 6 | Similar events: 50-318/82-01.
0 7 |
0 8 |

0 9 | S | A | E | B | P | E | N | E | T | R | A | Z |
7 8 9 10 11 12 13 18 19 20
17 | LER/RO REPORT NUMBER | 8 | 2 | 0 | 4 | 1 | 0 | 3 | L | 0 |
21 22 23 24 26 27 28 29 30 31 32
ACTION TAKEN | FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS | ATTACHMENT SUBMITTED | NPRD-4 FORM SUB. | PRIME COMP. SUPPLIER | COMPONENT MANUFACTURER
E | E | Z | Z | 0 | 0 | 0 | 0 | N | N | A | C | 3 | 1 | 1 | 0 |
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause of the leakage was a decrease in the force holding the door
1 1 | shut. The door operating mechanism was adjusted to increase this force.
1 2 | The seals tested satisfactorily afterward. Door alignment and closure
1 3 | tightness will be checked and adjusted to the proper levels during the
1 4 | airlock upgrade, scheduled for the next refueling outage (Fall 1982).

1 5 | C | 0 | 2 | 0 | N/A | B | Surveillance
7 8 9 10 12 13 44 45 46
1 6 | Z | Z | N/A | N/A
7 8 9 10 11 44 45
1 7 | 0 | 0 | 0 | Z | N/A
7 8 9 10 11 12 13
1 8 | 0 | 0 | 0 | N/A
7 8 9 10 11 12
1 9 | Z | N/A
7 8 9 10
2 0 | N | N/A | B210040069 820924 PDR ADOCK 05000318 S PDR
7 8 9 10 68 69 80