LICENSEE EVENT REPORT

	LICENSEE EVENT REPORT
	CONTROL BLOCK: [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 8	C A S O S 2 2 O O - O O O O O O O
O 1	REPORT L 6 0 5 0 0 0 3 5 1 7 0 8 2 8 0 9 2 4 8 2 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	While in Mode 3, the turbine of Auxiliary Feedwater Pump 2P-140 tripped. Repeated
0 3	attempts failed to start the pump. There was no consequence to public health and
0 4	safety since any one of the two remaining operable pumps would have performed the
0 5	necessary decay heat removal function if called to do so.
0 6	
0 7	
08	SYSTEM CAUSE CAUSE 1 COMP. VALVE
0 9	HH H 11 E 12 B 13 V A L V E X 14 E 15 SUBCODE SUBCODE 12 13 13 13 18 18 19 15 EG 16
	LER/RO EVENT YEAR SEQUENTIAL REPORT NO. 17) REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
	ACTION FUTURE ACTION ON PLANT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER K 0 8 5 26 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
1 0	Tripping of the pump drive turbine was caused by moisture in the steam supply header
11	and throttle valve. An operator was posted at the pump to blow down the steam
1 2	traps at 2-hour intervals. Some drains were modified and others are under study and
1 3	may also be modified. The turbine operating procedure is being reviewed
1 4	and may also be revised.
1 5	STATUS SPOWER OF DISCOVERY DESCRIPTION (32) NA OTHER STATUS (30) METHOD OF DISCOVERY DESCRIPTION (32) B (31) Operator Observation (32)
	CTIVITY CONTENT LECASED OF RELEASE AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36) NA LOCATION OF RELEASE (36)
7 8	NUMBER DESCRIPTION (39) NA N
1 8	NUMBER DESCRIPTION 41 NA
1 9	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA NA
2 0	PUBLICITY 8210050098 820924 SSUED DESCRIPTION 45 PDR ADOCK 05000361 NRC USE ONLY PDR ADOCK 05000361
	NAME OF PREPARER H. B. Ray HB Ping / Minhy 714/492-7700