

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

September 22, 1982

H. B. RAY
STATION MANAGER

RECEIVED
NRC

1982 SEP 27 PM 1:10

SCE

RECEIVED

TELEPHONE
(714) 492-7700

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. R. H. Engelken, Regional Administrator

Dear Sir:

Subject: Docket No. 50-361
30-Day Report
Licensee Event Report No. 82-080
San Onofre Nuclear Generating station, Unit 2

This submittal is in accordance with the reporting requirements of Section 6.9.1.13b of Appendix A to Facility Operating License NPF-10. It describes a reportable condition involving Limiting Condition for Operation (LCO) 3.8.1.1 associated with A.C. electrical power sources. A completed copy of LER 82-080 is enclosed.

On August 23, 1982 at 1401, while in Mode 4 and returning feeder breaker 2A0101 to service after repair, feeder breaker 2A0104 failed to open during testing for proper breaker operation. Reactor Coolant Pump (RCP)-004, the only load on bus 2A01, was then secured. At the time, and in accordance with Technical Specification 3.8.1.1a, the two offsite transmission networks were feeding the reserve auxiliary transformer 2XR3 and main transformer 2XM/unit auxiliary transformer 2XU1. To manually open feeder breaker 2A0104 for trouble shooting, main transformer 2XM was de-energized and the associated Action Statement entered.

As required by this Action Statement, feeder breaker 2A0104 was racked out and power was restored to 2XM at 1410 on August 23, 1982.

On August 24, 1982, the breaker was placed in a breaker test stand and after repeated testing, proved to be working satisfactorily. The breaker was then racked into its cubicle and tested satisfactorily. This event is believed to be an isolated occurrence and no further corrective action is planned.

8210050151 820922
PDR ADOCK 05000361
S PDR

IE-29
82-336

September 22, 1982

Since the redundant offsite transmission network remained operable as well as the two standby diesel generators, both of which are capable of supplying electrical power to all necessary engineered safety feature systems, there was no impact on health and safety of plant personnel or the public.

If there are any questions regarding the above, please contact me.

Sincerely,

HB Poy / NIM

Enclosure: LER 82-080

cc: A. E. Chaffee (USNRC Resident Inspector, San Onofre Unit 2)

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement

U. S. Nuclear Regulatory Commission
Office of Management Information and Program Control

Institute of Nuclear Power Operations