

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | C | A | S | O | S | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5
7 8 9 14 15 25 26 30 57 CAT 58

CON'T
0 1 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 6 | 1 | 7 | 0 | 8 | 2 | 3 | 8 | 2 | 8 | 0 | 9 | 2 | 2 | 8 | 2 | 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 | With the plant in Mode 4, during feeder breaker testing after returning breaker
0 3 | 2A0101 to service, feeder breaker 2A0104 failed to open. This resulted in the loss
0 4 | of one off-site transmission network supply path. Since the redundant off-site
0 5 | network remained operable as well as the two standby diesel generators, both of which
0 6 | are capable of supplying electrical power to all necessary engineered safety feature
0 7 | systems, there was no impact on health and safety of plant personnel or the public.
0 8 | _____
7 8 9

0 9 | SYSTEM CODE | E | A | 11 | CAUSE CODE | X | 12 | CAUSE SUBCODE | Z | 13 | COMPONENT CODE | Z | Z | Z | Z | Z | Z | 14 | COMP. SUBCODE | Z | 15 | VALVE SUBCODE | Z | 16
7 8 9 10 11 12 13 18 19 20
17 | LER/RO REPORT NUMBER | 8 | 2 | 21 | 22 | SEQUENTIAL REPORT NO. | 0 | 8 | 0 | 24 | 26 | OCCURRENCE CODE | / | 27 | REPORT TYPE | L | 30 | REVISION NO. | 0 | 32
ACTION TAKEN | X | 18 | FUTURE ACTION | Z | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 37 | 40 | ATTACHMENT SUBMITTED | N | 23 | NPRD-4 FORM SUB. | N | 24 | PRIME COMP. SUPPLIER | Z | 25 | COMPONENT MANUFACTURER | Z | 9 | 9 | 9 | 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0 | The breaker was removed and successfully tested in a test stand as well as in its
1 1 | cubicle. The failure could not be reproduced and, therefore, the cause was not
1 2 | identified. This event was an isolated occurrence and no further action is
1 3 | deemed necessary.
1 4 | _____
7 8 9

1 5 | FACILITY STATUS | B | 28 | % POWER | 0 | 0 | 0 | 29 | OTHER STATUS | N/A | 30 | METHOD OF DISCOVERY | C | 31 | DISCOVERY DESCRIPTION | Operability test | 32
7 8 9 10 12 13 44 45 46 80

1 6 | ACTIVITY CONTENT RELEASED OF RELEASE | Z | 33 | Z | 34 | AMOUNT OF ACTIVITY | N/A | 35 | LOCATION OF RELEASE | N/A | 36
7 8 9 10 11 44 45 80

1 7 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | N/A | 39
7 8 9 11 12 13 80

1 8 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | N/A | 41
7 8 9 11 12 80

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | _____ | 43
7 8 9 10 80

2 0 | PUBLICITY ISSUED | N | 44 | DESCRIPTION | _____ | 45
7 8 9 10 80

8210050234 820922
PDR ADOCK 05000361
S PDR

NRC USE ONLY

NAME OF PREPARER H.B. RAY *HB Ray / NRC* PHONE 714-492-7700