LICENSEE EVENT REPORT

	LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 7 8	G A E I H 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 57 CAT 58
CON'T	REPORT L 6 0 5 0 0 0 3 6 6 7 0 8 3 1 8 2 8 C 9 2 3 8 2 6 60 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2	On 8-31-82, during normal operation, quarterly surveillance was being
0 3	performed on the post-accident drywell hydrogen and oxygen analyzer.
0 4	This is required by Technical Specifications 4.3.6.4 for Item 9 of Table
0 5	3.3.6.4-1. The "B" analyzer would not calibrate due to instrument fluct-
0 6	uation. A 30 day LCO existed with the "B" analyzer inoperable. The "A"
0 7	analyzer remained operable. There were no effects upon public health
08	and safety due to this non-repetitive event.
7 8	SYSTEM CAUSE CODE SUBCODE SUBC
	17 LER/RO REPORT NO. SEQUENTIAL REPORT NO. CODE TYPE NO. NO.
	ACTION FUTURE ON PLANT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER A 18 Z 19 Z 20 Z 21 36 37 40 41 41 23 Y 24 43 25 D 0 9 6 26
10	The instrument fluctuation has been attributed to a worn pump head ass-
111	embly on the sample pumps. Both the upper and lower pump head assemblies
12	were replaced. The analyzer was then successfully recalibrated, and
1 3	returned to service.
1 4	
7 8	PACILITY STATUS SPOCE SE OTHER STATUS OTH
	CCTIVITY CONTENT ELEASED OF RELEASE Z 33 Z 34 NA LOCATION OF RELEASE 36 NA BO 80
1 7	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) NA 9 PERSONNEL INJURIES 13 80
1 8	NUMBER O O O O O O O O O O O O O O O O O O O
7 8	9 11 12 LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA NA
7 8	9 10 8210060248 820923 80
20	DESCRIPTION (45) NA S PDR
	NAME OF PREPARER H. L. Sumner - Supt. Plt. Eng. Serv. PHONE 912-367-7851

LER #: 50-366/1982-090

Licensee: Georgia Power Company Facility Name: Edwin I. Hatch

Docket #: 50-366

Narrative Report for LER 50-366/1982-090

On 8-31-82, during normal operation, quarterly surveillance was being performed on the post-accident monitoring instrument drywell H2-O2 analyzer. Calibration is required by Technical Specifications 4.3.6.4 for Item 9 of Table 3.3.6.4-1, and was being performed per "COMSIP DELPHI MODEL K-IV HYDROGEN AND OXYGEN ANALYZER FT&C" procedure. During the test, the "B" hydrogen and oxygen analyzer would not calibrate due to instrument fluctuation. With the "B" analyzer inoperable, a 30 day LCO existed. During that time, the "A" analyzer remained operable. No significant occurrence took place as a result of this event. There were no effects upon public health and safety due to this non-repetitive event.

The instrument fluctuation has been attributed to a worn pump head assembly on the sample pumps. Both the upper and lower pump head assemblies were replaced. The analyzer was then successfully recalibrated per the "COMSIP DELPHI MODEL K-IV HYDROGEN AND OXYGEN ANALYZER FT&C" procedure, and returned to service. This particular component failure is not a recurring problem. This problem is not applicable to Hatch Unit 1 since Unit 1 uses HAYS-REPUBLIC analyzers.