



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D. C. 20555

AEOD/E117

JUL 16 1981

This is an internal, pre-decisional document not necessarily representing a position of AEOD or NRC.

MEMORANDUM FOR: File

50-328

FROM: Harold L. Ornstein  
Office for Analysis and Evaluation  
of Operational Data

SUBJECT: EVENTS AT TMI-2 DURING PREOPERATIONAL  
TESTING (SEPTEMBER 5-12, 1977)

With John Pellet's assistance, I have reviewed the TMI-2 logbook entries of September 5-12, 1977. Unfortunately, the data available is sparse, but nonetheless many important pieces of information can be gleaned from that document.

1. The polisher malfunction resulted in the introduction of resins into the demineralized water system. The polisher system interfaces with the demineralized water system so that polisher water can be diverted to the demineralized water system, and demineralized water can be directed to the polisher inlet. It is not clear from the log sheets exactly how the alignment or alignments were such that the resins migrated from the polisher to the demineralized water system, but they did.
2. The logbook indicated (9/7/77, 1st shift) that resin (from the polishers) was found in the demineralized water system in the turbine and auxiliary buildings. The resin clogged the pump suction strainers of all the Nuclear Service Closed Cooling Water (NSCCW) pumps. Figure 1 is a simplified piping diagram of the demineralized water system (based upon TMI FSAR figures 9.2-9 and 10.4-1). As shown in Figure 1, some of the important systems and components in the auxiliary and turbine buildings which connect to the demineralized water system are:

Diesel generator jacket cooling water  
Borated water storage tank  
Boric acid makeup tank  
Reactor building normal cooling water  
Core flood makeup tank  
Nuclear services closed cooling water  
Intermediate closed cooling water  
Decay heat closed cooling water  
Reactor building spray pumps suction header  
Makeup pump suction  
Seal return coolers  
Spent fuel cooling system

It is interesting to note that the demineralized water system also feeds into the "emergency steam generator feed pumps" which are located in the control building area.

It is not possible to tell from the logbook or the FSAR data which of the aforementioned components have strainers to catch resins in the demineralized water, which actually did have such strainers in place during the event, or which specific components in the auxiliary or turbine buildings were found to contain resins during the event.


3. The logbook did not pinpoint the times that the following events took place:

- a. Loss of reactor coolant pumps (due to loss of NSCCW which cools the RCP seals and motors).
- b. Formation of bubble(s) in the hot leg(s) with the resultant loss of natural circulation cooling.
- c. Loss of makeup (HPI) pumps (due to loss of NSCCW which cools the makeup pump motors).

It is conceivable that, under other circumstances, these events (a, b, and c) could occur concurrently, thereby losing all convective "core cooling" and eventually uncovering the core. The time it took to establish nuclear service river water cooling to the makeup pumps (and thereby reestablish makeup pump flow) during the subject event is not known; however, if the reactor was fueled and at power at the time of the event, the time required to reestablish makeup pump flow (initiate feed and bleed) would be crucial. It is estimated that for a B&W 205 FA plant, failure to do so within about 30 minutes of event initiation would result in core uncovering.

In conclusion, the subject logbook entries can be envisioned to be similar to that of a fair maiden in a bikini - very revealing - very interesting - but still keeping important parts under wraps, possibly never to be known.

In addition to the obvious recommendations about looking into systems interactions, polishers, demineralized water systems, etc., in retrospect it might be worthwhile to pursue installation of a "reactimeter" in all plants prior to startup testing so that important operational data (potential precursors) may not be lost.



Harold L. Ornstein  
Office for Analysis and Evaluation  
of Operational Data

Enclosures:

1. Figure 1 - Simplified Piping  
Diagram - Demineralized Water System
2. TMI-2 Logsheets (September 9-12, 1977)
3. J. Pellet's Overview of TMI-2 Logsheets  
(September 5-12, 1977)

cc w/enclosures:

C. Michelson  
J. Heltemes  
T. Rehm  
J. Pellet


# FIGURE 1

ENCLOSURE 1

S.P. 11/16/81

Simplified Piping Diagram for the Demineralized Water System\*

From FSAR Fig 9.2-9, 10.4-1



## ENCLOSURE:2

TMI 2 Logsheet (9/9-12/77)

It appears buster pump low suction pressure was caused by high SP across condenser pipelines. CO-P-10 did not trip. Buster by-pass was opened and CO-P-2A and FW-P-1A were resetted. Buster outlet valves were checked wide open and hot-well fuel control was fine in normal. Closed buster by-pass (CO-V-12) and buster pump outlet were dropped to 15 psi. Hot-well level was put back in ~~auto~~ <sup>MAN</sup> auto. Problem will be further investigated on next shift. Relieved by Andre Dominguez.

Craig M. Gullin 9-5-77

Relieved Craig M. Gullin, RCS at 532F, 0155PSIG  
pressurizer level at 215". RC-P-1A/RA/10DB running with MO-P-4A<sup>10P</sup>/1C supplying seals. Restored Condensate system to normal until CO-P-1B/2A & FW-P-1A running. FW-V16R is in auto. & CO-V35R is failed open. VA-P-1C/1L maintaining 27" vacuum. Valve stem leak off of RC-V1 & 2 were passing steam into A.D-ring thru the line that should be connected to RC-V122. also check valve W.O.C.-V1102 was leaking at 20 l/min tank. Installed temporary plug in line from RC-V122 & stopped leak valve leak by tightening bonnet. Replaced seal injection filter but SP still indicates 21.5 PSIG. Ran EF-P-1 after packing on outside <sup>of pump</sup> thus indicated at 2000 RPM packing gland temp. read 161F. Then packing gland was checked when packing was

inspected and it was good. Will write to you  
jet tomorrow. FF-V163 is manually shut since it  
was passing ~2000PM after it was "shut" from control  
5/20/23. Room. Conducted Class "C" briefings for FC-62438.  
Received by Jon Green (GPU)

PMSF). Dominguez 9-5-77

Received Andre Dominguez. RCS at 532  
PER 655°F. PER Level 220", FWS-PA  
running. Attempted to run EF-0-1 again  
but packing gland reached 168°F in  
five minutes. Requested UEGC to replace  
packing in outlet bearing. 44 Poleska  
back on line. Trilling on tank. As operator  
noticed water coming from overflow line first  
on "C" bleed tank. Investigated and found  
tank full even though level instrumentation  
indicated 4 ft. Found that reference leg  
had filled with water (see to high level) and  
caused false indication. Assigned technician to  
"B" <sup>100</sup> bleed tank. Recurring "C" bleed tank  
for lab analysis. Briefed C. Adams for

TP600-15. - TP 600-15. - Long flat test. Bringing RCS  
- pieces to 000s for TP600-13. Sampled  
from "A" seal rectra color to "B" cooler as  
TP600-4 required in TP600-4. Relieved by Craig McPherson  
CG Date:

Sept. 6, 1977

<sup>1<sup>st</sup> SHIFT</sup>

2:16 Relieved for Greene and Cal Gatto. RCS at 1400 psig and 532°F. pressurizer level at 220". VA-P-10/1C maintaining 27" vacuum. CO-P-10/2A running with FW-P-1A. CO-V-35H is failed open. and CO-V-16H is maintaining 1000 gpm. Started VA-P-1A and stopped VA-P-1B w/ instrumentation TP600/28 could be calibrated on VA-P-1B. Conducted class TP600/13 C brief for TP 600/28. Conducted class DLT 5090 brief for TP 600/13 and received PH 5090, due D-15. Total pressure-heat exchanger input for 170 gpm exceeded TP600/17 total pressure-heat exchanger output. (D-15) Conducted class C brief for TP600/19 and cycled all CRD's in groups 1-8. Tagged-out segmentation tank on pipelines due to insulation problem can be fitted. Tank has been drained and now is in storage tank from 1<sup>st</sup> pipeline. Increased RCS to 2155 psig. Relieved by Andre Dominguez. Craig McMillan - 96-77

Relieved Craig McMillan. RCS at 532F, 2170 PSIG, pressure level at 230", all 4 RC-P's running with HO-P-1C supplying seals. Seal injection filter should be changed when P.P. ac read or less. gauges across the filters reads  $20 + 25 = 40 \text{ PSI}$  due to clean filter showing 20 PSI ΔP. Placed a clean filter in SF-F-1A, manually closed AH-E-HC's section damper to stop bypass flow from windmilling it. Set RR-V9C to put up.

<sup>2<sup>nd</sup> SHIFT</sup>

2:16

flow three other & running fans. Tested one 4.5 relief PR 50 valve - It did not meet its acceptance criteria. Valve to be retested. Conducted a class "C" briefing for TP 5042. Received by John Ulrich.

Review of Log 9-6-77 following comments:

1. Review Log 9-6-77 for Aug 1. SCU on 8-30 - no WP on CO-P-2B that wouldn't trip. Some late and PR issued on 8-30 on PC-PV-2. Continuation of PR 5073 for PC-PV-2

2. SCU on 9-2-77 EF-P-2A tripped twice no PR. Problem was identified to T.M. Hawkins

3. CMK - Q-5 cut by the trip bells are not to be used on MDCT.

PJ Tool 9-6-77

Received Andre Dominguez, PCN 2153 pig and 532°F. Pressurizer level at 220" and temperature at 655°F. HCU-P-1C running supplying LC

3rd SHIFT 9-6 pump seals. All 4 LC pumps running. CO-P-1A and FA-P-1A running through COV 35A (bulbage) and FW-816A and feeding OTSG's. VA-P-1A/1D

1B(2-31A) running maintaining 27" vacuum. Secured

VA-P-1B. Conducted a class "C" briefing for TP 5042-260/3 and 600/2.8 psig. Rich Orff conducted

a class C briefing for TP 271/4 psig. The oil pressure switch for 1H-8-1B doesn't allow the pump to start. T.M. Hawkins was notified of the problem and installed a 110# gage on MIL-6-PS for special test on the block orifice per

5  
1555-2500. Completed testing tonight of 2  
H.S. relief valves. The testing will continue  
tonight. DH-L S-7795 was calibrated  
in preparation for TP 20/3 (TCN-2). Revo-  
ment of sections 9.1 and 9.2 for TP 20/3.  
These sections will be completed tomorrow  
when necessary information, support is available.  
H.A.U.-6405 repair was completed. Relieved  
by Craig McMillan. John G Ulrich 9-6-77

Sept. 7, 1977

Relieved John Ulrich. RCS at 2155 psi and 532°F.  
Bunser test at 320° and temperature at 655°F.  
NS-P-1C supplying RCP seals. CO-2-113/2A and  
FW-2-1A running thru CO-2-35A (failed open) and  
FW-2-10A, V4-4-777/13 (open) running 27°  
maximum. Completed repairing the repair and cleaned  
top. NS-P-1A/18 tripped on low cooling H<sub>2</sub>O  
flow to motors. Tried to start NS-P-1C, it  
tripped within a minute. Called section  
heads overall 3 pumps and found main  
failed in them. Bear has come from concrete  
pitless bear den. H<sub>2</sub>O up to NSCCW up.  
The motors make up water. Cleaned and replaced  
the 3 motor strainers 2-4 times and failed  
to lift a 105 pump running for more than  
20 minutes. Started floating pump. H<sub>2</sub>O up.  
and had water in tunnel and out buildings.

Flushing will continue this next shift. Notified T.P. 00014 T. Hanks of problem. Completed section 7.1 for T.P. 00014. Sealed man-p-1C, RC-P-1A/JIC and all 4 RCP's. Shifted cooling water flow to man pumps to wash up, and started man-p-1B. Established seal injection and return to RCP's. When RCP's were tripped RC-P-2B and oil pump did not start. T. Hanks notified J. problem. Relieved by John Ulrich.

Received Craig McMullen. RCS pressure at 2100 psig and decreasing. RCS temperature at 390°F and decreasing. Pressurizer level at 190" and temperature at 645°F. All RC pumps secured. M4-P1/B supplying RC pump seals. CO-P-1B/2A and FW-P-1A running on cleanup recirc. Through FW-V16A and CO-V55A. VA-P-1A/JB (2-31A) maintaining 27" vacuum. Started VA-P/C and stopped VA-P-1B. Closed NSCCW strainers again several times trying to flush debris out of pipes. Flushed DW upstream of level control valve on NSCCW. Replaced the intervals of DW-V173. There was a fire trailer complex. Some heat tracing caught a fire. No one was hurt and damage was minimal. Conducted a class G briefing for TP 204/3 pt. The DH level switches which intersect with

2<sup>ND</sup> SHIFT  
9-7

DA-V6A/B were rechirated with proper lead corrections inserted. LC-V3 and LG-V108 were closed to work on ABL-Vac. Jack Knop worked on E-F-P-2B breaker problem with no resolution of problem. Relieved by Jack Garrison. *John Ulrich 9-7-77*

Relieved John Ulrich. RCS at = 1400 psig 330°F with no RCP's running. MU-P-1B running. RCS pressure and temps are decreasing. Continuously filling and draining pressure in attempt to reduce plant pressure.

Secondary plant @ 27" vacuum with CO-P-1G/2A & FW-P-1A running via FW-V16A & CO-V35A. Flushing of DW & NSCCW system still in progress. Started VA-P-1E and secured VA-P-1A when was discovered no water level in reservoir. When VA-P-1A was secured a water level returned to reservoir. Secured CO-P-2A and FW-P-1A due to plant cooldown. Conducted class C briefings for TP 204/3 section 9.4 with S/F satisfactorily. Testing of DA-V6A/B except for section 9.8.9 which failed. DH-V6B could be closed from CR with level interlock in effect. Issued PR 5092. Level actuation points were not correct. Resolution and resetting of switches is being work by Met Ed just dept. Relieved by John Ulrich.

*Jack Garrison 9-7-77*

Sept 8, 1977

Relieved Jack Garrison. RCS at 1100 psig and temperature at  $\approx 290^{\circ}\text{F}$ . Surveying pressure

3<sup>RD</sup> SHIFT  
9-7

TP 204/3  
PR 5092

1<sup>ST</sup> SHIFT  
4-8

so pressure level is constantly changing.  
CO-P-1B running through FW-V16A and CO-V15A  
on cleanup recirc. VA-P-1B/1C maintaining 27"  
vacuum. MU-P-1B running and supplying RC pump  
seals and level makeup. Flushing of NSLCW  
in progress. Started CO-P-1A and secured  
CO-P-1B due to <sup>packing</sup> ~~no special~~ leakage. MEC wrote  
WR to adjust packing. Collected data needed  
to reset level switches for DH-V16A/B  
interlocks and instrument department is  
resetting the setpoint to appropriate value.  
Re-established NS flow to the reactor  
Blody Re-established NS flow to MU pumps  
and shut off NR to MU pumps. Tried to  
start MU-P-1A and both MU-P-1A and -B  
triggered on low suction pressure. The problem  
was identified to T.M. Hawkins. I isolated  
MU-P-1A suction pressure switch long enough  
to get MU-P-1A running. Re-established RC  
pump seal injection. Placed BW5/T on  
cleanup recirc. using SF-P-2. Opened RC-  
V155 and -V137 and started venting the pressurizer  
to the RG drain tank. Started venting the main  
generator. Completed recalibration of DH-V16A/B  
interlock-level switches. Placed RR-P-1A  
and -1C back into service to LB cooling  
coils. Relived by Andre Dominguez.

*John C. Ulrich 9-8-77*

Rained John Ulrich. RCS at 200F & 460PSIG,  
pressurizer being restored to normal level. CO-P-1A  
 running thru FW-VIBA's, CO-V35A, VA-P-1B/1C  
 maintaining 27" vacuum. MU-P-1A running  
 supplying RC pump seals. Adjusted the piping on  
 DS-P-1C and started it satisfactorily. MEC  
 mechanical maintenance started cleaning VA-P-1A  
 water receivers. MU-P-1B, NS flow switches are  
 now installed and calibrated. Lined up flow thru  
 FW-P-1B to change level switch in FW-T-1A but  
 could not isolate it from condenser because Turbine  
 exhaust valve 45-V45 was leaking. Ran OG-P-1B & HE  
 for ten minutes to check suction strainers, they  
 read 1" & 3" respectively. MU-P-1A aux gear oil  
 pump was noticed running. Press on speed  
 increaser was 7° but no sight oil level. Let off  
 MO-P-1C and secured MU-P-1A. Pressurizer level  
unexpectedly increased when venting the  
pressurizer and decreased pressure from 500psig to  
100psig. Pressurizer level increased  $\approx 150''$  during  
 this evolution. Pressurizer temp was = 340F.  
apparently the reference legs have flashed and  
there was no steam in pressurizer to fill the  
reference legs. One reference is going <sup>big H.P.</sup> filled to  
justify the correct level. MU-P-1A air level is going  
 to be restored to normal & Aux oil pump desired

2nd SHIFT  
Q-D

out on next shift. Received by Jay Garrison.

Received Andre Dominguez. RCS at  $\approx 340$  psig and  $\approx 250^{\circ}$  indicated. Plant cooling down naturally. No RCP's running. MUPIC running supplying seals. Preparations being made to place plant on DH. cooldown and drain RCS for RCP seal inspections. Secondary plant at  $26^{\circ}$  vacuum with VAP-181C and CO-P-1A on recirc via CO-V35-A & FW-V16B.

3rd SHIFT  
Q-B RCS-LT3 was backfilled at reference leg. Comparison was made between LT1-LT2-and LT3. All three were reading same. Pressure level indication as shown in control room is believed to be correct. Started DH-P-1B and commenced plant cooldown. Plant temperature at start  $160^{\circ}\text{F}$ . Plant cooled down to  $100^{\circ}\text{F}$ . Whenever RC-V137 was opened to vent pressure, level would indicate an increase. Closed DH-V4B and put maximum auxiliary spray flow to pressurizer in attempt to cool down pressurizer. Feed both ORSG's up to 400" in preparation for wet layup. Shifted RR-P-1A to off and started RR-P-1B for RR flush being conducted by UEIC startup engineers. Discovered oil level in MU-P-1A speed changer was actually high and not low as previously reported. Drained oil down to visible level. Secured seal injection and seal

return on RCP's. Closed MU-V18. Changed IC-F-1B due to high SP. Found IC-V5 closed for no apparent reason. Reopened it & vented ed from floor. Relined by John Ulrich  
Jack Garrison 9/8/77

Sept. 9, 1977

~~5 SHIFT~~  
~~A-A~~

Retired Jack Garrison. LCS pressure at 150 psig and decreasing. MU-F-1C running on recirc. DH-P-1B on recirc to the RC vessel. CO-P-1A on recirc. through CO-V35A and FW-V16B. Closed RC-V137 and applied nitrogen to the pressurizer. The pressurizer level came down proving that there was a steam bubble in each of the hot legs. Left N<sub>2</sub> on until pressure started to slightly increase and secured N<sub>2</sub>. Opened cold leg drains and lined up to the A' RCBT and drained LC system until level was not decreasing on pressurizer level recorder and then closed cold leg drains. Previous to draining, the hot legs and the pressurizer were equalized in pressure through the nitrogen system piping. Continued to decrease LCS pressure by venting the hot legs to atmosphere and the pressurizer to the LC drain tank. Stopped VA-P-1B and started VA-F-1A. Secured DH-P-1B and secured LCS cooldown at approx. 100°F. Reestablished sealing steam to FW-P-1A turbine and

connected RCS-V45 to the condenser. Secured auxiliary spray lines to the pressurizer. Started transfer of LCBT 'A' to RC BT 'C'. Connected tygon tubing to RC-V110 and -V111 for RCS level indication when pressure is sufficiently decreased. Secured IC system due to the requirement for the system cooling on bottom coolers and CLD's.

Relieved by Andre Dominguez. John C. Ulrich 9-9-71.

Relieved John Ulrich. RCS vented with 92" in tygon tube coil  $\frac{1}{10}$ " connected to RC-V110 & V111. MO-P-1C running on recirc to MO-T-1. CO-P-1A running thru CO-V35A & FW-V16B. Started VA-P-1B & secured VA-P-1C for reservoir clearing. Drained the RC systems to 22" in tygon tube connected to RC-V110 & V111. Conducted a class 'C' brushing for

TP 204/3 and completed section 9.4.B (DH-V671B auto open) satisfactorily and cleared D-23. Picred the "A" OTSA on recirc and added 3.5 gal. of hydrazine at 19:40. Relieved by Jack Garrison Andre). Dominguez 9-9-71

Relieved Andre Dominguez RCS vented and drained. Secondary plant at 27" vacuum with CO-P-1A running. Secured MO-P-1C when it was discovered tygon hose reading of 139". Opened hot leg vents and pressurizer vent to atmosphere. Drained RCS to 16" as indicated on tygon hose at RC-V110 & V111. Conducted class C brushing for TP 310/3 satisfactorily and tested ES actuation of

330/3  
5093

1C-V3, 4, & 5 with noted deficiency and issuance  
of PR 5093 against not being able to open valves  
after ES reset using "TEST RESET" switch at gen 13  
when DC power circuit was deenergized. OTSG  
A on recirc with hydrazine added. Believed by  
Craig McMullin

Jack Garrison 9/9/77  
Sept. 10, 1977

~~5 SHIFT~~  
~~9-10~~  
Believed Jack Garrison. RCS vented and drained.  
Secondary plant at 27" vacuum with CO-P-1A  
TP 202/3 running. Conducted a class C brief for TP  
202/3. Tried to start MU-P-1B from 2-1E from  
c.i. Pump would not start. Notified T. Hawkins  
PR 5094 of problem. Issued PR 5094 after MU-P-1B(2-2E)  
D-51 tripped on low cooling water flow and MU-P-1C  
did not start automatically. (D-51). Tried to  
transfer bus 2A-1E-2 to 2B-1E-2, 2A-1E-2  
opened but 2B-1E-2 did not close. Closed tie  
breakers on 2-3E-2 and 2-4E-2. Notified T.  
Hawkins of problem. Believed by Eddie Dominguez.  
Craig McMullin 9-10-77

~~2 PPSHIFT~~  
~~9-10~~  
Believed Craig McMullin. RCS vented with 14"  
in legs <sup>11/10</sup> Tygon tube connected to RC-V 110 & 111. CO-P-1A  
running thru CO-U35A & FW-V-16B, VA-P-1A & 1C running  
maintaining 27" vacuum. RC system & Secondary side  
of OTSG's have N<sub>2</sub> blankets. Added 2 gal. of hydra-  
zine to A' OTSG making a total of 5.5 gals. added.  
Conducted a class C brief and satisfactorily

3:01/3 completed sections <sup>9.4.12.1</sup> ~~9.4.12.1~~ thru 9.7.12.4 satisfactorily, TP256/4 are  
NH-V142 has blown apart, This is the 5<sup>th</sup> regulate  
in reactor building. MEC has submitted VR.

<sup>3P</sup> FW-P-1A is isolated for suction strainer seals  
repair. Structural steel is being removed from  
alone RC-P-2B and a clean room is being built  
around RC-P-1A seal area. Relieved by Jack Garrison

Andre Dominguez 9-10-77

<sup>3P SHIFT</sup> Relieved Andre Dominguez. RCS vented and drained  
with  $\approx 14"$  in Tygon hose (RC-V110,111) Secondary  
plant at 27" vacuum with condensate on recirc  
clean-up. Conducted check of auto start features  
of EFW pumps. EF-P-2A was not checked because  
2-IE was deenergized. 2-IE is deenergized due to  
fault in 2A-IE2 and 2B-IE2 breakers not being  
able to be reclosed after surveillance test. EF-P-2C PR 5097  
did not auto start. T. Hawkins notified of problem. PR 5098

Relieved by Craig McMullin Jack Garrison 9/10/77

Sept. 11, 1977

<sup>5<sup>th</sup> SHIFT</sup> Relieved Jack Garrison. RCS vented and drained.  
Secondary plant at 27" vacuum with condensate  
<sup>α-"</sup> on recirc clean-up. Tygon tube on RC-V110 & 111  
<sup>273/3</sup> is  $\approx 13"$ . Conducted class C lifting for TP 273/3.  
Run EF-P-2B and verified 3<sup>rd</sup> port on head/flo-  
cuse by lifting pump up to B'0150. MS-V-207  
would not open from C.A. T. Hawkins notified of  
problem. Added 3 gal. of hydrazine to "B" 0150

secondary  
5<sup>th</sup> regulator  
2.  
Seals  
from  
built  
ison  
7-10-77  
ained  
ary  
recirc  
tours  
cause  
ne to  
ing  
EF-P-28  
problem.  
~ 7/10/77  
ained.  
crete  
111  
273/3-  
flow  
-v-207  
tified f  
3" 0150

1 P-235/4 and put on recirc. Conducted class C briefings for TP 235/4 and satisfactory tested MS-V-3 A/B at 0600. loss of circ. air. EF-P-1 could not maintain 4250 rpm when discharge valve was open to fill "B" OTSG. Pump was line-up to Aux steam which was at 160 psig. T. Harkin notified of problem.

Relieved by Andre Dominguey.

Craig M. Mullin 9-11-77

Relieved Craig M. Mullin. RCS vented & drained. Secondary plant at 27" vacuum with condensate on clean-up recirc. Tygon tube on RC-V110 & 111 is 14". Conducted Class C briefings for TP 235/1 and completed the TP with the following deficiencies:

D-4 Rx Building dump, Level HI - errors in reverse issued PR to resolve

D-5 WOL-P-3N&B did not meet flow capacity. Issued PR to resolve.

PS-V10 is shut and MS-V207 does not open fully. Construction will start up instrument shop and repair MS-V207 tomorrow. Relieved by Jack Garrison

Andre J. Dominguey 9-11-77

Relieved Andre Dominguey. RCS drained for CCP work. Secondary plant at 27" vacuum. Damped 3 OTSG. Results 255 ppb SO<sub>4</sub>. Drained 6 OTSG to 30". Shifted condensate lineups thru FW-12A & 12B. Closed FW-V16B. Found out that flow has been secured thru CO-V55A since day shift

2<sup>ND SHIFT</sup>  
Q-II

1 P-235/1

PR 5097

PR 5098

3<sup>RD SHIFT</sup>

Q-II

yesterday due to tag out of CO-P-2A and closing of its respective suction valve. All condensate flow was going thru FW-V16B. By log review it was  $\approx$  2100 gpm. (800 gpm via #2 polisher 1300 via #4 polisher). Sampled FW at 55-V17 local sample point (55-V117). Results 25 ppb PO<sub>4</sub>. Resampled 3 hours later. Results 120 ppb. FW continuing to clean up & 55-V117 open constantly. Made preparations for TP 160/3 Emergency Rx Bldg Cooling.

Met Ed ran DH-P-1B on recirc of Rx vessel for surveillance leak rate test. DH-P-1B is secured. Relieved by Craig McMullin. Jack Garrison 9/11/77.

Sept 12, 1977

Relieved Jack Garrison. RCS drained and vented. Secondary plant at 27" vacuum. Put N<sub>2</sub> on both OTSGs. Found 555-V-293A/S, 294A/B, 295A/S and 296A/B closed. Drained A" OTSG to 30" due to PO<sub>4</sub>. Filled both A" & B" OTSG to  $\approx$  400" TP 160/3 after FW came in spec. Conducted class C lifting for TP 160/3. Verified head/flow curves PR 5096 for RR-P-1A/1B/1C. Issued PH for D-3; A pump at 3000 gpm did not meet acceptance criteria. Lined up RR-P-1A/1C to Rx Bldg. Fans. Relieved by Andre Dominguez.

Craig McMullin 9-12-77

2<sup>nd</sup> SHIFT  
9-12 Relieved Craig McMullin. RCS vented & drained. Secondary plant at 27" vacuum. added 3" liters

way of  
flow  
it was  
a #4  
couple  
led  
ng to  
lay.  
el  
is secured  
on 9/11/77.

11.  
both  
1/2 and  
the  
vac"  
c  
curves  
-3;  
stance  
ldy.

12-77

met.  
this

to intend after increasing colliers & securing  
running water to Unit 2. Demin steam to T-312

Reviewed log with following comments

1. JCU 9-6 entry valve number MU-V-405? is  
not clear. MU-V405A valve disc had fallen off stem. New one was put  
in.
2. CMM - 9-7 entry when RC-P-2B didn't start  
a PR should have been issued. CMM
3. JCU Fire was under S&H piping trailer  
toilet. (9-7-77)
4. JWG - no entry as to what was done on  
Vac Pumps.

5. Generally this week we had a major  
unusual occurrence and numerous things  
were not entered in the log that should  
have been for example a. Vacuum Pumps were all  
cleaned of resin. b. Did Condensate Pump 1B on  
JCU 9-8 entry have resin in it? c. No one  
logged the fact that we did a complete flush of  
the Demin Water System.

6. There is no reason given for how we got into  
problem on Pressurizer Level. A change to cooldown  
procedure could be made if we knew what to do.

R. Toole 9-12-77

Fwd. 1st. Please measure at CECO. Demin G.S.  
and service CO-2-1,2. Isolated CO & FI systems.  
CO-2-5 P-350 is on valve. Added 5 gal. of hydroxyl  
T-12 -> C-1,2. I tested it. Min CO-T-1F is

Dolewell and CO-T-113 to the yard drain. Relieved  
by Jack Garrison. Andre Dominguez 9-12-77

77266/1

Relieved Andre Dominguez. RCS drained & RCP  
work in progress on seals. Secondary plant  
shutdown. Turbine on turning gear. Lined up  
EFW system for auto start checks of all  
three pumps. EF-P-2A & 2B started satisfactorily  
however neither amp meter in control showed any  
current. The MS-V207 value is blowing fuses and  
was not ~~checked~~ checked. T. Hawkins notified of  
problems. Removed MU-F-4B filter cartridge  
in preparation for AP check of cartridge  
housing. CO-P-1C was put on recirc for  
EFW checks. It is presently secured.

Relieved by Craig McMullen Jack Garrison 9/14/77

Sept. 13, 1977

Relieved Jack Garrison. RCS drained and RCP  
work in progress on seals. Secondary plant  
shutdown. Turbine on turning gear. Started  
CO-P-1C and ran EF-P-1 on recirc. Bulk  
steam pressure was 180 psig and max. rpm  
that ~~it~~ was obtained was 4700 rpm. T.  
Hawkins notified of problem. Secured EF-P-1  
and CO-P-1C. Ran MU-F-4B on recirc for  
seal injection, AP verification. Opened MU-V  
32 and MU-V-275 and established 40 gpm.  
AP thru MU-F-4B with filter removed

## Overview of TMI-2 Log, September 5 - 12, 1977

1. 9-5-77 shift 1      High differential pressure across condensate polishers causes condensate booster pump trip on low suction pressure so polisher bypass opened and polisher repair started.
2. 9-5-77 shift 3      Polisher back on line, filling demineralized water tank (from condensate system).
3. 9-7-77 shift 1      All Nuclear Service Closed Cooling Water (NSCCW) pumps tripped due to clogged pump suction strainers. Clogging resin came from condensate polishers thru demin. water system. Resin found in demin. water system in turbine and auxiliary buildings. Loss of NSCCW produced a loss of RCP seal and motor cooling. Also loss of cooling to makeup (MU) pump motors occurred and makeup was secured. All RCP's were immediately secured on loss of both seal injection and seal cooling. Nuclear Service River Water cooling to MU pumps was established and MU restored.
4. 9-7-77 shift 2      Isolated normal pressurizer spray line to work on liquid waste system valving (note: spray lost when RCP's secured).
5. 9-7-77 shift 3      RCS on natural circulation with makeup via MU-P-1B. RCS temperature and pressure decreasing. Continuously filling and draining pressurizer to reduce RCS pressure. Secured condensate booster and main feedwater pumps due to plant cooldown (1 CBP on).
6. 9-8-77 shift 1      Pressurizer level constantly surging. Started venting pressurizer to reactor drain tank.
7. 9-8-77 shift 2      RCS at 200°F and 400 psig. Pressurizer level being restored to normal level. Pressurizer level increased 150" while

venting RCS from 500 psig to 460 psig. Pressurizer temperature about  $340^{\circ}$  F. From the log, "Apparently the reference legs have flashed and there was no steam in the pressurizer to fill the reference legs." (note that at 460 psig  $T_{sat} > 450^{\circ}$  F).

8. 9-8-77 shift 3      RCS at  $250^{\circ}$  F and 340 psig. Pressurizer level transmitter LT-3 backfilled. LT-1, LT-2, and LT-3 all read the same in the control room and are believed to be correct. DHR started with B pump with RCS at  $160^{\circ}$  F and cooled to  $100^{\circ}$  F. Whenever the pressurizer was vented pressurizer level increased. DHR to vessel isolated and maximum auxiliary pressurizer spray established to try to cool the pressurizer. Secured seal injection and return on all RCP's.
9. 9-9-77 shift 1      RCS at 150 psig ( $T_{sat} \approx 360^{\circ}$  F). Closed pressurizer vent and, "...applied nitrogen to the pressurizer. The pressurizer level came down proving that there was a steam bubble in each of the hot legs." Left nitrogen on until pressure started to increase then secured. Opened cold leg drains to Reactor Coolant Bleed Tank and drained RCS until pressurizer level recorder was not decreasing. The hot legs and pressurizer were equalized in pressure thru the nitrogen piping. RCS pressure decrease continued by venting hot legs to atmosphere and pressurizer to Reactor Drain Tank. Secured cooldown with RCS at about  $100^{\circ}$  F. Connected Tygon tubing to RCS to measure RCS level when pressure decreased sufficiently.

10. 9-9-77 shift 2      RCS vented and drained such that level in tubing decreased from 92" to 22".
11. 9-9-77 shift 3      Secured makeup when tubing indicated a level of 139". Opened hot leg and pressurizer vents to atmosphere and drained RCS to an indicated 16".
12. 9-10-77 shift 2      Inside containment nitrogen regulator (5#) found "blown apart" (NM-V142).
13. 9-12-77 Review      "There is no reason given for how we got into a problem on pressurizer level. A change to cooldown procedure could be made if we knew what to do."