



GULF STATES UTILITIES COMPANY

RIVER BEND STATION POST OFFICE BOX 220 ST. FRANCISVILLE, LOUISIANA 70775

AREA CODE 504 835-6094 346.8651

November 26, 1990
RBG- 34065
File Nos. G9.5, G9.25.1.3

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Gentlemen:

River Bend Station - Unit 1
Docket No. 50-458

Please find enclosed Licensee Event Report No. 90-034 for River Bend Station - Unit 1. This report is being submitted pursuant to 10CFR50.73.

Sincerely,

W. H. Odell
Manager-Oversight
River Bend Nuclear Group

W. H. Odell
LAE/PDG/DEJ/DCH/RCL/pg

cc: U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011

NRC Resident Inspector
P.O. Box 1051
St. Francisville, LA 70775

INPO Records Center
1100 Circle 75 Parkway
Atlanta, GA 30339-3064

Mr. C. R. Oberg
Public Utility Commission of Texas
7800 Shoal Creek Blvd., Suite 400 North
Austin, TX 78757

9012070136 901126
PDR ADDCK 05000458
S PDC

TEED
11

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATES TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20545, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1): RIVER BEND STATION

DOCKET NUMBER (2): 050004581 OF 013

PAGE (3): 1 OF 013

TITLE (4): Reactor Protection System Actuation due to Shorting in the Connectors During Under Vessel Decontamination Activities

EVENT DATE (5)			LER NUMBER (6)		REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES
10	27	90	90	034	001	11	26	90	
								DOCKET NUMBER(S):	
								050000	
								050000	

OPERATING MODE (9): 5

POWER LEVEL (10): 0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5 (Check one or more of the following) (11):

<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.406(e)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)
<input type="checkbox"/> 20.405(a)(1)(iii)	<input type="checkbox"/> 50.36(e)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(c)
<input type="checkbox"/> 20.405(a)(1)(ii)	<input type="checkbox"/> 50.36(e)(2)	<input type="checkbox"/> 50.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
<input type="checkbox"/> 20.405(a)(1)(iii)	<input type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 50.73(a)(2)(vii)(A)	
<input type="checkbox"/> 20.405(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)	
<input type="checkbox"/> 20.405(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12):

NAME: J. A. England, Director-Nuclear Licensing

TELEPHONE NUMBER: 510 438 1111 (411) 415

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13):

CAUSE	SYSTEM	COMPONENT	MANUFAC TURER	REPORTABLE TO NRCDS	CAUSE	SYSTEM	COMPONENT	MANUFAC TURER	REPORTABLE TO NRCDS

SUPPLEMENTAL REPORT EXPECTED (14):

YES (If yes, complete EXPECTED SUBMISSION DATE): NO:

EXPECTED SUBMISSION DATE (15):

MONTH	DAY	YEAR

ABSTRACT (Limit to 7400 spaces, i.e., approximately fifteen single space typewritten lines) (16):

At approximately 1338 on 10/27/90 with the unit in Operational Condition 5 (Refueling), the reactor protection system (RPS) actuated on high neutron flux signals from intermediate range monitors (IRMs) F and G. No rod movement resulted from this RPS actuation. The root cause was shorting in two IRM detector connectors due to the introduction of water into the connectors. This event is reportable pursuant to 10CFR50.73(a)(2)(iv) as an engineered safety (ESF) actuation.

The maintenance procedure governing control rod drive removal will be revised. A precaution will be added to alert personnel to the need for care when performing decontamination while in proximity to nuclear instruments. In addition, prerequisites will be added to verify the integrity of the cable guards which protect the IRM connectors, prior to CRD removal work.

All installed control rods were inserted prior to this event. Note that some control rods had been removed for replacement. Additionally, no rod motion occurred as a result of the unplanned RPS actuation and the RPS system responded as designed. Therefore, this event did not adversely affect the health and safety of the public.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE: TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST, 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (F-630), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) RIVER BEND STATION	DOCKET NUMBER (2) 0 5 0 0 0 4 5 8 9 0	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		0	3	4	0	0 2 OF 0 3

TEXT (if more space is required, use additional NRC Form 306A's) (17)

REPORTED CONDITION

At approximately 1138 on 10/27/90, with the unit in Operational Condition 5 (Refueling), the reactor protection system (RPS) (*JE*) actuated on high neutron flux signals from intermediate range monitors (IRMs) (*IG*) F and G. All installed control rods were previously inserted and no additional rod motion occurred due to the RPS (*JE*) actuation. The root cause of this actuation was shorting in two IRM connectors due to the introduction of water into the connectors. This event is reportable pursuant to 10CFR50.73 (a)(2)(iv) as an engineered safety feature (ESF) actuation.

INVESTIGATION

On October 27, 1990, contract personnel had completed torquing of control rod drive mechanism flange bolts and were in the process of decontaminating the undervessel equipment handling platform using a water spray wand. Near the end of the decontamination operation, the RPS actuation occurred.

Following the RPS actuation, the operators followed plant procedures and reset the scram at 1142. Prompt maintenance work orders (MWOs) 056642 and 056648 were written to trouble shoot and repair the IRM connectors. Upon disassembly, maintenance personnel discovered water present in both connectors. The connectors were removed, dried, cleaned, and then replaced in their respective IRMs. The individual IRMs were tested satisfactorily per their surveillance test procedures and were returned to service.

CORRECTIVE ACTION

Following the RPS actuation, the shift supervisor suspended undervessel activities and initiated prompt MWOs to investigate IRM F and IRM G as stated in the investigation section. In addition, the plant manager reviewed the circumstances of the event with the personnel involved.

The maintenance procedure governing control rod drive removal will be revised. A precaution will be added to alert personnel to the need for care when performing decontamination while in proximity to nuclear instruments. In addition, prerequisites will be added to verify the integrity of the cable guards which protect the IRM connectors, prior to CRD removal work.

SAFETY ASSESSMENT

All installed control rods were inserted prior to this event. Note that some control rods had been removed for replacement. Additionally, no rod motion occurred as a result of the unplanned RPS

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (F-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) RIVER BEND STATION	DOCKET NUMBER (2) 0 5 0 0 0 4 5 8	LER NUMBER (8)			PAGE (9)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		9 0	0 3 4	0 0	0 3	OF 0 3

TEXT (If more space is required, use additional NRC Form 386A's) (17)

(*JE*) actuation, and the system responded as designed. Therefore, this event did not adversely affect the health and safety of the public.

NOTE: Energy Industry Identification System Codes are identified in the text as (*XX*).