	CONTROL BLOCK:
7 8	0 T M N S 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 6 6 LICENSE TYPE 30 57 CAT 58
O 1 7 8	SOURCE
0 2	During routine surveillance testing, with the plant in Mode 1 and 100 per cent
0 3	power, the packing that seals the operator shaft in the primary containment outer
0 4	airlock door leaked and the test pressure could not be maintained. The plant was
0 5	operated in accordance with Technical Specification Statement 3.6.1.3 for 4 hours
0 6	and 45 minutes. Similar LER's: None
0 7	
0 8	9 SYSTEM CAUSE CAUSE CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE
0 9 7 8	S A 10 E 12 X 13 PENETTR 14 A 15 Z 16 SEQUENTIAL OCCURRENCE REPORT REVISION
	TYPE NO. REPORT N
	ACTION FUTURE COMPONENT SHUTDOWN HOURS (22) ATTACHMENT FORM SUB. PRIME COMP. SUPPLIER SUBMITTED FORM SUB. SUPPLIER SUPPLIER SUBMITTED FORM SUB. SUPPLIER SUP
10	
111	was tightened. The Preventative Maintenance Schedule has been changed to include
1 2	inspection and, if necessary, replacement of the packing at the end of each
13	refueling.
1 4 8	80
1 5	FACILITY STATUS THE STATUS TO
	ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA NA NA
7 8	9 10 11 44 45 80
17	NUMBER 13 TYPE DESCRIPTION (39) NA NA NA NA NA NA NA N
118	PERSONNEL INJURIES NUMBER DESCRIPTION 41
7 8	SO LOSS OF OR DAMAGE TO FACILITY (43)
1 9	Z 2 NA
20	ISSUED DESCRIPTION (S) 8210210160 821013 PDR ADOCK 05000336 S PDR
	NAME OF PREPARER Gary Komosky PHONE: 447-1791 Ext 4725