

Log # TXX-901021 File # 10200 911.5 Ref. # 50.73(a)(2)(iv)

William J. Cahill, Jr. Executive Vice President December 5, 1990

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, D. C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION DOCKET NO. 50-445 MANUAL OR AUTOMATIC ACTUATION OF ANY ENGINEERED SAFETY FEATURE LICENSEE EVENT REPORT 90-038-00

Gentlemen:

Enclosed is Licensee Event Report 90-038-00 for Comanche Peak Steam Electric Station Unit 1, "Gas Channel Alarm Initiated a Containment Ventilation Isolation Due to Stagnant Air Pockets in Containment."

Sincerely,

Welliam & Cakilly Dr.

William J. Cahill, Jr.

2-11/. 6 DUBE By:

Roger D. Walker Manager of Nuclear Licensing

DEN/daj

Enclosure

c - Mr. R. D. Martin, Region IV Resident Inspectors, CPSES (3)

9012110019 901205 PDR ADOCK 05000445 PDC

		L	IC	EN	SE	EE	EVI	EM	чт	REF		EAR REG	ER)	Y COMMISSIO	ESTIMA COLLEC BURDEI BRANCH DC. 205 OFFICE	TED B TION N ES H (P-6 IS5, A OF M		AJ DEN P DUES U.S. I TO T DEMI	PPRO ER A IT: TO T NUCL HE P ENT /	VED EXP 50.0 THE EAP APE	ONS HRS HRS REC REC BUD	B NO S: 4/3 E TC D FO DORC GULA DRK GET,	916 0/92 0 COI 0 RW/ 0 S A 1 OR RED WAS	ND IND IND IND IND IND IND IND IND IND I	WIT COM REP MMI ON F	H TH MEN DRTI SSIO PROJ	IS INI TS F S MA N, W IECT 2050	FOR NEGA NAG ASH (318 20.	MATIO NRDING BEMEN INGTO 60-010
Facility N	ame (	1)						-	*****				NUCL DECEMBER OF STREET, ST.		Docker N	lumbe	125			-					-				
C	ON	IAN	10	HE	PE	A	5-	U	NĽ	T 1					015	51	01	0	10	1	11	A	15		4	10	age (3	10	-
Event D Month I 111 0 Doerating Mode (9) Power evel 10	Day 15		0	9 0 Y max 9 0 This re 20. 20. 20. 20. 20. 20.		G ER N Seq Seq Seq Seq Seq Seq Seq Seq Seq Seq	A urribe uentis imber mitted ) ) ) ) ) ) ) ) ) ) ) ) )	8 pu	rsua	Q Q Q   Revision Number   Q Q Q   nt to the r 20.41   50.34 50.37   50.71 50.72   50.72 50.72	POCH   Re   Month   1   205(c)   S(c)(2)   S(c)(2)	Day Day 015	S IN C • (7) Year 9 10 OFR § : (7)	Check one or n 50.73(a)(2) 50.73(a)(2) 50.73(a)(2) 50.73(a)(2) 50.73(a)(2) 50.73(a)(2) 50.73(a)(2)	Facility Na   Facility Na   N/A   N/A   (w)   (w)   (wi)   (wii)   (wiii)(A)   (wiii)(B)	mes mes	Q) (1	1) 7 7	acilitie 3.71(1 3.71( 3.71)		votve votve Q Q Q city i For	5 5 5 5			2   2	0	Dxf.	1	1
Name			-								-	Licensee	Contact F	or This LER (1	5)							*****				-			-
ТΔ	H	np	E							~		÷.,	د الب			-	Area	Cox	10	-	Tak	phon	e Nu	mber					
		UF.	-					-		00	2MPI	IAN	CES	UPER	/ISOR	1	31	1	2	18	31	9	17	1-	1	61	3	17	10
Cause	Syste	em	C	cmpon	ine	T	lanuti	actu	rer	Rec	prete One	Line Fo	r Each Co	Tiponent Failur	e Described	in Thi	s Re	port (	13)					D			1.000		
		+				+				101	NPROS			Catuse	aystem	0	ompo	nent	-	Ma	nuta	sturer	1	ToM	NP R(	ne )S			
		-	_		_	+	1	_	1			-				11	1	1		1	1	1							
	1		1	1	1	1	1	1	1						1	1	1	1	T	1	1	1			-			*****	
	-			-		-					Suppleme	ental Rep	xort Expect	ed (14)			da		+	Exp	ecto	1	M	onth	T	Dav	1	V	8.07
Yes (H Abstract (L	yes, c imit to	:omple 1400	He E	rpecter	Sub	rrissi	on Da ately I	te) If a	en sir	ngle-spac	No No	tten lines	i) (16)							Sub Da	тіззі Io (15	on 5)		L		1			1

On November 5, 1990, Comanche Peak Steam Electric Station Unit 1 was in Mode 5, Cold Shutdown, with a containment purge in progress. The Containment Air Cooling and Recirculation System (CACRS) fans were running, recirculating air inside containment. Approximately three hours after shifting the CACRS fans, a Containment Airborne Contamination High Radiation alarm was received which initiated a Containment Ventilation Isolation. The increase in Noble Gas activity was attributed to stagnant air pockets in containment that were subsequently mixed when the CACRS fans were shifted, causing an increase in detected airborne activity. The root cause was determined to be a phenomenon in which stagnant air with a higher Noble Gas content existed during a containment purge along with having the high alarm set point on the gaseous monitor set too conservatively for the existing conditions. Corrective actions are to revise containment purge procedures to ensure a good mixing of the containment atmosphere prior to purging and to review the guidelines for radioactive effluent releases, to ensure that set points are not set so conservatively that automatic safety functions are actuated unnecessarily.

NHC FORM 366A LICENSEE TEXT	EVENT REPORT (LE,	ISSION APPROVED OMB NO. 3150-0104 EXPIRES: 4/30/92 EST.MATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC. 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104). OFFICE OF MANAGEMENT AND BUDGET, WAGHINGTON, DC. 20505.
Facility Name (1)	Docket Number (2)	LER Number (6) Page (3) Year Sequential Revision

COMANCHE PEAK - UNIT 1 015101010141415 910 - 01318 - 010 012 OF 017

# I. DESCRIPTION OF THE REPORTABLE EVENT

#### A. REPORTABLE EVENT CLASSIFICATION

Any event or condition that resulted in manual or automatic actuation of any Engineered Safety Feature (ESF), including the Reactor Protection System.

# B. PLANT OPERATING CONDITIONS PRIOR TO THE EVENT

On November 5, 1990, just prior to the condition Comanche Peak Steam Electric Station Unit 1 was in Mode 5, Cold Shutdown, with reactor coolant temperature approximately 123 degrees Farenheit. The Containment Air Cooling and Recirculation System (CACRS) fans 1 and 2 (EIIS:(BK)(FAN)) were operating, recirculating air inside containment. Personnel air lock (PAL) doors (EIIS:(NH)(AL)) were open and a containment purge was in progress.

# C. STATUS OF STRUCTURES, SYSTEMS, OR COMPONENTS THAT WERE INOPERABLE AT THE START OF THE EVENT AND THAT CONTRIBUTED TO THE EVENT

There were no inoperable structures, systems or components that contributed to the event.

# D. NARRATIVE SUMMARY OF THE EVENT, INCLUDING DATES AND APPROXIMATE TIMES

At 2344, November 4, 1990, with the plant in Mode 5, a containment purge was started. This was the initial purge prior to containment entry. At 0034, November 5, 1990, both PAL doors were opened. At 1913, two CACRS fans were switched, shutting down fan 3 and starting up fan 2 in accordance with the equipment rotation procedure. An increase in airborne contamination levels was detected by the containment Particulate, Iodine, Gaseous (PIG) Monitor gaseous monitoring channels (EIIS:(IK)(RA)). The PIG gas channel showed an increase due to Noble

NRC FORM 366A LICENSEE TEX	U.S. NUCLEAR REQULATORY COMMISSI EVENT REPORT (LER) F CONTINUATION	SSION APPROVED OMB NO. 3150-0104 EXPIRES: 4/30/92 ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMAT COLLECTION REQUEST: 50,0 HRS. FORWARD COMMENTS REGARD BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEL BRANCH (P-50), U.S. NUCLEAR REGULATORY COMMISSION, WASHING OC. 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-1 OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC. 20503.
Facility Name (1)	Docket Number (2)	LER Number (6) Page (3)
	무료 모두 집에서 가지 않는 것이 같다.	Year Sequential Revision Number Number
COMANCHE PEAK	- UNIT 1 01510101014141	15 910 - 013 18 - 010 013 OF 0
Gases. The during the Airborne C 2.00E-4 me backgrour	ne Noble Gases were from fission operating cycle. After entering M Contamination High Radiation (Hig icrocuries per milliliter (µCi/ml) to ind levels. The Offsite Dose Calcu	n product buildup inside containment Mode 5, the PIG gas channel Containment igh Alarm) set point was lowered from o 1.26E-4 µCi/ml due to lower radiation wlation Manual (ODCM) calculated High
backgrour Alarm set	d levels. The Offsite Dose Calcul point for this release was 1.82E-2	ulation Manual (ODCM) calculated High 2 µCi/ml, over 144 times greater than the

actual High Alarm set point. The lower set point was chosen as a conservative measure to ensure that any change in airborne contamination levels would alert the operator. The set point is derived from administrative procedures that specify the set point to be three times a ten minute trend of containment atmosphere gaseous activity. The Containment Airborne Contamination High Radiation Alert Alarm (Alert Alarm) is set at 80 percent of the High Alarm.

Approximately two hours after the CACRS fans were switched, an Alert Alarm was received from the PIG gas channel. A Radiation Protection technician (utility, nonlicensed) was contacted and the channel was monitored. The Radiation Protection technician and the Shift Supervisor (utility, licensed) concluded that the Noble Gases were from stagnant pockets of air that were mixed when the CACRS fans were shifted at 1913 and that no work was in progress that would release radioactive gas. At 2159, a High Alarm on the PIG gas channel was received and a Containment Ventilation Isolation (CVI) occurred as designed. At 2220 hours, both CACRS fans were shutdown, a containment evacuation was ordered, and a containment preaccess filter unit was started. At 2245 the containment PAL doors were shut. All CACRS fans were started at 2310 and the High Alarm cleared. At 2359 the Nuclear Regulatory Commission was notified of the event via the Emergency Notification System pursuant to 10CFR50.72(b)(2)(ii). At 0010, November 6, 1990, normal access to containment was restored, but one Personnel Airlock door was maintained shut. At 0407, CVI was reset and the containment purge was commenced.

# E. THE METHOD OF DISCOVERY OF EACH COMPONENT OR SYSTEM FAILURE OR PROCEDURAL ERROR

A Containment Airborne Contamination High Radiation alarm was received from a PIG gas channel followed by a CVI.

	SEE EVENT F TEXT CONTIN	U.S. NUCLEAR REGULATORY COMMISSION	ESTIMATE COLLECTI BURDAN BRANCH ( DC. 20555 OFFICE OF	D BURDE ION REQ ESTIMAT (P-630), U 5, AND TI F MANAG	APPROVI E EN PER RE UEST: & TE TO TH S. NUCLE O THE PA EMENT AN	ED OME XPIRES SPONS D.D HRS IE REC AR REC PERWO ID BUDX	I NO. 3150- 4/30/92 E TO COMP FORWAR 20RDS AN 3ULATORY DRK REDUI QET, WASH	DID4 PLY WITH D COMM D REPO COMMISI DTION PI INGTON,	THIS INF ENTS RI RTS MAI SION, WA ROJECT ( DC. 2050	ORMATION EGARDING NAGEMENT ISHINGTON, (3150-0104). 9.
Facility Name (1)		Docket Number (2)		LERN	umber (6)			T	Page (3	,
COMANCHE PE Text (If more space is required, u	AK - UNIT 1 se additional NRC Form 388.	015101010141415	Year 910 -	- 0	iumber	3 -	Number 010	014	OF	017

# II. COMPONENT OR SYSTEM FAILURES

## A. FAILURE MODE, MECHANISM, AND EFFECT OF EACH FAILED COMPONENT

No failed components contributed to this event.

# B. CAUSE OF EACH COMPONENT OR SYSTEM FAILURE

No failed components contributed to this event.

# C. SYSTEMS OR SECONDARY FUNCTIONS THAT WERE AFFECTED BY FAILURE OF COMPONENTS WITH MULTIPLE FUNCTIONS

No failed components contributed to this event.

## D. FAILED COMPONENT INFORMATION

No failed components contributed to this event.

#### III. ANALYSIS OF THE EVENT

# A. SAFETY SYSTEM RESPONSES THAT OCCURRED

A CVI occurred when a Containment Airborne Contamination High Radiation alarm was received from a PIG gas channel. Operators verified that the CVI occurred as designed.

	U.S. NUCLEAR REGULATORY COMMISSION EE EVENT REPORT (LER) XT CONTINUATION	ESTIMA COLLEC BURDEI BRANCH DC. 206 OFFICE	TED I DTION N ES H (P-I 555, J OF N	A BURDEN F N REQUES STIMATE 530), U.S. AND TO 1 MANAGEM	PPROVE EI PER RES ST: 50 TO TH NUCLE/ THE PAI IENT AN	D OME PIRES PONSI D HRS E REC AR REC PERWO D BUDO	I NO. 3150- II 4/30/92 E TO COMF FORWAR IORDS AN IULATORY ORK REDUK GET, WASH	DIDA PLY WITH ID COMMI D REPOI COMMISS CTION PF (INGTON,	THIS INF ENTS R RTS MA HON, WA HOJEOT DC. 2050	ORMATION EGARDING NAGEMENT ISHINGTON, (3150-0104). 3.		
Facility Name (1)	Dookel Number (2)		LEA Number (6)					1	Page (3	Page (3)		
		Yea/		Seque	ential toer		Revision		T	T		
COMANCHE PEAK	K - UNIT 1 0 5 0 0 0 0 4 4 5	910	**	01:	3   8	-	010	015	OF	1717		
rear in more space 5 required, use ac	Sanonei MHC Porm Sobers) (17)											

# B. DURATION OF SAFETY SYSTEM TRAIN INOPERABILITY

No safety system trains were inoperable as a result of this event.

## C. SAFETY CONSEQUENCES AND IMPLICATIONS OF THE EVENT

The increased airborne contamination level detected by the PIG gas channel was due to stagnate air in containment that was mixed when CACRS fans were shifted. The detector set point for the High Alarm (CVI actuation) had been moved to a conservative set point. The PIG is not required to provide a CVI function in Mode 5. No maintenance or operation had occurred that could have caused the increased Noble Gas reading. At no time during the event were any release limits violated. No significant exposure was received by anyone inside containment during this event. At no time during this period did an actual condition exist that threatened the health or safety of the public.

# IV. CAUSE OF THE EVENT

#### ROOT CAUSE

- 1. The root cause was determined to be a phenomenon in which stagnant air with a higher Noble Gas content existed during a containment purge. The phenomenon was discovered when CACRS fans were switched and the stagnant air was moved to the air stream of the PIG gaseous radiation detector causing an increase in detected airborne contamination which actuated the CVI.
- 2. The high alarm set point on the gaseous monitor was set too conservatively for the existing conditions.

## GENERIC CONSIDERATIONS

Radiation monitor set points must be set conservatively to quickly identify problems before they escalate, yet set points must not be set so conservatively that automatic protective functions are challenged unnecessarily.

IC FORM 366A	U.S. NUCLEAR REQULATORY COMMISSION	APPROVED OMB NO. 3150-0104 EXPIPES: 4/30/92
LICENSEE EVENT TEXT CONTI	REPORT (LER) NUATION	COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (F-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON OC. 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104) OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC. 20503.

1	Facility Name (1)	Docket Number (2)			LEA Number (6)				Page (3)	
	전에 관련적 물건 가지 않을까?		Year		Sequential Number		Revision			
	COMANCHE PEAK - UNIT 1	0 5 0 0 0 4 4 5	910	-	01318	-	010	016	OF	017

## V. CORRECTIVE ACTIONS

## CORRECTIVE ACTIONS TO PREVENT RECURRENCE

#### ROOT CAUSE

1. The root cause was determined to be a phenomenon in which stagnant air with a higher Noble Gas content existed during a containment purge. The phenomenon was discovered when CACRS fans were switched and the stagnant air was moved to the air stream of the PIG gaseous radiation detector causing an increase in detected airborne contamination which actuated the CVI.

#### CORRECTIVE ACTION

The containment ventilation procedure is being revised to eliminate the possibility of this event from occuring by securing a purge whenever CACRS fans are shifted and allowing gas channel readings to stabilize before reinitiating the purge.

2. The High Alarm set point on the gaseous monitor was set too conservatively for the existing conditions.

#### CORRECTIVE ACTION

The administrative procedure for radioactive effluent releases, which provides guidance on radioactive effluent monitor set points, is being reviewed to ensure that set points are not set so conservatively that automatic safety functions are actuated unnecessarily. This review will take into account the changes made to the containment ventillation procedure prescribed in above.

NRC FORM 366A	U.S. NUCLEAR REGULATORY COMMISSION	N APPROVED OMB NO. 3150-0104 EXPIRES: 4/30/80
LICENSEE	EVENT REPORT (LER) CONTINUATION	ES IMAYED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMAT COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDI BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEM BRANCH (P-630), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGT DC. 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-01 OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC. 20503.
Facility Name (1)	Docket Number (2)	LER Number (6) Page (3)
		Year Sequential Revision Number Number
COMANCHE PEAK -	UNIT 1015101010141415	5 010 - 012 10 - 010 017 OF 01

#### **GENERIC CONSIDERATIONS**

Radiation monitor set points must be set conservatively to quickly identify problems before they escalate, yet set points must not be set so conservatively that automatic proective functions are challenged unnecessarily.

## CORREC IVE ACTION

The administrative procedure for radioactive effluent releases, which provides guidance on radioactive effluent monitor set points, is being reviewed to ensure that set points are not set so conservatively that automatic safety functions are actuated unnecessarily.

# VI. PREVIOUS SIMILAR EVENTS

There have been no previous similar events reported pursuant to 10CFR50.73.

## VII. ADDITIONAL INFORMATION

The times listed in the report are approximate and Central Standard Time.