Attachment to AECM-82/470 Page 1 of 1

	Page 1 of 1
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 8	M S G G S 1 2 0 0 - 0 0 0 0 0 0 3 4 1 1 1 1 4 5 5 CAT 58
CON'T 0 1 7 8	SOURCE L 6 0 5 0 0 0 4 1 6 7 0 9 1 0 8 2 8 1 0 0 8 8 2 9 EVENT DATE 74 75 REPORT DATE 80
0 2	The smoke detectors in the zone covering the Auxiliary Building corridor area(elevation)
0 3	119 foot) alarmed and would not reset. Investigation revealed no smoke or fumes
0 4	present in the area. A fire watch was established in accordance with
0 5	Tech Spec 3.3.7.9. There was no effect on the health and safety of the public and
06	did not constitute a threat to plant safety.
07	
0 8 7 8	9 5007514 60055 6005
0 9	SYSTEM CAUSE CAUSE SUBCODE SUB
	17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32 REVISION NO.
	ACTION FUTURE ACTION ON PLANT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP. SUPPLIER MANUFACTURER X 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 A 25 H 2 6 0 26 33 34 35 36 37 40 41 37 42 43 43 44 47 47 47 47 47
1101	The continuous alarm was found to be caused by an accumulation of dust on the
	pionization smoke detector combined with too high a sensitivity setting. The
1 2	detector was cleaned, its sensitivity adjusted and returned to service on September
13	12, 1982. This is a final report.
7 8	9 80
1 5	B 28 0 0 0 29 NA A Alarmed condition 32
	9 10 12 13 44 45 46 CTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36 Z (33) Z (34) NA
7 8	Z 33 Z 34 NA 9 10 11 44 45 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39
1 7	9 0 0 0 37 Z 38 NA NA 80
1 8	NUMBER DESCRIPTION (41) NA NA
7 8	9 11 12 LOSS OF OR DAMAGE TO FACILITY (43) LYPE DESCRIPTION LYPE DESCRIPTION LYPE DESCRIPTION NA SPDR ADDCK 05000416 PDR
7 8	9 10 80
2 0	N 44 DESCRIPTION 45
7 8	9 10 68 69 80 5