

CONTROL BLOCK: [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N | C | M | G | S | 1 | 2 | 0 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | [ ] | [ ] | 5  
7 8 9 14 15 25 26 30 37 38  
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 38

CONT  
0 1 | R | P | T | S | O | U | R | C | E | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 6 | 9 | 7 | 0 | 9 | 1 | 6 | 8 | 2 | 2 | 8 | 1 | 0 | 1 | 5 | 8 | 2 | 9  
7 8 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51  
 REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While in mode 1, during performance of a routine functional test of the waste gas  
 0 3 | analyzers, 1 of the 2 required oxygen analyzers failed to alarm after a simulated  
 0 4 | high oxygen concentration was generated. The failed oxygen analyzer was declared  
 0 5 | inoperable per T.S.3.3.3.9 which is reportable pursuant to T.S.6.9.1.13(b).  
 0 6 | Although both analyzers measured Waste Gas System(WG) oxygen concentrations, only  
 0 7 | the Teledyne analyzer would have initiated the alarm signal. Since the WG System  
 0 8 | operated with the capacity for alarm response, health and safety of the public  
 0 9 | were unaffected.

0 9 | M | C | 11 | B | 12 | C | 13 | I | N | S | T | R | U | 14 | S | 15 | Z | 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE  
 17 | L | E | R | / | R | O | R | E | P | O | R | T | N | U | M | B | E | R | 8 | 2 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 | 48 | 49 | 50 | 51 | 52 | 53 | 54 | 55 | 56 | 57 | 58 | 59 | 60  
 ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPDR-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
 E | 18 | F | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | N | 22 | N | 23 | L | 24 | Z | 25 | Z | 26 | 9 | 0 | 9 | 27  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The Bendix analyzer failed to alarm as the result of the toggle switch which con-  
 1 1 | trols the analyzer alarms being in the wrong position. The switch is installed  
 1 2 | in a location susceptible to inadvertent operation and apparently had been brushed  
 1 3 | by a passerby. The switch was returned to the dual analyzer alarm position and  
 1 4 | secured. Completion of a modification to the gas analyzer rack will eliminate  
 1 5 | potential reoccurrences.

1 5 | E | 28 | 0 | 7 | 5 | 29 | N/A | B | 31 | Routine Surveillance Test  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
 FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)

1 6 | Z | 33 | Z | 34 | N/A | N/A  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 7 | 0 | 0 | 0 | 37 | Z | 38 | N/A  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)

1 8 | 0 | 0 | 0 | 40 | N/A  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
 PERSONNEL INJURIES NUMBER DESCRIPTION (41)

1 9 | Z | 42 | N/A  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)

2 0 | N | 44 | N/A  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
 PUBLICITY ISSUED DESCRIPTION (45) NRC USE ONLY

NAME OF PREPARFR Phillip B. Nardoci PHONE: (704) 373-7432