NRC FORM 366 **U.S. NUCLEAR REGULATORY COMMISSION** (7.77) -Attachment to AECM-82/469 LICENSEE EVENT REPORT Page 1 of 1 CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)](1)0 0 0 0 0 (3) 0 00 G -LICENSE NUMBER CON'T REPORT 6 7 0 9 0 8) 0 0 51 0 0 0 4 9 0 1 L(6) 0SOURCE DOCKET NUMBER EVENT DATE EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) On September 9, 1982 at 1600 hours, the Auxiliary Building zone 2-6 smoke detectors 0 2 alarmed with no fire present. The smoke detectors were deactivated and a hourly fire 0 3 0 4 patrol established pursuant to T.S.3.3.7.9. There was no effect to the health and safety of the public or a threat to plant safety. This report is being submitted per T.S.6.9.1.13.b. 6 80 CODE CAUSE CAUSE COMP VALVE COMPONENT CODE SUBCODE SUBCODE SUBCODE Z (13) S AB (12 U E (15 Z C N T R (16 OCCURRENCE REVISION SEQUENTIAL REPORT EVENT YEAR REPORT NO. CODE TYPE NO LER/RO REPORT 8 2 0 17 13 01 3 0 L NUMBER PRIME GOMP COMPONENT EFFECT ON PLANT SHUTDOWN ATTACHMENT SUBMITTED NPRD-4 ACTION FUTURE TAKEN ACTION HOURS (22) FORM SUB. MANUFACTURER SUPPLIER N X 10 10 N (23) 12 16 10 Z Z (20 Z 0 σ (24) H Х 18) CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The alarm was caused by paint fumes resulting from maintenance painting activities in the area. The smoke detectors were cleaned and placed back into service on September 10, 1982. This is intended as a final report. 4 80 FACILITY METHOD OF DISCOVERY (30) DISCOVERY DESCRIPTION (32) % POWER OTHER STATUS A (31) Condition 0 Alarmed 0 3.3 20 ACTIVITY CONTENT AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) RELEASED_OF RELEASE Z (34) (33) NA NA 80 44 PERSONNEL EXPOSURES DESCRIPTION (39) NUMBER TYPE Z (38) 0 0 0 NA 80 PERSONNEL INJURIES DESCRIPTION (41) NUMBER 0 0 (40)NA 80 LOSS OF OR DAMAGE TO FACILITY (43) DESCRIPTION 8210220462 821008 PDR ADDCK 05000416 (42) Z NA 80 PUBLICITY PDR NRC USE ONLY DESCRIPTION (45) SSUED (44) NA N 68 69 80 NAME OF PREFARER Original signed by Ron Byrd PHONE --